

**OWNER:** J.E.P. DEVELOPEMENT CORP.  
**ADDRESS:** 1 GALLERIA TOWER  
DALLAS TX 75240  
**PHONE:**  
**FAX:**

**OPERATOR:** NORTH DALLAS AVIATION INC.  
**ADDRESS:** P.O. BOX 1807  
ADDISON TX 75001  
**PHONE:** 972-233-3334 EXT 3  
**FAX:** 972-447-9777

**ANALYST:** KIRK WILLIAMS  
**EMAIL:** KWILLIAMS@CAMPSYSTEMS.COM

1-866-581-2267 (OFFICE)  
316-462-2442 (FAX)  
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)  
631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

**AIRCRAFT SERIAL/REGNO:** 35A210/N770JP      **MODEL:** LEARJET 35A      **MANUFACTURER:** BOMBARDIER INCORPORATED

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 23-OCT-1978		10965 A/C HRS	as of 05-MAR-2010	A/C HRS	as of ___/___/___
		9235 AFL	as of 05-MAR-2010	AFL	as of ___/___/___

**ENGINE NO. 1 SERIAL/PART:** P-74621/3070300-9      **MODEL:** TFE731-2      **MANUFACTURER:** HONEYWELL

INSTALLED ON 19-SEP-1978		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	10633.8 ENG. HRS	as of 05-MAR-2010	ENG. HRS	as of ___/___/___
138 ENC		9222 ENC	as of 05-MAR-2010	ENC	as of ___/___/___

**ENGINE NO. 2 SERIAL/PART:** P-74622/3070300-5      **MODEL:** TFE731-2      **MANUFACTURER:** HONEYWELL

INSTALLED ON 25-SEP-1978		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	10662.4 ENG. HRS	as of 05-MAR-2010	ENG. HRS	as of ___/___/___
217 ENC		9042 ENC	as of 05-MAR-2010	ENC	as of ___/___/___

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Work Packages

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	DISPOSITION	TIME REMAINING
WORKCARD	PKG #			NEXT DUE	
			TIME SINCE	ACTUAL	MAXLIMIT
				COMPLIANCE	
				WARR EXP	
<b>CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS</b>					
<b>ENGINE NO. 1 Model : TFE731-2 Serial # P-74621 Part # 3070300-9</b>					
+ 057110	NO. 1 ENGINE - 150/250 HOUR INSPECTION PKG 1 in PKG 2	MOS HRS/MSC	150 +100	17-FEB-2010 10625.3	(10775.3) 11106.5
	REF:	ENC		9211	
+ 057120	NO. 1 ENGINE - 300/400 HOUR INSPECTION PKG 2	MOS HRS/MSC	300 +100	17-FEB-2010 10625.3	(10925.3) 11256.5
	REF:	ENC		9211	
+ 057130	NO. 1 ENGINE - 600/800 HOUR INSPECTION PKG 3	MOS HRS/MSC	800	17-FEB-2010 10625.3	(11425.3) 11756.5
	REF:	ENC		9211	
057140	NO. 1 ENGINE - 1000/1500 HOUR INSPECTION PKG 4	MOS HRS/MSC	1400 +100	17-FEB-2010 10625.3	(12025.3) 12356.5
	REF:	ENC		9211	
<b>ENGINE NO. 2 Model : TFE731-2 Serial # P-74622 Part # 3070300-5</b>					
+ 057110	NO. 2 ENGINE - 150/250 HOUR INSPECTION PKG 1 in PKG 2	MOS HRS/MSC	150 +100	17-FEB-2010 10653.9	(10803.9) 11106.5
	REF:	ENC		9031	
+ 057120	NO. 2 ENGINE - 300/400 HOUR INSPECTION PKG 2	MOS HRS/MSC	300 +100	17-FEB-2010 10653.9	(10953.9) 11256.5
	REF:	ENC		9031	
+ 057130	NO. 2 ENGINE - 600/800 HOUR INSPECTION PKG 3	MOS HRS/MSC	800	17-FEB-2010 10653.9	(11453.9) 11756.5
	REF:	ENC		9031	
057140	NO. 2 ENGINE - 1000/1500 HOUR INSPECTION PKG 4	MOS HRS/MSC	1400 +100	17-FEB-2010 10653.9	(12053.9) 12356.5
	REF:	ENC		9031	
<b>CHAPTER 34 NAVIGATION</b>					

?-Insufficient Information    +-Task exists in Inspection Manual    (s)-Suppressed Requirement    (EBT)-Estimated Base Time    \*-Estimated Due (New Requirement)  
 (EFF)-Effective C/W

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

**Work Packages**

**Aircraft**

TASK NO WORKCARD	TASK DESCRIPTION PKG #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAXLIMIT	
340200	RVSM - CONTINUED AIRWORTHINESS CERTIFICATION - ST00952SE OR ST01122SE (INCLUDING 91.411 AND 91.413 REQUIREMENTS) PKG 2	MOS	24		-18		28-MAY-2009 10838.5	31-MAY-2011		449 d
	REF: OMM AMI-STC-LJ3536 (STC SA00952SE-D)	HRS/MSC AFL					9102			

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE ( ENH )	NEXT DUE ACTUAL MAX LIMIT		
<b>CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS</b>										
+ 051060	ACCOMPLISH 12000 HOUR AIRFRAME INSPECTION	MOS					23-OCT-1978			
05.060		HRS/MSC	12000	+25/-25			0	12000	12025	1035 (+25)
	REF: AMM 5-10-28	AFL					0			
+ 0510A1	ACCOMPLISH PHASE A1 - 300 HOUR INSPECTION/CHECK	MOS	12	+14d/-14d			07-DEC-2009	31-DEC-2010	31-DEC-2010	298 d
05.002		HRS/MSC	300	+25/-25			10928.4	11228.4	11253.4	263.4 (+25)
	REF: AMM 5-10-01	AFL					9202			
+ 0510A2	ACCOMPLISH PHASE A2 - 300 HOUR INSPECTION/CHECK	MOS	12	+14d/-14d			07-DEC-2009	31-DEC-2010	31-DEC-2010	298 d
05.004		HRS/MSC	300	+25/-25			10928.4	11228.4	11253.4	263.4 (+25)
	REF: AMM 5-10-02	AFL					9202			
+ 0510A3	ACCOMPLISH PHASE A3 - 300 HOUR INSPECTION/CHECK	MOS	12	+14d/-14d			07-DEC-2009	31-DEC-2010	31-DEC-2010	298 d
05.006		HRS/MSC	300	+25/-25			10928.4	11228.4	11253.4	263.4 (+25)
	REF: AMM 5-10-03	AFL					9202			
+ 0510A4	ACCOMPLISH PHASE A4 - 300 HOUR INSPECTION/CHECK	MOS	12	+14d/-14d			07-DEC-2009	31-DEC-2010	31-DEC-2010	298 d
05.008		HRS/MSC	300	+25/-25			10928.4	11228.4	11253.4	263.4 (+25)
	REF: AMM 5-10-04	AFL					9202			
+ 0510A5	ACCOMPLISH PHASE A5 - 300 HOUR INSPECTION/CHECK	MOS	12	+14d/-14d			07-DEC-2009	31-DEC-2010	31-DEC-2010	298 d
05.010		HRS/MSC	300	+25/-25			10928.4	11228.4	11253.4	263.4 (+25)
	REF: AMM 5-10-05	AFL					9202			
+ 0510A6	ACCOMPLISH PHASE A6 - 300 HOUR INSPECTION/CHECK	MOS	12	+14d/-14d			07-DEC-2009	31-DEC-2010	31-DEC-2010	298 d
05.012		HRS/MSC	300	+25/-25			10928.4	11228.4	11253.4	263.4 (+25)
	REF: AMM 5-10-06	AFL					9202			
+ 0510B1	ACCOMPLISH PHASE B1 - 600 HOUR INSPECTION/CHECK	MOS	24	+14d/-14d	-10		22-DEC-2008	31-DEC-2010	31-DEC-2010	298 d
05.014		HRS/MSC	600	+25/-25			10763.7	11363.7	11388.7	398.7 (+25)
	REF: AMM 5-10-07	AFL					9035			
+ 0510B2	ACCOMPLISH PHASE B2 - 600 HOUR INSPECTION/CHECK	MOS	24	+14d/-14d	-10		22-DEC-2008	31-DEC-2010	31-DEC-2010	298 d
05.016		HRS/MSC	600	+25/-25			10763.7	11363.7	11388.7	398.7 (+25)
	REF: AMM 5-10-08	AFL					9035			
+ 0510B3	ACCOMPLISH PHASE B3 - 600 HOUR INSPECTION/CHECK	MOS	24	+14d/-14d	-10		22-DEC-2008	31-DEC-2010	31-DEC-2010	298 d
05.018		HRS/MSC	600	+25/-25			10763.7	11363.7	11388.7	398.7 (+25)
	REF: AMM 5-10-09	AFL					9035			
+ 0510B4	ACCOMPLISH PHASE B4 - 600 HOUR INSPECTION/CHECK	MOS	24	+14d/-14d	-10		22-DEC-2008	31-DEC-2010	31-DEC-2010	298 d
05.020		HRS/MSC	600	+25/-25			10763.7	11363.7	11388.7	398.7 (+25)
	REF: AMM 5-10-10	AFL					9035			

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
+ 0510B5	ACCOMPLISH PHASE B5 - 600 HOUR INSPECTION/CHECK	MOS	24	+14d/-14d	-10	22-DEC-2008	31-DEC-2010	31-DEC-2010	298 d
05.022		HRS/MSC	600	+25/-25		10763.7	11363.7	11388.7	398.7 (+25)
	REF: AMM 5-10-11	AFL				9035			
+ 0510B6	ACCOMPLISH PHASE B6 - 600 HOUR INSPECTION/CHECK	MOS	24	+14d/-14d	-10	22-DEC-2008	31-DEC-2010	31-DEC-2010	298 d
05.024		HRS/MSC	600	+25/-25		10763.7	11363.7	11388.7	398.7 (+25)
	REF: AMM 5-10-12	AFL				9035			
+ 0510C1	ACCOMPLISH PHASE C1 - 1200 HOUR INSPECTION/CHECK	MOS	48	+14d/-14d		22-DEC-2008	31-DEC-2012	05-JAN-2013	1029 d (+5)
05.026		HRS/MSC	1200	+25/-25		10763.7	11963.7	11988.7	998.7 (+25)
	REF: AMM 5-10-13	AFL				9035			
+ 0510C2	ACCOMPLISH PHASE C2 - 1200 HOUR INSPECTION/CHECK	MOS	48	+14d/-14d		22-DEC-2008	31-DEC-2012	05-JAN-2013	1029 d (+5)
05.028		HRS/MSC	1200	+25/-25		10763.7	11963.7	11988.7	998.7 (+25)
	REF: AMM 5-10-14	AFL				9035			
+ 0510C3	ACCOMPLISH PHASE C3 - 1200 HOUR INSPECTION/CHECK	MOS	48	+14d/-14d		22-DEC-2008	31-DEC-2012	05-JAN-2013	1029 d (+5)
05.030		HRS/MSC	1200	+25/-25		10763.7	11963.7	11988.7	998.7 (+25)
	REF: AMM 5-10-15	AFL				9035			
+ 0510C4	ACCOMPLISH PHASE C4 - 1200 HOUR INSPECTION/CHECK	MOS	48	+14d/-14d		22-DEC-2008	31-DEC-2012	05-JAN-2013	1029 d (+5)
05.032		HRS/MSC	1200	+25/-25		10763.7	11963.7	11988.7	998.7 (+25)
	REF: AMM 5-10-16	AFL				9035			
+ 0510C5	ACCOMPLISH PHASE C5 - 1200 HOUR INSPECTION/CHECK	MOS	48	+14d/-14d		22-DEC-2008	31-DEC-2012	05-JAN-2013	1029 d (+5)
05.034		HRS/MSC	1200	+25/-25		10763.7	11963.7	11988.7	998.7 (+25)
	REF: AMM 5-10-17	AFL				9035			
+ 0510C6	ACCOMPLISH PHASE C6 - 1200 HOUR INSPECTION/CHECK	MOS	48	+14d/-14d		22-DEC-2008	31-DEC-2012	05-JAN-2013	1029 d (+5)
05.036		HRS/MSC	1200	+25/-25		10763.7	11963.7	11988.7	998.7 (+25)
	REF: AMM 5-10-18	AFL				9035			
+ 0510D1	ACCOMPLISH PHASE D1 - 2400 HOUR INSPECTIONS/CHECKS	MOS	96	+14d/-14d		07-DEC-2009	31-DEC-2017	31-DEC-2017	2855 d
05.038		HRS/MSC	2400	+25/-25		10928.4	13328.4	13353.4	2363.4 (+25)
	REF: AMM 5-10-19	AFL				9202			
+ 0510D2	ACCOMPLISH PHASE D2 - 2400 HOUR INSPECTIONS/CHECKS	MOS	96	+14d/-14d		07-DEC-2009	31-DEC-2017	31-DEC-2017	2855 d
05.040		HRS/MSC	2400	+25/-25		10928.4	13328.4	13353.4	2363.4 (+25)
	REF: AMM 5-10-20	AFL				9202			
+ 0510D3	ACCOMPLISH PHASE D3 - 2400 HOUR INSPECTIONS/CHECKS	MOS	96	+14d/-14d		07-DEC-2009	31-DEC-2017	31-DEC-2017	2855 d
05.042		HRS/MSC	2400	+25/-25		10928.4	13328.4	13353.4	2363.4 (+25)
	REF: AMM 5-10-21	AFL				9202			
+ 0510D4	ACCOMPLISH PHASE D4 - 2400 HOUR INSPECTIONS/CHECKS	MOS	96	+14d/-14d		07-DEC-2009	31-DEC-2017	31-DEC-2017	2855 d
05.044		HRS/MSC	2400	+25/-25		10928.4	13328.4	13353.4	2363.4 (+25)
	REF: AMM 5-10-22	AFL				9202			

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
+ 0510D5	ACCOMPLISH PHASE D5 - 2400 HOUR INSPECTIONS/CHECKS								
05.046		MOS	96	+14d/-14d			07-DEC-2009	31-DEC-2017	2855 d
		HRS/MSC	2400	+25/-25			10928.4	13328.4	2363.4 (+25)
	REF: AMM 5-10-23	AFL					9202		
+ 0510D6	ACCOMPLISH PHASE D6 - 2400 HOUR INSPECTIONS/CHECKS								
05.048		MOS	96	+14d/-14d			07-DEC-2009	31-DEC-2017	2855 d
		HRS/MSC	2400	+25/-25			10928.4	13328.4	2363.4 (+25)
	REF: AMM 5-10-24	AFL					9202		
+ 051100	ACCOMPLISH 3000 LANDING INSPECTION								
05.100		MOS					20-APR-2000		
		HRS/MSC					8999		
	REF: AMM 5-10-25	AFL	3000	+25/-25			7352	10352	10377
+ 051110	ACCOMPLISH MAJOR LANDING GEAR INSPECTION								
05.110		MOS					18-APR-1997		
		HRS/MSC					7283.8		
	REF: AMM 5-10-26	AFL	6000	+25/-25			5992	11992	12017
+ 051120	ACCOMPLISH 12 YEAR AIRFRAME INSPECTION								
05.120		MOS	144	+14d/-14d			23-SEP-2002	30-SEP-2014	1667 d (+7)
		HRS/MSC					9789.9		
	REF: AMM 5-10-27	AFL	6000	+25/-25			8061	14061	14086
									4826 (+25)
<b>CHAPTER 08</b>	<b>LEVELING AND WEIGHING</b>								
082000	REWEIGH AIRCRAFT								
		MOS	36				17-FEB-2010	28-FEB-2013	1088 d
		HRS/MSC					10956.5		
	REF: OMM NDA LJ 35/36 AAIP APPENDIX C	AFL					9224		
<b>CHAPTER 21</b>	<b>AIR CONDITIONING</b>								
21-17	TEMP CONTROL:COCKPIT GAUGE TEMP CONTROL								MEL
	PN	MOS			TSN:10504		19-AUG-2007		
	SN-UNKNOWN	HRS/MSC	O/C						
	REF:	AFL							
210101	VALVE:LEFT BLEED AIR CHECK VALVE								
21.110	PN	MOS			TSN:0		23-OCT-1978		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 36-10-02	AFL			TSN:0		0		
210103	VALVE:LEFT EMERGENCY 3 WAY REGULATOR VALVE								
21.310	6600199-9	MOS			TSO:0		15-APR-1990		
	524	HRS/MSC	O/C		TSO:0		5178.1		
	REF: AMM 21-30-09	AFL			TSO:0		4219		
210106	VALVE:RIGHT BLEED AIR CHECK VALVE								
21.110	PN	MOS			TSN:0		23-OCT-1978		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 36-10-02	AFL			TSN:0		0		
210108	VALVE:RIGHT EMERGENCY 3 WAY REGULATOR VALVE								
21.310	2619500-10	MOS			TSO:0		17-NOV-1997		
	9H0099	HRS/MSC	O/C		TSO:0		7526.5		
	REF: AMM 21-30-09	AFL			TSO:0		6179		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
WORKCARD	PART#/PKG SERIAL #									
210111	VALVE:FLOW CONTROL VALVE 27441496-02	MOS		TSO:0			07-DEC-2009			
21.030	12AE21 REF: AMM 21-41-01	HRS/MSC AFL	O/C	TSO:0 TSO:0			10928.4 9202			
210116	VENTURI:VENTURI PN	MOS		TSN:0			23-OCT-1978			
21.130	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
210121	VALVE:HOT AIR BYPASS VALVE 6600211-28	MOS		TSN:0			20-DEC-1996			
21.030	P-925 REF: AMM 21-41-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			7162.2 5895			
210126	EXCHANGER:HEAT EXCHANGER PN	MOS		TSN:0			23-OCT-1978			
21.120	SN-UNKNOWN REF: AMM 21-41-03	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
210131	VALVE:RAM AIR CHECK VALVE PN	MOS		TSN:0			23-OCT-1978			
21.130	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
210136	VALVE:LEFT CABIN AIR DISTRIBUTION CHECK VALVE PN	MOS		TSN:0			23-OCT-1978			
21.140	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
210141	VALVE:RIGHT CABIN AIR DISTRIBUTION CHECK VALVE PN	MOS		TSN:0			23-OCT-1978			
21.140	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
210201	INSEPCT AIR CONDITIONER MOTOR & COMPRESSOR									<b>STC-SUPPLEMENTAL TYPE CERTIFICATE</b>
		MOS					14-NOV-2008			
		HRS/MSC	300				10763.4			98.4
	REF: OMM SANDEN I-503 (STC# ST01586AT)	AFL					9034			
210202	INSPECT MOTOR BRUSHES & FAN									<b>STC-SUPPLEMENTAL TYPE CERTIFICATE</b>
		MOS					19-NOV-2004			
		HRS/MSC	600				10438.3			73.3
	REF: OMM SANDEN I-503 (STC# ST01586AT)	AFL					8769			
210203	FUNCTION TEST PRESSURE SWITCH									<b>STC-SUPPLEMENTAL TYPE CERTIFICATE</b>
		MOS					08-JUN-2007			
		HRS/MSC	1200				10494.7			729.7
	REF: OMM SANDEN I-503 (STC# ST01586AT)	AFL					8823			

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
210601	INDICATOR:TEMPERATURE CONTROL INDICATOR								
21.150	PN SN-UNKNOWN REF: AMM 21-60-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
210606	HEATER:LEFT CABIN AUXILIARY HEATER								
21.160	PN SN-UNKNOWN REF: AMM 21-42-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
210608	HEATER:RIGHT CABIN AUXILIARY HEATER								
21.160	PN SN-UNKNOWN REF: AMM 21-42-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
211101	SELECTOR:TEMPERATURE (CABIN TEMP) SELECTOR								
21.280	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
211106	UNIT:TEMPERATURE CONTROL UNIT								
21.170	PN SN-UNKNOWN REF: AMM 21-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
211111	SENSOR:CABIN TEMPERATURE SENSOR								
21.040	6600211-23 P-738 REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			02-SEP-2007 10509.9 8839		
211123	BLOWER:CABIN TEMPERATURE SENSOR BLOWER								
21.040	6600231-1 4053 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAY-1996 6778.4		
211126	THERMOSTAT:HI LIMIT THERMOSTAT								
21.180	PN SN-UNKNOWN REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
211136	SENSOR:DUCT TEMPERATURE SENSOR								
21.190	6600211-38 1366 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			12-SEP-2007 10509.9 8839		
211139	LIMITER:DUCT TEMPERATURE LIMITER								
21.320	6600211-37 1122 REF: AMM 21-60-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-FEB-1986 2916.9		
211146	SENSOR:CABIN SKIN TEMPERATURE SENSOR								
21.190	PN SN-UNKNOWN REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
211156	VALVE:LEFT CABIN PRESSURE REGULATOR VALVE								
21.360	PN SN-UNKNOWN REF: AMM 21-30-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		



Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
211158	REGULATOR:LEFT PRESSURE TEMPERATURE CONTROL SYSTEM REGULATOR								
21.370	PN SN-UNKNOWN REF: AMM 21-60-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
211161	VALVE:LEFT CABIN TEMPERATURE ALCOHOL CHECK VALVE								
21.380	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
211166	VALVE:RIGHT CABIN TEMPERATURE ALCOHOL CHECK VALVE								
21.380	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
211171	CONTROL:MANUAL OVERRIDE CABIN TEMPERATURE CONTROL								
21.380	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
211176	VALVE:RIGHT CABIN PRESSURE REGULATOR VALVE								
21.360	PN SN-UNKNOWN REF: AMM 21-30-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
211178	REGULATOR:RIGHT PRESSURE TEMPERATURE CONTROL SYSTEM REGULATOR								
21.370	PN SN-UNKNOWN REF: AMM 21-60-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
211601	COMPRESSOR:FREON COMPRESSOR								
21.230	2380155-5 4392 REF: AMM 21-50-01	MOS HRS/MSC AFL	O/C				08-JUN-1998 7928.1 6478		
211607	FAN BLADE:AIR CONDITION COMPRESSOR FAN BLADE								
21.060	6608059-5 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-AUG-1989 4789.2 3883		
211621	MOTOR:COMPRESSOR MOTOR								
21.050	6608267-2 2303 REF: AMM 21-50-02	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			23-FEB-2001 9361.3 7647		
211631	CONDENSER:CONDENSER								
21.020	6608061-6 80K-175 REF: AMM 21-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-FEB-1981		
211636	DEHYDRATOR:DEHYDRATOR								
21.020	PN SN-UNKNOWN REF: AMM 21-50-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			08-JUN-1998 7928.1 6478		
211641	SWITCH:REFRIGERATION PRESSURE SWITCH								
21.070	PN-UNKNOWN SN-UNKNOWN REF: AMM 21-50-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-FEB-1981		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
211651	EVAPORATOR:EVAPORATOR 2499002-2	MOS		TSN:0			25-MAY-1998		
21.010	SN-UNKNOWN REF: AMM 21-50-06	HRS/MSC AFL	O/C	TSN:0 TSN:0			7907.8 6461		
211656	BLOWER ASSY.:COCKPIT BLOWER ASSY. PN-UNKNOWN	MOS		TSO:0			12-SEP-1994		
21.010	161 REF: AMM 21-50-06	HRS/MSC AFL	O/C	TSO:0 TSO:0			6235.6 5126		
211657	BLOWER ASSY.:CABIN BLOWER ASSY. PN	MOS		TSN:0			23-OCT-1978		
	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
211661	FAN:COOLING COCKPIT FAN PN	MOS		TSN:0			23-OCT-1978		
21.200	SN-UNKNOWN REF: AMM 21-21-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
211671	VALVE:EXPANSION VALVE 226-210	MOS		TSN:0			16-APR-1999		
21.240	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			8396.5 6845		
212101	VALVE:CABIN AIR EXHAUST VALVE 130406-1	MOS		TSN:0			23-SEP-2002		
21.080	118-3952 REF: AMM 21-30-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			9789.9 8061		
212111	VALVE:DIFFERENTIAL PRESSURE RELIEF VALVE PN	MOS		TSN:0			23-OCT-1978		
21.270	SN-UNKNOWN REF: AMM 21-30-03	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
212116	PUMP:PRESSURE JET (VACUUM REGULATOR) PUMP PN	MOS		TSN:0			23-OCT-1978		
21.090	SN-UNKNOWN REF: AMM 21-30-06	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
212126	MODULE:PRESSURIZATION MODULE 2614062-12	MOS					21-MAY-1997		
21.100	47-192 REF: AMM 21-30-08	HRS/MSC AFL	O/C				7286.8 5996		
212141	LIMITER:FORWARD CABIN ALTITUDE LIMITER PN	MOS		TSN:0			23-OCT-1978		
21.390	SN-UNKNOWN REF: AMM 21-30-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
212143	LIMITER:AFT CABIN ALTITUDE LIMITER PN	MOS		TSN:0			23-OCT-1978		
21.390	SN-UNKNOWN REF: AMM 21-30-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
212151	VALVE:CABIN SAFETY VALVE 6600207-3	MOS		TSN:0			26-OCT-1999		
21.030	96-5375 REF: AMM 21-30-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			8635.5 7074		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
212154	FILTER:SAFETY VALVE FILTER								
21.290	PN SN-UNKNOWN REF: AMM 21-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
212155	FILTER:CABIN PRESSURE FILTER								
21.290	PN SN-UNKNOWN REF: AMM 21-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
212166	ANEROID:CABIN (PRIMARY AURAL WARNING) ANEROID								
21.350	PN SN-UNKNOWN REF: AMM 21-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
212601	ANEROID:CABIN PRESSURE AIR EXHAUST VALVE ANEROID								
21.350	PN SN-UNKNOWN REF: AMM 21-30-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
212606	INDICATOR:CABIN RATE-OF-CLIMB INDICATOR								
21.210	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
212611	INDICATOR:DIFFERENTIAL PRESSURE INDICATOR								
21.210	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
212616	CONTROLLER:ALTITUDE CONTROLLER								
21.210	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
212621	VALVE:MANUAL CABIN ALTITUDE VALVE								
21.220	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
212626	CONTROLLER:RATE CONTROLLER								
21.220	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
212628	SELECTOR:RATE SELECTOR								
21.280	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
212631	MODULE:DIFFERENTIAL PRESSURE RELIEF VALVE- MODULE								
21.220	PN-UNKNOWN P675 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-JUN-1982 1887 1361		
212656	FILTER:MODULE PRESSURE FILTER								
21.300	PN SN-UNKNOWN REF: AMM 21-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
212661	SWITCH:LEFT EMERGENCY PRESSURE ANEROID SWITCH								
21.340	PN-UNKNOWN SN-UNKNOWN REF: AMM 21-30-07	MOS HRS/MSC AFL	O/C				06-AUG-1993 5909.2		
212671	SWITCH:RIGHT EMERGENCY PRESSURE ANEROID SWITCH								
21.340	PN-UNKNOWN SN-UNKNOWN REF: AMM 21-30-07	MOS HRS/MSC AFL	O/C				06-AUG-1993 5909.2		
213013	ASSEMBLY:VACUUM CABIN PRESSURE REGULATOR ASSEMBLY								
	PN SN-UNKNOWN REF: AMM 21-30-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
+ 213050	CHECK CABIN LEAK RATE (IRN H2130007)								
21.400	REF: AMM 21-30-00	MOS HRS/MSC AFL	1200				10-JAN-2005 10438.3 8767	11638.3	673.3
213101	INDICATOR:CABIN TEMPERATURE INDICATOR								
21.250	PN SN-UNKNOWN REF: AMM 21-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
213106	AMPLIFIER:CABIN TEMPERATURE AMPLIFIER								
21.260	PN SN-UNKNOWN REF: AMM 21-61-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
213110	FAN:CABIN TEMPERATURE FAN								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
213111	SENSOR:AFT CABIN TEMPERATURE SENSOR								
21.250	PN SN-UNKNOWN REF: AMM 21-61-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
213116	SWITCH:DUCT PRESSURE SWITCH								
21.330	PN SN-UNKNOWN REF: AMM 36-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
215040	HOURLY:METER:COMPRESSOR MOTOR HOURLY								
31.020	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
<b>CHAPTER 22 AUTO FLIGHT</b>									
220101	CONTROLLER:AUTOPILOT CONTROLLER								
22.010	501-1107 1280 REF: AMM 22-10-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			26-MAR-1993 5789.5 4732		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
220111	CONTROLLER:YAW COMPUTER/ CONTROLLER 501-1111-02	MOS					09-MAY-1998		
22.040	1284 REF: AMM 22-11-10	HRS/MSC AFL	O/C				7875.2 6432		
220112	BOARD:PRIMARY YAW PRINTED CIRCUIT BOARD PN	MOS		TSN:0			23-OCT-1978		
22.050	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
220113	BOARD:SECONDARY YAW PRINTED CIRCUIT BOARD PN	MOS		TSN:0			23-OCT-1978		
22.050	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
220131	ELECTRIC BOX:AUTOPILOT ELECTRIC BOX PN	MOS		TSN:0			23-OCT-1978		
22.030	SN-UNKNOWN REF: AMM 22-10-03	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
220141	COMPUTER:AUTOPILOT (PITCH AND ROLL) COMPUTER 501-1108-03	MOS		TSR:0			14-APR-2005		
22.040	1303 REF: AMM 22-10-04	HRS/MSC AFL	O/C	TSR:0 TSR:0			10441 8769		
220142	BOARD:ROLL AUTOPILOT PRINTED CIRCUIT BOARD 502-1078-03	MOS					20-NOV-2001		
22.060	1447 REF: GENERIC NO REF	HRS/MSC AFL	O/C				9585.6 7827		
220143	BOARD:PITCH AUTOPILOT PRINTED CIRCUIT BOARD PN	MOS		TSN:0			23-OCT-1978		
22.060	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
220148	ACCELEROMETER:VERTICAL ACCELEROMETER PN	MOS		TSN:0			23-OCT-1978		
22.140	SN-UNKNOWN REF: AMM 22-12-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
220151	INTERFACE BOX:FLIGHT DIRECTOR INTERFACE BOX PN	MOS		TSN:0			23-OCT-1978		
22.030	SN-UNKNOWN REF: AMM 22-10-05	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
220601	ACTUATOR:PRIMARY YAW SERVO ACTUATOR PN	MOS		TSN:0			23-OCT-1978		
22.070	SN-UNKNOWN REF: AMM 22-11-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
220606	CAPSTAN:PRIMARY YAW SERVO CAPSTAN PN	MOS		TSN:0			23-OCT-1978		
22.070	SN-UNKNOWN REF: AMM 22-11-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
220616	GYRO:PRIMARY YAW RATE GYRO PN	MOS		TSN:0			23-OCT-1978		
22.120	SN-UNKNOWN REF: AMM 22-11-05	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
220621	ACCELEROMETER:PRIMARY LATERAL ACCELEROMETER								
	PN	MOS		TSN:0			23-OCT-1978		
22.130	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-11-06	AFL		TSN:0			0		
220626	INDICATOR:YAW DAMPER INDICATOR								
	PN-UNKNOWN	MOS		TSR:0			15-SEP-1995		
22.190	1374	HRS/MSC	O/C	TSR:0			6434.5		
	REF: GENERIC NO REF	AFL		TSR:0					
221101	ACTUATOR:SECONDARY YAW SERVO ACTUATOR								
	501-1112-03	MOS					10-JAN-2005		
22.080	1371	HRS/MSC	O/C				10438.3		
	REF: AMM 22-11-01	AFL					8767		
221106	CAPSTAN:SECONDARY YAW SERVO CAPSTAN								
	PN	MOS		TSN:0			23-OCT-1978		
22.080	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-11-02	AFL		TSN:0			0		
221116	GYRO:SECONDARY YAW RATE GYRO								
	PN	MOS		TSN:0			23-OCT-1978		
22.120	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-11-05	AFL		TSN:0			0		
221121	ACCELEROMETER:SECONDARY LATERAL ACCELEROMETER								
	PN	MOS		TSN:0			23-OCT-1978		
22.130	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-11-06	AFL		TSN:0			0		
221126	GYRO:ROLL RATE GYRO								
	501-1169-01	MOS		TSO:0			04-DEC-2007		
22.180	1477	HRS/MSC	O/C	TSO:0			10573.1		
	REF: AMM 22-13-04	AFL		TSO:0			8885		
222001	UNIT:AIR DATA UNIT								
	PN	MOS		TSN:0			23-OCT-1978		
22.240	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-21-00	AFL		TSN:0			0		
222101	ACTUATOR:ELEVATOR PITCH SERVO ACTUATOR								
	501-1112-02	MOS		TSO:0			14-APR-2005		
22.090	1137	HRS/MSC	O/C	TSO:0			10441		
	REF: AMM 22-12-01	AFL		TSO:0			8769		
222106	CLUTCH:PITCH CAPSTAN SLIP CLUTCH								
	57507-000	MOS		TSO:0			21-FEB-1996		
22.100	0180-46AA	HRS/MSC	O/C	TSO:0			6608.1		
	REF: AMM 22-12-02	AFL		TSO:0			5446		
223101	ACTUATOR:AILERON ROLL SERVO ACTUATOR								
	501-1112-01	MOS		TSO:0			25-NOV-2007		
22.110	1504	HRS/MSC	O/C	TSO:0			10566.8		
	REF: AMM 22-13-01	AFL		TSO:0			8881		
223106	CLUTCH:ROLL CAPSTAN SLIP CLUTCH								
	PN	MOS		TSN:0			23-OCT-1978		
22.100	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-13-02	AFL		TSN:0			0		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
224101	COMPUTER:MACH TRIM COMPUTER								
22.160	501-1132-01	MOS					16-MAY-1980		
	1223	HRS/MSC	O/C				819		
	REF: AMM 22-20-01	AFL					675		
224111	SWITCH:MACH TRIM SWITCH								
22.170	PN	MOS		TSN:0			23-OCT-1978		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
224121	SENSOR:MACH TRIM POSITION SENSOR								
22.230	PN	MOS		TSN:0			23-OCT-1978		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-20-02	AFL		TSN:0			0		
224126	SENSOR:AILERON POSITION (FOLLOW-UP) SENSOR								
22.150	509-1005-01	MOS		TSN:0			25-NOV-2007		
	13370	HRS/MSC	O/C	TSN:0			10566.8		
	REF: AMM 22-13-03	AFL		TSN:0			8881		
224131	SENSOR:PRIMARY YAW DAMPER SENSOR								
22.150	PN	MOS		TSN:0			23-OCT-1978		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-11-04	AFL		TSN:0			0		
225101	SENSOR:LEFT YAW DAMPER FORCE SENSOR								
22.200	PN	MOS		TSN:0			23-OCT-1978		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-11-07	AFL		TSN:0			0		
225103	SENSOR:RIGHT YAW DAMPER FORCE SENSOR								
22.200	PN	MOS		TSN:0			23-OCT-1978		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-11-07	AFL		TSN:0			0		
225105	DETECTOR:YAW DAMPER FORCE DETECTOR								
22.210	PN	MOS		TSN:0			23-OCT-1978		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-11-08	AFL		TSN:0			0		
225107	BOX:THREE AXIS DISCONNECT BOX								
22.220	PN	MOS		TSN:0			23-OCT-1978		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-11-09	AFL		TSN:0			0		
225109	SENSOR:AUTOPILOT ELEVATOR POSITION SENSOR								
22.230	PN	MOS		TSN:0			23-OCT-1978		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-12-03	AFL		TSN:0			0		
<b>CHAPTER 23 COMMUNICATIONS</b>									
230101	TRANSCEIVER:NO. 1 VHF TRANSCEIVER								
23.040	622-1334-002	MOS		TSR:0			20-MAR-1998		
	1363	HRS/MSC	O/C	TSR:0			7813.3		
	REF: AMM 23-11-01	AFL		TSR:0			6377		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
230111	CONTROL:NO. 1 VHF CONTROL								
23.050	PN SN-UNKNOWN REF: AMM 23-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
230121	ANTENNA:NO. 1 VHF ANTENNA								
23.060	PN SN-UNKNOWN REF: AMM 23-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
230601	TRANSCEIVER:NO. 2 VHF TRANSCEIVER								
23.040	622-1879-002 17016 REF: AMM 23-11-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			04-NOV-2007 10562.9 8878		
230611	CONTROL:NO. 2 VHF CONTROL								
23.050	PN SN-UNKNOWN REF: AMM 23-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
230621	ANTENNA:NO. 2 VHF ANTENNA								
23.060	PN SN-UNKNOWN REF: AMM 23-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
230631	RECEIVER/TRANSMITTER:AUXILIARY COMMUNICATION VHF RECEIVER/TRANSMITTER								
23.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
231013	CONTROL PANEL:NO. 1 HF CONTROL PANEL								
	PN SN-UNKNOWN REF: AMM 23-12-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
231031	CONTROL:DUAL VHF CONTROL								
	G-5392 84 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			23-SEP-2002 9789.9 8061		
231060	AMPLIFIER:TCAS AMPLIFIER								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
231101	TRANSCEIVER:NO. 1 HF TRANSCEIVER								
23.010	PN SN-UNKNOWN REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
231111	CONTROLLER:NO. 1 HF CONTROLLER								
23.020	PN SN-UNKNOWN REF: AMM 23-12-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
231121	COUPLER:NO. 1 HF ANTENNA COUPLER								
23.080	PN SN-UNKNOWN REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		



Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
231131	POWER SUPPLY:NO. 1 HF POWER SUPPLY								
	PN	MOS		TSN:0				23-OCT-1978	
23.090	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
231136	TUNER:NO. 1 HF TUNER								
	PN	MOS		TSN:0				23-OCT-1978	
23.100	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
231141	ANTENNA:AUXILIARY COMMUNICATION ANTENNA								
	PN	MOS		TSN:0				23-OCT-1978	
23.030	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
231146	TRANSCEIVER:AUXILIARY VHF COMMUNICATION PORTABLE TRANSCEIVER								
	PN	MOS		TSN:0				23-OCT-1978	
23.030	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
231303	ANTENNA:SKY CONNECT SATCOM ANTENNA								
	PN	MOS		TSN:0				23-OCT-1978	
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
231304	CONTROLLER:SKY CONNECT SATCOM CONTROLLER								
	PN	MOS		TSN:0				23-OCT-1978	
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
231305	TRANSCEIVER:SKY CONNECT SATCOM TRANSCEIVER								
	PN	MOS		TSN:0				23-OCT-1978	
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
231319	INTERFACE UNIT:ANALOG INTERFACE UNIT								
	PN	MOS		TSN:0				23-OCT-1978	
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
231601	TRANSCEIVER:NO. 2 HF TRANSCEIVER								
	PN	MOS		TSN:0				23-OCT-1978	
23.010	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 23-12-01	AFL		TSN:0			0		
231611	CONTROLLER:NO. 2 HF CONTROLLER								
	PN	MOS		TSN:0				23-OCT-1978	
23.020	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 23-12-04	AFL		TSN:0			0		
231621	COUPLER:NO. 2 HF ANTENNA COUPLER								
	PN	MOS		TSN:0				23-OCT-1978	
23.080	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 23-12-02	AFL		TSN:0			0		
231631	ANTENNA:HF ANTENNA								
	PN	MOS		TSN:0				23-OCT-1978	
23.070	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 23-12-03	AFL		TSN:0			0		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
231641	POWER SUPPLY:NO. 2 HF POWER SUPPLY								
23.090	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
231646	TUNER:NO. 2 HF TUNER								
23.100	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
232101	TRANSCEIVER:RADIO TELEPHONE TRANSCEIVER								
23.110	400-0033 2069 REF: AMM 23-13-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			15-MAY-1996 6757.7 5553		
232111	CONTROLLER:CABIN RADIO TELEPHONE CONTROLLER								
23.120	PN SN-UNKNOWN REF: AMM 23-13-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
232121	ANTENNA:RADIO TELEPHONE ANTENNA								
23.130	PN SN-UNKNOWN REF: AMM 23-13-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
232601	CONTROL:PILOT AUDIO CONTROL								
23.140	1250-1 400 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			08-FEB-2000		
232606	CONTROL:COPILOT AUDIO CONTROL								
23.140	1251-1 699 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-NOV-2007 10562.9 8878		
233000	AMPLIFIER:MID CONTINENT AMPLIFIER								
233001	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
233001	DIGITAL INTERFACE UNIT:COLLINS AIRSHOW 400 DIGITAL INTERFACE UNIT								
233007	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
233101	PLAYER:DVD PLAYER								
23.150	PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
233601	GENERATOR:TONE GENERATOR								
23.160	PN SN-UNKNOWN REF: AMM 23-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		

**Model :** LEARJET 35A  
**Owner :** J.E.P. DEVELOPEMENT CORP.  
**Operator :** NORTH DALLAS AVIATION INC.

**A/C Serial #:** 35A210 **A/C Reg. #:** N770JP

**Aircraft HRS:** 10965

**Landings:** 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
234101	STEREO:STEREO								
23.100	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
234106	CONTROLLER:COCKPIT RADIO TELEPHONE CONTROLLER								
23.120	400-0032-2 1762 REF: AMM 23-13-03	MOS HRS/MSC AFL	O/C				20-MAR-1998 7813.3 6377		
234116	HANDSET/HANGER:RADIO TELEPHONE HANDSET/HANGER								
23.130	PN-UNKNOWN 5253 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-MAR-1996 6689.6 5505		
237005	RECORDER:COCKPIT VOICE (CVR) RECORDER								
23.170	89090-00321 A01220 REF: AMM 23-70-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			04-APR-2001 9408.4 7675		
237012	CONTROL:COCKPIT VOICE CONTROL								
23.180	25000-00312 A01073 REF: AMM 23-70-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			24-NOV-2003 10421.9 8753		
237013	MICROPHONE:COCKPIT VOICE RECORDER MICROPHONE								
23.190	PN SN-UNKNOWN REF: AMM 23-70-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
237016	SWITCH:COCKPIT VOICE RECORDER G SWITCH								
23.190	PN SN-UNKNOWN REF: AMM 23-70-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
<b>CHAPTER 24 ELECTRICAL POWER</b>									
240101	INVERTER:PRIMARY AC INVERTER								
24.070	6608109-3 5905-T REF: AMM 24-20-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-DEC-2007 10573.1 8885		
240106	SENSOR:PRIMARY AC OVERLOAD SENSOR								
24.090	PN SN-UNKNOWN REF: AMM 24-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
240111	RELAY:PRIMARY AC POWER RELAY								
24.100	PN SN-UNKNOWN REF: AMM 24-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
240116	AUTOTRANSFORMER:PRIMARY AUTOTRANSFORMER								
24.080	PN SN-UNKNOWN REF: AMM 24-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
240601	INVERTER:SECONDARY AC INVERTER 6608109-3	MOS		TSR:0			04-DEC-2007		
24.070	3279-T REF: AMM 24-20-01	HRS/MSC AFL	O/C	TSR:0 TSR:0			10573.1 8885		
240606	SENSOR:SECONDARY AC OVERLOAD SENSOR PN	MOS		TSN:0			23-OCT-1978		
24.090	SN-UNKNOWN REF: AMM 24-20-03	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
240611	RELAY:SECONDARY AC POWER RELAY PN	MOS		TSN:0			23-OCT-1978		
24.100	SN-UNKNOWN REF: AMM 24-20-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
240616	AUTOTRANSFORMER:SECONDARY AUTOTRANSFORMER PN	MOS		TSN:0			23-OCT-1978		
24.080	SN-UNKNOWN REF: AMM 24-20-05	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
241101	INVERTER:STATIC INVERTER PN	MOS		TSN:0			23-OCT-1978		
24.070	SN-UNKNOWN REF: AMM 24-20-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
241106	SENSOR:AUXILIARY AC OVERLOAD SENSOR PN	MOS		TSN:0			23-OCT-1978		
24.090	SN-UNKNOWN REF: AMM 24-20-03	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
241111	RELAY:AUXILIARY AC POWER RELAY PN	MOS		TSN:0			23-OCT-1978		
24.100	SN-UNKNOWN REF: AMM 24-20-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
241601	CONTROL BOX:AC PARALLEL CONTROL BOX 6608118-1	MOS		TSO:0			02-DEC-2007		
24.120	2517-T3 REF: AMM 24-20-02	HRS/MSC AFL	O/C	TSO:0 TSO:0			10573.1 8885		
241606	VOLTMETER:AC VOLTMETER PN	MOS		TSN:0			23-OCT-1978		
24.130	SN-UNKNOWN REF: AMM 24-31-06	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
242101	GENERATOR:NO. 1 ENGINE GENERATOR 30B107-19A	MOS		TSO:0			06-DEC-2007		<b>OVERHAUL</b>
24.010	1932 REF: AMM 24-31-01	HRS/MSC AFL	2000	TSO:0 TSO:0			10573.4 8886	<b>12573.4</b>	1608.4
242102	GENERATOR:REPLACE NO. 1 ENGINE GENERATOR BEARINGS (IRN C2431016) MOS						06-DEC-2007		<b>SCRAP</b>
24.010	REF: GENERIC NO REF	HRS/MSC AFL	1050				10573.4 8886	<b>11623.4</b>	658.4
242111	REGULATOR:LEFT GENERATOR VOLTAGE REGULATOR 2680014-8	MOS		TSO:0			22-JUL-1999		
24.170	2523U REF: AMM 24-31-03	HRS/MSC AFL	O/C	TSO:0 TSO:0			8515.7		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	PART#/PKG	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
								COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	SERIAL #							ACTUAL	MAX LIMIT		
242121	SENSOR:LEFT GENERATOR OVERLOAD DC SENSOR										
	PN		MOS		TSN:0			23-OCT-1978			
24.110	SN-UNKNOWN		HRS/MSC	O/C	TSN:0			0			
	REF: AMM 24-31-04		AFL		TSN:0			0			
242126	RELAY:LEFT GENERATOR FEEDER BUS RELAY										
	PN		MOS		TSN:0			23-OCT-1978			
24.120	SN-UNKNOWN		HRS/MSC	O/C	TSN:0			0			
	REF: AMM 24-31-05		AFL		TSN:0			0			
242131	AMMETER:LEFT GENERATOR AMMETER										
	4101-3015		MOS		TSN:0			10-JAN-2005			
24.140	470		HRS/MSC	O/C	TSN:0			10438.3			
	REF: AMM 24-31-06		AFL		TSN:0			8767			
242138	REPLACE LEFT ** ESSENTIAL A/B BUS (40A) CIRCUIT BREAKER (IRN G2431047)									<b>SCRAP</b>	
			MOS	144	+14d/-14d			09-APR-2007	<b>30-APR-2019</b>	30-APR-2019	3340 d
24.190			HRS/MSC					10494.2			
	REF: GENERIC NO REF		AFL	6000	+25/-25			8821	<b>14821</b>	14846	5586 (+25)
242601	GENERATOR:NO. 2 ENGINE GENERATOR									<b>OVERHAUL</b>	
	30B107-19-A		MOS		TSO:0			30-JAN-2008			
24.010	1340		HRS/MSC	2000	TSO:0			10618.6	<b>12618.6</b>		1653.6
	REF: AMM 24-31-01		AFL		TSO:0			8919			
242602	GENERATOR:REPLACE NO. 2 ENGINE GENERATOR BEARINGS (IRN C2431016)									<b>SCRAP</b>	
			MOS					30-JAN-2008			
24.010			HRS/MSC	1050				10618.6	<b>11668.6</b>		703.6
	REF: GENERIC NO REF		AFL					8919			
242611	REGULATOR:RIGHT GENERATOR VOLTAGE REGULATOR										
	2680014-8		MOS		TSR:0			03-MAR-1998			
24.170	1025U		HRS/MSC	O/C	TSR:0			7774			
	REF: AMM 24-31-03		AFL		TSR:0			6346			
242621	SENSOR:RIGHT GENERATOR OVERLOAD DC SENSOR										
	PN		MOS		TSN:0			23-OCT-1978			
24.110	SN-UNKNOWN		HRS/MSC	O/C	TSN:0			0			
	REF: AMM 24-31-04		AFL		TSN:0			0			
242626	RELAY:RIGHT GENERATOR OVERLOAD DC RELAY										
	PN		MOS		TSN:0			23-OCT-1978			
24.120	SN-UNKNOWN		HRS/MSC	O/C	TSN:0			0			
	REF: AMM 24-31-05		AFL		TSN:0			0			
242631	AMMETER:RIGHT GENERATOR AMMETER										
	4101-3011		MOS		TSO:0			06-FEB-1998			
24.140	287		HRS/MSC	O/C	TSO:0			7727			
	REF: AMM 24-31-06		AFL		TSO:0			6313			
242643	REPLACE RIGHT ** ESSENTIAL A/B BUS (40A) CIRCUIT BREAKER (IRN G2431045)									<b>SCRAP</b>	
			MOS	144	+14d/-14d			09-APR-2007	<b>30-APR-2019</b>	30-APR-2019	3340 d
24.190			HRS/MSC					10494.2			
	REF: GENERIC NO REF		AFL	6000	+25/-25			8821	<b>14821</b>	14846	5586 (+25)
242648	REPLACE ** MAIN BUS TIE (50A) CIRCUIT BREAKER (IRN G2431049)									<b>SCRAP</b>	
			MOS	144	+14d/-14d			09-APR-2007	<b>30-APR-2019</b>	30-APR-2019	3340 d
24.190			HRS/MSC					10494.2			
	REF: GENERIC NO REF		AFL	6000	+25/-25			8821	<b>14821</b>	14846	5586 (+25)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
+ 243053	BATTERY:INSPECT NO. 1 BATTERY INSTALLATION (IRN B2432010)	MOS	6	+14d/-14d			25-OCT-2009	30-APR-2010	09-MAY-2010	53 d (+9)
24.020	REF: AMM 24-32-01	HRS/MSC AFL					10911.9 9181			
+ 243054	BATTERY:INSPECT NO. 2 BATTERY INSTALLATION (IRN B2432010)	MOS	6	+14d/-14d			25-OCT-2009	30-APR-2010	09-MAY-2010	53 d (+9)
24.025	REF: AMM 24-32-01	HRS/MSC AFL					10911.9 9181			
243080	DISCHARGE/RECHARGE EMERGENCY EXIT AND WING INSPECTION LIGHT POWER SUPPLY (IRN C1223021)	MOS					15-SEP-2004	<b>N/A EQUIPMENT NOT INSTALLED</b>		
24.200	REF: AMM 12-23-02	HRS/MSC AFL	N/A				10437.5 8766			
243101	CONTROL PANEL:GENERATOR CONTROL PANEL	MOS					03-MAR-1998			
24.150	6608205-6 324 REF: AMM 24-31-02	HRS/MSC AFL	O/C				7774 6346			
243106	VOLTMETER:DC VOLTMETER	MOS					10-JUN-1993			
24.130	4006-3001 166 REF: AMM 24-31-06	HRS/MSC AFL	O/C		TSR:0 TSR:0 TSR:0		5859.8 4800			
243121	BATTERY:NO. 1 BATTERY	MOS					01-AUG-2008			
24.020	G-6381E G02406179 REF: AMM 24-32-01	HRS/MSC AFL	O/C		TSO:0 TSO:0 TSO:0		10735.6 9013			
+ 243122	BATTERY:CHECK/SERVICE NO. 1 BATTERY (CAP)	MOS	6	+1m/-1m			25-OCT-2009	30-APR-2010	25-MAY-2010	53 d (+25)
24.020	REF: AMM 24-32-01	HRS/MSC AFL	400				10911.9 9181	11311.9		346.9
+ 243131	INSPECT NO. 1 BATTERY CABLES AND RECEPTACLES (IRN H2431017)	MOS	300	+25/-25			29-AUG-2008	11053.8	11078.8	88.8 (+25)
24.020	REF: AMM 24-32-01	HRS/MSC AFL					10753.8 9029			
+ 243132	INSPECT NO. 2 BATTERY CABLES AND RECEPTACLES (IRN H2431017)	MOS	300	+25/-25			29-AUG-2008	11053.8	11078.8	88.8 (+25)
24.025	REF: AMM 24-32-01	HRS/MSC AFL					10753.8 9029			
243601	BATTERY:NO. 2 BATTERY	MOS					01-AUG-2008			
24.025	G6381E G02228806 REF: AMM 24-32-01	HRS/MSC AFL	O/C		TSO:0 TSO:0 TSO:0		10735.6 9013			
+ 243602	BATTERY:CHECK/SERVICE NO. 2 BATTERY (CAP)	MOS	6	+1m/-1m			25-OCT-2009	30-APR-2010	25-MAY-2010	53 d (+25)
24.025	REF: AMM 24-32-01	HRS/MSC AFL	400				10911.9 9181	11311.9		346.9
244101	TEMPERATURE SWITCH:NO. 1 BATTERY LOW LIMIT TEMPERATURE SWITCH	MOS					23-OCT-1978			
24.040	PN SN-UNKNOWN REF: AMM 24-32-04	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0			

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
244103	TEMPERATURE SWITCH:NO. 1 BATTERY HIGH LIMIT TEMPERATURE SWITCH									
	PN	MOS		TSN:0			23-OCT-1978			
24.050	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 24-32-04	AFL		TSN:0			0			
244106	THERMISTOR:NO. 1 BATTERY THERMISTOR									
	PN	MOS		TSN:0			23-OCT-1978			
24.030	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 24-32-03	AFL		TSN:0			0			
244116	TEMPERATURE SWITCH:NO. 2 BATTERY LOW LIMIT TEMPERATURE SWITCH									
	PN	MOS		TSN:0			23-OCT-1978			
24.040	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 24-32-04	AFL		TSN:0			0			
244119	TEMPERATURE SWITCH:NO. 2 BATTERY HIGH LIMIT TEMPERATURE SWITCH									
	PN	MOS		TSN:0			23-OCT-1978			
24.050	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 24-32-04	AFL		TSN:0			0			
244121	THERMISTOR:NO. 2 BATTERY THERMISTOR									
	PN	MOS		TSN:0			23-OCT-1978			
24.030	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 24-32-03	AFL		TSN:0			0			
244136	INDICATOR:BATTERY TEMPERATURE INDICATOR									
	PN	MOS		TSN:0			23-OCT-1978			
24.160	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 24-32-02	AFL		TSN:0			0			
244601	POWER SUPPLY:NO. 1 EMERGENCY POWER SUPPLY									
	501-1075-02 (PS823B)	MOS					13-FEB-2008			
24.060	3107	HRS/MSC	O/C				10630.2			
	REF: AMM 24-33-01	AFL					8930			
+ 244602	POWER SUPPLY:INSPECT NO. 1 EMERGENCY POWER SUPPLY NI-CAD BATTERY (IRN D1223000)									
	MOS	3	+14d/-14d		-23		17-FEB-2010	<b>30-APR-2010</b>	09-MAY-2010	53 d (+9)
24.060	HRS/MSC	100	+25/-25				10956.5	<b>11056.5</b>	11081.5	91.5 (+25)
	REF: AMM 24-33-01	AFL					9224			
+ 244604	POWER SUPPLY:DISCHARGE/RECHARGE NO. 1 EMERGENCY POWER SUPPLY BATTERY (IRN D1223001 OR IRN D1223015)									
	MOS	12	+14d/-14d				25-OCT-2009	<b>31-OCT-2010</b>	08-NOV-2010	237 d (+8)
24.060	HRS/MSC						10911.9			
	REF: AMM 12-23-01	AFL					9181			
5-10-29-E2431030-L	REMOVE/INSPECT AND LUBRICATE GENERATOR DRIVE SPLINE ADAPTER.									
	MOS						17-FEB-2010			
	HRS/MSC	MPI					10956.5			
	REF:	AFL					9224			
5-10-29-E2431030-R	REMOVE/INSPECT AND LUBRICATE GENERATOR DRIVE SPLINE ADAPTER.									
	MOS						17-FEB-2010			
	HRS/MSC	MPI					10956.5			
	REF:	AFL					9224			

**CHAPTER 25 EQUIPMENT/FURNISHINGS**

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
250101	SEAT:PILOT SEAT								
25.010	PN SN-UNKNOWN REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
250106	BELT:PILOT SEAT BELT								
25.020	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
250111	REEL:PILOT SHOULDER HARNESS / REEL								
25.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
250601	SEAT:COPILLOT SEAT								
25.010	PN SN-UNKNOWN REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
250606	BELT:COPILLOT SEAT BELT								
25.020	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
250611	REEL:COPILLOT SHOULDER HARNESS/ REEL								
25.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
250616	SEAT:LEFT FORWARD SWIVEL SEAT								
25.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
250621	SEAT:LEFT AFT SWIVEL SEAT								
25.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
250626	SEAT:RIGHT FORWARD SWIVEL SEAT								
25.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
250631	SEAT:RIGHT AFT SWIVEL SEAT								
25.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
251107	INTERFACE UNIT:ELT/NAV INTERFACE UNIT								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
251116	CHARGER:EMERGENCY LOCATING CHARGER								
25.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		



Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
251121	ANTENNA:NO. 1 EMERGENCY LOCATING ANTENNA									
25.080	PN-UNKNOWN 14209 REF: AMM 25-63-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-MAR-1992 5481			
251126	ANTENNA:NO. 2 EMERGENCY LOCATING ANTENNA									
25.080	PN SN-UNKNOWN REF: AMM 25-63-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
252015	DIVAN:LEFT PASSENGER DIVAN									
	PN SN-UNKNOWN REF: AMM 25-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
252016	DIVAN:RIGHT PASSENGER DIVAN									
	PN SN-UNKNOWN REF: AMM 25-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
252101	DRAG CHUTE:MAIN DRAG CHUTE									
25.090	6600180-11 JUL81-002749 REF: AMM 25-62-00	MOS HRS/MSC AFL	O/C				31-MAY-2005 10446.8			
252106	DRAG CHUTE:PILOT DRAG CHUTE									
25.090	PN SN-UNKNOWN REF: AMM 25-62-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
252111	CANISTER:DRAG CHUTE CANISTER									
25.130	PN SN-UNKNOWN REF: AMM 25-62-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
252116	LID:DRAG CHUTE CANISTER LID									
25.100	2488717-14 SN-UNKNOWN REF: AMM 25-62-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-NOV-2001 9585.1 7825			
+ 252121	DRAG CHUTE:FUNCTIONAL TEST	MAIN DRAG CHUTE (IRN E2562001)								
25.090		MOS HRS/MSC AFL	6 +14d/-14d		6		14-DEC-2009 10935 9208	30-JUN-2010	04-JUL-2010	114 d (+4)
252131	CABLE ASSEMBLY:DRAG CHUTE CABLE ASSEMBLY									
25.100	PN SN-UNKNOWN REF: AMM 25-62-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
256005	BEACON:COCKPIT VOICE RECORDER (CVR) UNDERWATER LOCATING BEACON									
25.110	DK100 DR3441 REF: AMM 25-64-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-DEC-1999 8739.5 7150			
256011	BEACON:REPLACE COCKPIT VOICE RECORDER (CVR) UNDERWATER LOCATING BEACON ** BATTERY (IRN F2566000)									
25.110		MOS HRS/MSC AFL	DUE				11-JUN-2007 10494.7 8823	31-JUL-2012 M		876 d

**Model :** LEARJET 35A  
**Owner :** J.E.P. DEVELOPEMENT CORP.  
**Operator :** NORTH DALLAS AVIATION INC.

**A/C Serial #:** 35A210 **A/C Reg. #:** N770JP

**Aircraft HRS:** 10965

**Landings:** 9235

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
+ 256012	BEACON:CLEAN/TEST COCKPIT VOICE RECORDER (CVR) UNDERWATER LOCATING BEACON (IRN F2565000)	MOS	24				29-APR-2009	<b>30-APR-2011</b>	418 d
25.110	REF: CMM SECTION IV,V,VI	HRS/MSC AFL					10810 9080		
256061	VEST:NO. 1 LIFE VEST 21850-6300 2-90-13101 REF:	MOS HRS/MSC AFL	O/C	TSN:193			01-MAR-2006 10469.7		
256061A	VEST:INSPECT NO. 1 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS 05-10-29-P2561005	MOS	12				29-APR-2009	<b>30-APR-2010</b>	53 d
	REF: See Workcard	HRS/MSC AFL					10810 9080		
256062	VEST:NO. 2 LIFE VEST PO723E-109P 83230 REF:	MOS HRS/MSC AFL	O/C	TSN:189			01-MAR-2006 10469.7		
256062A	VEST:INSPECT NO. 2 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS 05-10-29-P2561005	MOS	12				29-APR-2009	<b>30-APR-2010</b>	53 d
	REF: See Workcard	HRS/MSC AFL					10810 9080		
256063	VEST:NO. 3 LIFE VEST S11150-1301 86-58878 REF:	MOS HRS/MSC AFL	O/C	TSN:234			01-MAR-2006 10469.7		
256063A	VEST:INSPECT NO. 3 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS 05-10-29-P2561005	MOS	12				29-APR-2009	<b>30-APR-2010</b>	53 d
	REF: See Workcard	HRS/MSC AFL					10810 9080		
256064	VEST:NO. 4 LIFE VEST S21150-6300 2-98-14012-1141 REF:	MOS HRS/MSC AFL	O/C	TSN:97			01-MAR-2006 10469.7		
256064A	VEST:INSPECT NO. 4 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS 05-10-29-P2561005	MOS	12				29-APR-2009	<b>30-APR-2010</b>	53 d
	REF: See Workcard	HRS/MSC AFL					10810 9080		
256065	VEST:NO. 5 LIFE VEST PO1074-101 606344 REF:	MOS HRS/MSC AFL	O/C	TSN:35			01-MAR-2006 10469.7		
256065A	VEST:INSPECT NO. 5 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS 05-10-29-P2561005	MOS	12				29-APR-2009	<b>30-APR-2010</b>	53 d
	REF: See Workcard	HRS/MSC AFL					10810 9080		
256066	VEST:NO. 6 LIFE VEST PN-UNKNOWN B85358 REF:	MOS HRS/MSC AFL	O/C	TSN:299			01-MAR-2006 10469.7		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
256066A	VEST:INSPECT NO. 6 LIFE VEST REF: See Workcard	PER MANUFACTURER'S INSTRUCTIONS MOS HRS/MSC AFL	12	05-10-29-P2561005		29-APR-2009 10810 9080	<b>30-APR-2010</b>	53 d	
256067	VEST:NO. 7 LIFE VEST PO723E105P 95180 REF:	MOS HRS/MSC AFL	O/C	TSN:103		01-MAR-2006 10469.7			
256067A	VEST:INSPECT NO. 7 LIFE VEST REF: See Workcard	PER MANUFACTURER'S INSTRUCTIONS MOS HRS/MSC AFL	12	05-10-29-P2561005		29-APR-2009 10810 9080	<b>30-APR-2010</b>	53 d	
256068	VEST:NO. 8 LIFE VEST P01074-101 967889 REF:	MOS HRS/MSC AFL	O/C			18-APR-2008 10686.2 8968			
256068A	VEST:INSPECT NO. 8 LIFE VEST REF: See Workcard	PER MANUFACTURER'S INSTRUCTIONS MOS HRS/MSC AFL	12	05-10-29-P2561005		29-APR-2009 10810 9080	<b>30-APR-2010</b>	53 d	
256071	VEST:PILOT LIFE VEST 3505-101 L1101896 REF:	MOS HRS/MSC AFL	O/C	TSN:112		01-MAR-2006 10469.7			
256071A	VEST:INSPECT PILOT LIFE VEST REF: CMM 25-60-05	PER MANUFACTURER'S INSTRUCTIONS MOS HRS/MSC AFL	12	05-10-29-P2561005		29-APR-2009 10810 9080	<b>30-APR-2010</b>	53 d	
256072	VEST:COPILOT LIFE VEST S51150-6300 21808-1660 REF:	MOS HRS/MSC AFL	O/C	TSN:96		01-MAR-2006 10469.7			
256072A	VEST:INSPECT COPILOT LIFE VEST REF: AMM 25-61-00	PER MANUFACTURER'S INSTRUCTIONS MOS HRS/MSC AFL	12	05-10-29-P2561005		29-APR-2009 10810 9080	<b>30-APR-2010</b>	53 d	
256116	EMERGENCY LOCATOR TRANSMITTER:(ARTEX ELT-200) EMERGENCY LOCATOR TRANSMITTER 453-0190 E06877 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		03-FEB-2004 10421.9 8753			
256116A	EMERGENCY LOCATOR TRANSMITTER:INSPECT/FUNCTIONAL CHECK (ARTEX ELT-200) EMERGENCY LOCATOR TRANSMITTER (12 MONTH) REF: OMM FAR 91.207 & ARTEX 570-1032	MOS HRS/MSC AFL	12			29-APR-2009 10810 9080	<b>30-APR-2010</b>	53 d	

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965 Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
WORKCARD	PART#/PKG SERIAL #									
256116B	EMERGENCY LOCATOR TRANSMITTER:REPLACE BATTERY (ARTEX ELT-200) EMERGENCY LOCATOR TRANSMITTER	MOS					22-JAN-2008	31-MAY-2010	M	84 d
	REF: OMM FAR 91.207 & ARTEX 570-1032	HRS/MSC AFL	DUE				10616.8 8915			
256116C	EMERGENCY LOCATOR TRANSMITTER:REPLACE REMOTE SWITCH BATTERY	MOS	24				29-APR-2009	30-APR-2011		INSPECT 418 d
	REF: OMM FAR 91.207 & ARTEX 570-1032	HRS/MSC AFL					10810 9080			
<b>CHAPTER 26 FIRE PROTECTION</b>										
260001	EXTINGUISHER:INSPECT PORTABLE FIRE EXTINGUISHER FIRE BOTTLE MONTHLY	MOS	1				17-FEB-2010	31-MAR-2010		23 d
	REF: OMM NDA LJ 35/36 AAIP APPENDIX E	HRS/MSC AFL					10956.5 9224			
260002	EXTINGUISHER:ANNUAL PORTABLE FIRE EXTINGUISHER WEIGHT CHECK	MOS	12				07-DEC-2009	31-DEC-2010		298 d
	REF: OMM NDA LJ35/36 AAIP APPENDIX E	HRS/MSC AFL					10928.4 9202			
260003	EXTINGUISHER:INTERNAL INSPECTION PORTABLE FIRE EXTINGUISHER	MOS	72				01-JAN-2007	31-JAN-2013		1060 d
	REF: OMM NDA LJ35/36 AAIP APPENDIX E	HRS/MSC AFL								
260101	EXTINGUISHER:NO. 1 ENGINE FIRE EXTINGUISHER	MOS		TSO:0			23-JAN-2004			
26.010	30402102 B13794	HRS/MSC AFL	O/C	TSO:0 TSO:0			10421.9 8753			
260108	WEIGHT CHECK AND PERFORM FUNCTIONAL TEST OF ENGINE FIRE EXTINGUISHER SYSTEM (IRN Q2620010)	MOS					15-APR-2008			
26.010	REF: See Workcard	HRS/MSC AFL	-				10686.2 8963			
+ 260111	EXTINGUISHER:HYDROSTATIC TEST NO. 1 ENGINE FIRE EXTINGUISHER (IRN Q2620025)	MOS	60		-7		30-JAN-2009	31-JAN-2014	MANDATORY	1425 d
26.010	REF:	HRS/MSC AFL					10765.3 9039			
260131	VALVE:LEFT 2 WAY CHECK VALVE	MOS		TSN:0			23-OCT-1978			
26.030	PN SN-UNKNOWN	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
	REF: GENERIC NO REF									
260601	EXTINGUISHER:NO. 2 ENGINE FIRE EXTINGUISHER	MOS		TSO:0			23-JAN-2004			
26.020	30402102 B361	HRS/MSC AFL	O/C	TSO:0 TSO:0			10421.9 8753			
	REF: AMM 26-20-01									

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
260608	WEIGHT CHECK AND PERFORM FUNCTIONAL TEST OF ENGINE FIRE EXTINGUISHER SYSTEM (IRN Q2620010)	MOS					15-APR-2008		
26.020		HRS/MSC -					10686.2		
	REF: See Workcard	AFL					8963		
+ 260611	EXTINGUISHER:HYDROSTATIC TEST NO. 2 ENGINE FIRE EXTINGUISHER (IRN Q2620025)	MOS	60		-7		30-JAN-2009	31-JAN-2014	MANDATORY
26.020		HRS/MSC					10765.3		1425 d
	REF:	AFL					9039		
260631	VALVE:RIGHT 2 WAY CHECK VALVE	PN		TSN:0			23-OCT-1978		
26.030	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
261101	ELEMENT:NO. 1 ENGINE TAILCONE SENSOR ELEMENT	PN		TSN:0			23-OCT-1978		
26.060	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 26-10-01	AFL		TSN:0			0		
261106	ELEMENT:NO. 1 ENGINE FIREWALL SENSOR ELEMENT	PN		TSN:0			23-OCT-1978		
26.070	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 26-10-01	AFL		TSN:0			0		
261111	ELEMENT:NO. 1 ENGINE GEARBOX SENSOR ELEMENT	PN		TSN:0			23-OCT-1978		
26.080	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 26-10-01	AFL		TSN:0			0		
261116	CONTROL:NO. 1 ENGINE FIRE DETECTOR CONTROL	PN		TSN:0			23-OCT-1978		
26.090	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 26-10-04	AFL		TSN:0			0		
261601	ELEMENT:NO. 2 ENGINE TAILCONE SENSOR ELEMENT	PN		TSN:0			23-OCT-1978		
26.060	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 26-10-01	AFL		TSN:0			0		
261606	ELEMENT:NO. 2 ENGINE FIREWALL SENSOR ELEMENT	PN		TSN:0			23-OCT-1978		
26.070	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 26-10-01	AFL		TSN:0			0		
261611	ELEMENT:NO. 2 ENGINE GEARBOX SENSOR ELEMENT	PN		TSN:0			23-OCT-1978		
26.080	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 26-10-01	AFL		TSN:0			0		
261616	CONTROL:NO. 2 ENGINE FIRE DETECTOR CONTROL	PN		TSN:0			23-OCT-1978		
26.090	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 26-10-04	AFL		TSN:0			0		
+ 262028	EXTINGUISHER:CHECK NO. 1 ENGINE FIRE EXTINGUISHER PRESSURE GAGE FOR PROPER PRESSURE AND PLUMBING FOR CONDITION AND SECURITY (IRN P2620042)	MOS	6	+14d/-14d	7		22-JAN-2010	31-JUL-2010	12-AUG-2010
26.115		HRS/MSC					10951.2		145 d (+12)
	REF: GENERIC NO REF	AFL					9219		

?-Insufficient Information (EFF)-Effective C/W

+-Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								NEXT DUE ACTUAL	NEXT DUE MAX LIMIT	
WORKCARD	PART#/PKG SERIAL #									
262029	EXTINGUISHER:CHECK NO. 2 ENGINE FIRE EXTINGUISHER PRESSURE GAGE FOR PROPER PRESSURE AND PLUMBING FOR CONDITION AND SECURITY (IRN P2620042)	MOS	6	+14d/-14d		7	22-JAN-2010	31-JUL-2010	12-AUG-2010	145 d (+12)
	REF:	HRS/MSC					10951.2			
		AFL					9219			
262044	REPLACE NO. 1 ENGINE NO.1 CARTRIDGE (LIFE LIMIT)	MOS	72	+14d/-14d			01-AUG-2009	31-AUG-2015	31-AUG-2015	2002 d
26.010	REF: See Workcard	HRS/MSC								
		AFL								
262045	REPLACE NO. 1 ENGINE NO.2 CARTRIDGE (LIFE LIMIT)	MOS	72	+14d/-14d			01-AUG-2009	31-AUG-2015	31-AUG-2015	2002 d
26.010	REF: See Workcard	HRS/MSC								
		AFL								
262046	REPLACE NO. 2 ENGINE NO.1 CARTRIDGE (LIFE LIMIT)	MOS	72	+14d/-14d			01-AUG-2009	31-AUG-2015	31-AUG-2015	2002 d
26.020	REF: See Workcard	HRS/MSC								
		AFL								
262047	REPLACE NO. 2 ENGINE NO.2 CARTRIDGE (LIFE LIMIT)	MOS	72	+14d/-14d			01-AUG-2009	31-AUG-2015	31-AUG-2015	2002 d
26.020	REF: See Workcard	HRS/MSC								
		AFL								
262101	SWITCH:NO. 1 LEFT EXTINGUISHER ARMED SWITCH	MOS						23-OCT-1978		
26.100	PN	HRS/MSC	O/C					0		
	SN-UNKNOWN	AFL						0		
	REF: AMM 26-10-02									
262106	SWITCH:NO. 2 LEFT EXTINGUISHER ARMED SWITCH	MOS						23-OCT-1978		
26.040	PN	HRS/MSC	O/C					0		
	SN-UNKNOWN	AFL						0		
	REF: AMM 26-10-02									
262111	SWITCH:NO. 1 ENGINE FIRE SWITCH	MOS						23-OCT-1978		
26.110	PN	HRS/MSC	O/C					0		
	SN-UNKNOWN	AFL						0		
	REF: AMM 26-10-03									
262601	SWITCH:NO. 1 RIGHT EXTINGUISHER ARMED SWITCH	MOS						23-OCT-1978		
26.100	PN	HRS/MSC	O/C					0		
	SN-UNKNOWN	AFL						0		
	REF: AMM 26-10-02									
262606	SWITCH:NO. 2 RIGHT EXTINGUISHER ARMED SWITCH	MOS						23-OCT-1978		
26.040	PN	HRS/MSC	O/C					0		
	SN-UNKNOWN	AFL						0		
	REF: AMM 26-10-02									
262611	SWITCH:NO. 2 ENGINE FIRE SWITCH	MOS						23-OCT-1978		
26.110	PN	HRS/MSC	O/C					0		
	SN-UNKNOWN	AFL						0		
	REF: AMM 26-10-03									
263601	EXTINGUISHER:PORTABLE FIRE EXTINGUISHER	MOS						19-DEC-2007		
26.055	C352	HRS/MSC	O/C					10574.2		
	X-412382	AFL						8888		
	REF: GENERIC NO REF									

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
+ 263611	EXTINGUISHER:HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER (IRN C2620030)	MOS	144				20-JUL-2007	01-JAN-2019	M	3221 d
26.055	REF: GENERIC NO REF	HRS/MSC AFL								
5-10-29-E2610020-L	INSPECT ENGINE TAILCONE FIRE DETECTOR ELEMENT FOR CHAFING, SECURITY OF CLAMPS, AND GENERAL CONDITION.	MOS					17-FEB-2010			
	REF:	HRS/MSC AFL	MPI				10956.5 9224			
5-10-29-E2610020-R	INSPECT ENGINE TAILCONE FIRE DETECTOR ELEMENT FOR CHAFING, SECURITY OF CLAMPS, AND GENERAL CONDITION.	MOS					17-FEB-2010			
	REF:	HRS/MSC AFL	MPI				10956.5 9224			
<b>CHAPTER 27 FLIGHT CONTROLS</b>										
270101	AILERON:LEFT AILERON									<b>LIFE LIMIT</b>
27.060	PN SN-UNKNOWN REF: AMM 27-10-01	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0	20000		9035
270103	AILERON:REPLACE LEFT AILERON * INBOARD AND OUTBOARD HINGE BOLTS (AN4H12A) (IRN M2710021)	MOS					23-OCT-1978			<b>LIFE LIMIT</b>
27.060	REF: GENERIC NO REF	HRS/MSC AFL	20000				0 0	20000		9035
270104	AILERON:REPLACE LEFT AILERON * HINGE BRACKET ASSEMBLY ON WING (2322530) (IRN E2710031)	MOS					23-OCT-1978			<b>LIFE LIMIT</b>
27.060	REF: GENERIC NO REF	HRS/MSC AFL	20000				0 0	20000		9035
270106	ACTUATOR:LEFT AILERON ACTUATOR									<b>LIFE LIMIT</b>
27.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
270107	ACTUATOR:REPLACE LEFT AILERON ACTUATOR * PULLEY ASSEMBLY (2324513) (IRN E2710023)	MOS					23-OCT-1978			<b>LIFE LIMIT</b>
27.690	REF: GENERIC NO REF	HRS/MSC AFL	20000				0 0	20000		9035
270108	ACTUATOR:REPLACE LEFT AILERON ACTUATOR * CLEVIS (2324512 OR 2324517) (IRN E2710025)	MOS					23-OCT-1978			<b>LIFE LIMIT</b>
27.695	REF: GENERIC NO REF	HRS/MSC AFL	20000				0 0	20000		9035
270109	ACTUATOR:REPLACE LEFT AILERON ACTUATOR * YOKE ASSEMBLY (2324511 OR 2324518) (IRN E2710027)	MOS					23-OCT-1978			<b>LIFE LIMIT</b>
27.700	REF: GENERIC NO REF	HRS/MSC AFL	20000				0 0	20000		9035
270110	ACTUATOR:REPLACE LEFT AILERON ACTUATOR * BEARING SUPPORT ASSEMBLY (2324505 OR 2324510) (IRN E2710029)	MOS					23-OCT-1978			<b>LIFE LIMIT</b>
27.705	REF: GENERIC NO REF	HRS/MSC AFL	20000				0 0	20000		9035

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
270111	AILERON:REPLACE LEFT AILERON * DRIVE YOKE BOLT (NAS1104-38D) (IRN E2710010)	MOS							LIFE LIMIT
27.080	REF: GENERIC NO REF	HRS/MSC AFL	3600				16-APR-1999 8396.5 6845	11996.5	1031.5
270116	AILERON:REPLACE LEFT AILERON * CENTER HINGE BOLT (AN4H13A) (IRN E2710014)	MOS							LIFE LIMIT
27.090	REF: GENERIC NO REF	HRS/MSC AFL	3600				23-SEP-2002 9789.9 8061	13389.9	2424.9
270118	AILERON:REPLACE LEFT AILERON * CLEVIS BOLT (NAS464P4) (IRN E2710020)	MOS							LIFE LIMIT
27.100	REF: GENERIC NO REF	HRS/MSC AFL	20000				25-AUG-1989 4789.2 3883	24789.2	13824.2
270121	TAB:AILERON TRIM TAB	PN		TSN:0					
27.110	SN-UNKNOWN REF: AMM 27-10-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			23-OCT-1978 0 0		
270126	ACTUATOR:AILERON TRIM TAB ACTUATOR	PN		TSN:0					
27.450	SN-UNKNOWN REF: AMM 27-10-06	HRS/MSC AFL	O/C	TSN:0 TSN:0			23-OCT-1978 0 0		
270131	POTENTIOMETER:AILERON TRIM POTENTIOMETER	PN		TSN:0					
27.450	SN-UNKNOWN REF: AMM 27-10-06	HRS/MSC AFL	O/C	TSN:0 TSN:0			23-OCT-1978 0 0		
270136	TAB:LEFT AILERON BALANCE TAB	PN		TSN:0					
27.110	SN-UNKNOWN REF: AMM 27-10-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			23-OCT-1978 0 0		
270601	AILERON:RIGHT AILERON	PN		TSN:0					LIFE LIMIT
27.060	SN-UNKNOWN REF: AMM 27-10-01	HRS/MSC AFL	20000	TSN:0 TSN:0			23-OCT-1978 0 0	20000	9035
270603	AILERON:REPLACE RIGHT AILERON * INBOARD AND OUTBOARD HINGE BOLTS (AN4H12A) (IRN M2710021)	MOS							LIFE LIMIT
27.060	REF: GENERIC NO REF	HRS/MSC AFL	20000				23-OCT-1978 0 0	20000	9035
270604	AILERON:REPLACE RIGHT AILERON * HINGE BRACKET ASSEMBLY ON WING (2322530) (IRN E2710031)	MOS							LIFE LIMIT
27.060	REF: GENERIC NO REF	HRS/MSC AFL	20000				23-OCT-1978 0 0	20000	9035
270606	ACTUATOR:RIGHT AILERON ACTUATOR	PN		TSN:0					
27.070	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			23-OCT-1978 0 0		
270607	ACTUATOR:REPLACE RIGHT AILERON ACTUATOR * PULLEY ASSEMBLY (2324513) (IRN E2710023)	MOS							LIFE LIMIT
27.690	REF: GENERIC NO REF	HRS/MSC AFL	20000				23-OCT-1978 0 0	20000	9035

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)



Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
270608	ACTUATOR:REPLACE RIGHT AILERON ACTUATOR * CLEVIS (2324512 OR 2324517) (IRN E2710025)	MOS					23-OCT-1978		LIFE LIMIT	
27.695	REF: GENERIC NO REF	HRS/MSC AFL	20000				0 0	20000		9035
270609	ACTUATOR:REPLACE RIGHT AILERON ACTUATOR * YOKE ASSEMBLY (2324511 OR 2324518) (IRN E2710027)	MOS					23-OCT-1978		LIFE LIMIT	
27.700	REF: GENERIC NO REF	HRS/MSC AFL	20000				0 0	20000		9035
270610	ACTUATOR:REPLACE RIGHT AILERON ACTUATOR * BEARING SUPPORT ASSEMBLY (2324505 OR 2324510) (IRN E2710029)	MOS					23-OCT-1978		LIFE LIMIT	
27.705	REF: GENERIC NO REF	HRS/MSC AFL	20000				0 0	20000		9035
270611	AILERON:REPLACE RIGHT AILERON * DRIVE YOKE BOLT (NAS1104-38D) (IRN E2710010)	MOS					16-APR-1999		LIFE LIMIT	
27.080	REF: GENERIC NO REF	HRS/MSC AFL	3600				8396.5 6845	11996.5		1031.5
270616	AILERON:REPLACE RIGHT AILERON * CENTER HINGE BOLT (AN4H13A) (IRN E2710014)	MOS					23-SEP-2002		LIFE LIMIT	
27.090	REF: GENERIC NO REF	HRS/MSC AFL	3600				9789.9 8061	13389.9		2424.9
270618	AILERON:REPLACE RIGHT AILERON * CLEVIS BOLT (NAS464P4) (IRN E2710020)	MOS					25-AUG-1989		LIFE LIMIT	
27.100	REF: GENERIC NO REF	HRS/MSC AFL	20000				4789.2 3883	24789.2		13824.2
270621	TAB:RIGHT AILERON BALANCE TAB	MOS		TSN:0			23-OCT-1978			
27.110	SN-UNKNOWN REF: AMM 27-10-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
271101	WHEEL:PILOT CONTROL WHEEL	MOS		TSN:0			23-OCT-1978			
27.020	SN-UNKNOWN REF: AMM 27-10-05	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
271111	COLUMN:CONTROL COLUMN	MOS		TSN:0			23-OCT-1978			
27.010	SN-UNKNOWN REF: AMM 27-30-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
271121	WHEEL:COPILOT CONTROL WHEEL	MOS		TSN:0			23-OCT-1978			
27.020	SN-UNKNOWN REF: AMM 27-10-05	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
271141	SWITCH:PILOT TRIM/TAB ARM SWITCH	MOS		TSN:0			23-OCT-1978			
27.410	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
271146	SWITCH:COPILOT TRIM/TAB ARM SWITCH	MOS					30-MAR-2001			
27.410	403-4300 SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C				9406.3 7672			

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
271601	CABLE:LEFT AILERON CONTROL WHEEL INTERCONNECT (PRIMARY) CABLE 2300003-243	MOS		TSN:0					SCRAP
27.710	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	2400	TSN:0 TSN:0			16-NOV-2001 9585.1 7825	11985.1	1020.1
271606	CABLE:RIGHT AILERON CONTROL WHEEL INTERCONNECT (PRIMARY) CABLE 2300003-216	MOS		TSN:0					SCRAP
27.710	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	2400	TSN:0 TSN:0			16-NOV-2001 9585.1 7825	11985.1	1020.1
271611	CABLE:LEFT AILERON FORWARD CABLE 2300003-245	MOS		TSN:0					SCRAP
27.720	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	2400	TSN:0 TSN:0			16-NOV-2001 9585.1 7825	11985.1	1020.1
271616	CABLE:RIGHT AILERON FORWARD CABLE 2300003-256	MOS		TSN:0					SCRAP
27.720	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	2400	TSN:0 TSN:0			16-NOV-2001 9585.1 7825	11985.1	1020.1
271621	CABLE:AILERON AFT SECTOR CABLE 2300003-17	MOS		TSN:0					SCRAP
27.730	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	2400	TSN:0 TSN:0			16-NOV-2001 9585.1 7825	11985.1	1020.1
271626	CABLE:LEFT AILERON INBOARD CABLE 2300003-78	MOS		TSN:0					SCRAP
27.740	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	2400	TSN:0 TSN:0			16-NOV-2001 9585.1 7825	11985.1	1020.1
271631	CABLE:LEFT AILERON OUTBOARD CABLE 2300003-16	MOS		TSN:0					SCRAP
27.750	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	2400	TSN:0 TSN:0			16-NOV-2001 9585.1 7825	11985.1	1020.1
271636	CABLE:RIGHT AILERON INBOARD CABLE 2300003-272	MOS		TSN:0					SCRAP
27.740	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	2400	TSN:0 TSN:0			16-NOV-2001 9585.1 7825	11985.1	1020.1
271641	CABLE:RIGHT AILERON OUTBOARD CABLE 2300003-16	MOS		TSN:0					SCRAP
27.750	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	2400	TSN:0 TSN:0			16-NOV-2001 9585.1 7825	11985.1	1020.1
271920	CABLE:AILERON / RUDDER INTERCONNECT CABLE PN	MOS		TSN:0					
	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			23-OCT-1978 0 0		
272601	INDICATOR:AILERON TRIM POSITION INDICATOR PN	MOS		TSN:0					
27.430	SN-UNKNOWN REF: AMM 27-10-03	HRS/MSC AFL	O/C	TSN:0 TSN:0			23-OCT-1978 0 0		
273099	ELEVATOR:REPLACE LEFT ELEVATOR * LEFT INBOARD ELEVATOR HINGE BRACKET (IRN E2730020)	MOS							LIFE LIMIT
27.685	REF: GENERIC NO REF	HRS/MSC AFL	20000				23-OCT-1978 0 0	20000	9035

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
273100	ELEVATOR:REPLACE RIGHT ELEVATOR * RIGHT INBOARD ELEVATOR HINGE BRACKET (IRN E2730020)								LIFE LIMIT
27.685		MOS					23-OCT-1978		
		HRS/MSC	20000				0	20000	9035
	REF: GENERIC NO REF	AFL					0		
273101	RUDDER:RUDDER								LIFE LIMIT
27.170		MOS		TSN:0			23-OCT-1978		
		HRS/MSC	20000	TSN:0			0	20000	9035
	REF: AMM 27-20-01	AFL		TSN:0			0		
273106	RUDDER:REPLACE RUDDER * RUDDER HINGE ASSEMBLY, UPPER (2331030) (IRN E2720024)								LIFE LIMIT
27.190		MOS					23-OCT-1978		
		HRS/MSC	20000				0	20000	9035
	REF: GENERIC NO REF	AFL					0		
273111	RUDDER:REPLACE RUDDER * RUDDER HINGE ASSEMBLY, CENTER (2331031) (IRN E2720025)								LIFE LIMIT
27.190		MOS					23-OCT-1978		
		HRS/MSC	20000				0	20000	9035
	REF: GENERIC NO REF	AFL					0		
273112	RUDDER:REPLACE RUDDER * RUDDER HINGE BOLTS (NAS144A23 AND AN4H11A) (IRN E2720021)								LIFE LIMIT
27.170		MOS					23-OCT-1978		
		HRS/MSC	20000				0	20000	9035
	REF: GENERIC NO REF	AFL					0		
273113	RUDDER:REPLACE RUDDER * LOWER RUDDER BEARING BLOCK ASSEMBLY (2312040) (IRN E2720023)								LIFE LIMIT
27.170		MOS					23-OCT-1978		
		HRS/MSC	20000				0	20000	9035
	REF: GENERIC NO REF	AFL					0		
273116	SECTOR:RUDDER SERVO SECTOR								
27.640		MOS		TSN:0			23-OCT-1978		
		HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-20-02	AFL		TSN:0			0		
273601	TAB:RUDDER TRIM TAB								
27.180		MOS		TSN:0			23-OCT-1978		
		HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-20-03	AFL		TSN:0			0		
273606	ACTUATOR:RUDDER TRIM TAB ACTUATOR								
27.180		MOS		TSN:0			23-OCT-1978		
		HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-20-06	AFL		TSN:0			0		
273611	POTENTIOMETER:RUDDER TRIM POTENTIOMETER								
27.180		MOS		TSN:0			23-OCT-1978		
		HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-20-07	AFL		TSN:0			0		
273616	INDICATOR:RUDDER TRIM POSITION INDICATOR								
27.430		MOS		TSN:0			23-OCT-1978		
		HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-20-05	AFL		TSN:0			0		
274101	CABLE:LEFT RUDDER CABLE								SCRAP
27.760		MOS		TSN:0			16-NOV-2001		
		HRS/MSC	2400	TSN:0			9585.1	11985.1	12010.1
	REF: GENERIC NO REF	AFL		TSN:0			7825		1020.1 (+25)

?-Insufficient Information (EFF)-Effective C/W

+-Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
274106	CABLE:RIGHT RUDDER CABLE 2300003-243	MOS		TSN:0					SCRAP
27.760	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	2400 +25/-25	TSN:0 TSN:0			16-NOV-2001 9585.1 7825	11985.1 12010.1	1020.1 (+25)
274601	ELEVATOR:LEFT ELEVATOR PN	MOS		TSN:0					LIFE LIMIT
27.220	SN-UNKNOWN REF: AMM 27-30-03	HRS/MSC AFL	20000	TSN:0 TSN:0			23-OCT-1978 0 0	20000	9035
274606	ELEVATOR:RIGHT ELEVATOR PN	MOS		TSN:0					LIFE LIMIT
27.220	SN-UNKNOWN REF: AMM 27-30-03	HRS/MSC AFL	20000	TSN:0 TSN:0			23-OCT-1978 0 0	20000	9035
274613	BELLCRANK:LEFT ELEVATOR BELLCRANK PN	MOS		TSN:0					LIFE LIMIT
27.200	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	20000	TSN:0 TSN:0			23-OCT-1978 0 0	20000	9035
274614	BELLCRANK:RIGHT ELEVATOR BELLCRANK PN	MOS		TSN:0					LIFE LIMIT
27.200	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	20000	TSN:0 TSN:0			23-OCT-1978 0 0	20000	9035
274616	CABLE:LEFT ELEVATOR FORWARD CABLE 2300003-240	MOS		TSN:0					SCRAP
27.770	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	2400	TSN:0 TSN:0			16-NOV-2001 9585.1 7825	11985.1	1020.1
274619	ROD:ELEVATOR UPPER LEFT PUSH-PULL ROD PN	MOS		TSN:0					LIFE LIMIT
27.210	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	20000	TSN:0 TSN:0			23-OCT-1978 0 0	20000	9035
274620	ROD:ELEVATOR UPPER RIGHT PUSH-PULL ROD PN	MOS		TSN:0					LIFE LIMIT
27.210	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	20000	TSN:0 TSN:0			23-OCT-1978 0 0	20000	9035
274621	CABLE:LEFT ELEVATOR AFT CABLE 2300003-171	MOS		TSN:0					SCRAP
27.780	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	2400	TSN:0 TSN:0			16-NOV-2001 9585.1 7825	11985.1	1020.1
274631	REPLACE ELEVATOR DOWNSPRING ASSEMBLY ATTACH BUSHING MOS	HRS/MSC	O/C						
27.670	REF: GENERIC NO REF	AFL					22-DEC-2008 10763.7 9035		
274641	REPLACE ELEVATOR DOWNSPRING ASSEMBLY DRAWBOLT BUSHING MOS	HRS/MSC	O/C						
27.660	REF: GENERIC NO REF	AFL					22-DEC-2008 10763.7 9035		
274651	REPLACE ** ELEVATOR DOWNSPRING ASSEMBLY ATTACH BOLT (IRN R2730027) MOS	HRS/MSC	144 +14d/-14d						SCRAP
27.680	REF: GENERIC NO REF	AFL	6000 +25/-25				22-DEC-2008 10763.7 9035	31-DEC-2020 05-JAN-2021	3951 d (+5) 5800 (+25)

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

**Model :** LEARJET 35A  
**Owner :** J.E.P. DEVELOPEMENT CORP.  
**Operator :** NORTH DALLAS AVIATION INC.

**A/C Serial #:** 35A210 **A/C Reg. #:** N770JP

**Aircraft HRS:** 10965 **Landings:** 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
274661	CABLE:RIGHT ELEVATOR AFT CABLE								SCRAP
27.780	2300003-172 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	2400	TSN:0 TSN:0 TSN:0			16-NOV-2001 9585.1 7825	11985.1	1020.1
274662	CABLE:RIGHT ELEVATOR FORWARD CABLE								SCRAP
27.770	2300003-239 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	2400	TSN:0 TSN:0 TSN:0			16-NOV-2001 9585.1 7825	11985.1	1020.1
+ 275043	DETAILED VISUAL INSPECTION LEFT FLAP CAM FOLLOWER BEARING (IRN H2750044)								
27.265		MOS HRS/MSC AFL	1200				09-APR-2007 10494.2 8821	11694.2	729.2
REF: AMM 5-10-00									
+ 275044	DETAILED VISUAL INSPECTION RIGHT FLAP CAM FOLLOWER BEARING (IRN H2750044)								
27.265		MOS HRS/MSC AFL	1200				09-APR-2007 10494.2 8821	11694.2	729.2
REF: AMM 5-10-00									
+ 275045	DETAILED VISUAL INSPECTION LEFT WING FLAP TRACK SUPPORT FITTING (IRN H5750046)								
27.265		MOS HRS/MSC AFL	1200	+25/-25			09-APR-2007 10494.2 8821	11694.2	11719.2 729.2 (+25)
REF: AMM 5-10-00									
+ 275046	DETAILED VISUAL INSPECTION RIGHT WING FLAP TRACK SUPPORT FITTING (IRN H5750046)								
27.265		MOS HRS/MSC AFL	1200	+25/-25			09-APR-2007 10494.2 8821	11694.2	11719.2 729.2 (+25)
REF: AMM 5-10-00									
+ 275051	VISUAL INSPECTION LEFT SHEET METAL TRACK ATTACH FITTINGS (IRN H2750048)								
27.265		MOS HRS/MSC AFL	1200				09-APR-2007 10494.2 8821	11694.2	729.2
REF: AMM 5-10-00									
+ 275052	VISUAL INSPECTION RIGHT SHEET METAL TRACK ATTACH FITTINGS (IRN H2750048)								
27.265		MOS HRS/MSC AFL	1200				09-APR-2007 10494.2 8821	11694.2	729.2
REF: AMM 5-10-00									
275101	STABILIZER:HORIZONTAL STABILIZER								
27.250	PN SN-UNKNOWN REF: AMM 27-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
275106	STABILIZER:REPLACE HORIZONTAL STABILIZER * HORIZONTAL STABILIZER HINGE PIN (IRN E2740010)								LIFE LIMIT
27.250		MOS HRS/MSC AFL	20000				23-OCT-1978 0 0	20000	9035
REF: AMM 27-40-04									
275107	ELEVATOR:REPLACE LEFT ELEVATOR * OUTBOARD HINGE BRACKET (IRN E2730020)								LIFE LIMIT
27.150		MOS HRS/MSC AFL	20000				23-OCT-1978 0 0	20000	9035
REF: GENERIC NO REF									
275108	ELEVATOR:REPLACE LEFT ELEVATOR * CENTER HINGE BRACKET (IRN E2730020)								LIFE LIMIT
27.160		MOS HRS/MSC AFL	20000				23-OCT-1978 0 0	20000	9035
REF: GENERIC NO REF									

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
275109	ELEVATOR:REPLACE RIGHT ELEVATOR * OUTBOARD HINGE BRACKET (IRN E2730020)	MOS							LIFE LIMIT
27.150	REF: GENERIC NO REF	HRS/MSC AFL	20000				23-OCT-1978 0 0	20000	9035
275110	ELEVATOR:REPLACE RIGHT ELEVATOR * CENTER HINGE BRACKET (IRN E2730020)	MOS							LIFE LIMIT
27.160	REF: GENERIC NO REF	HRS/MSC AFL	20000				23-OCT-1978 0 0	20000	9035
275111	ACTUATOR:HORIZONTAL STABILIZER ACTUATOR 2332540-214	MOS		TSO:0					
27.030	374 REF: AMM 27-40-05	HRS/MSC AFL	O/C	TSO:0 TSO:0			03-APR-2009 10801.6 9072		
+ 275114	ACTUATOR:PERFORM HORIZONTAL STABILIZER ACTUATOR OVERHAUL (IRN Q2740021)	MOS							
27.030	REF: GENERIC CMM	HRS/MSC AFL	600	+25/-25			03-APR-2009 10801.6 9072	11401.6	11426.6 436.6 (+25)
275121	REPLACE * HORIZONTAL STABILIZER ACTUATOR UPPER ATTACH BOLT (IRN G2740011)	MOS	144	+14d/-14d					LIFE LIMIT
27.030	REF: GENERIC NO REF	HRS/MSC AFL	6000	+25/-25			10-MAY-2007 10494.7 8823	31-MAY-2019 14823	31-MAY-2019 14848 5588 (+25)
275126	REPLACE * HORIZONTAL STABILIZER ACTUATOR LOWER ATTACH BOLT (IRN G2740011)	MOS	144	+14d/-14d					LIFE LIMIT
27.030	REF: GENERIC NO REF	HRS/MSC AFL	6000	+25/-25			10-MAY-2007 10494.7 8823	31-MAY-2019 14823	31-MAY-2019 14848 5588 (+25)
275128	REPLACE LEFT ELEVATOR * HINGE BOLTS (IRN E2730024)	MOS							LIFE LIMIT
27.220	REF: GENERIC NO REF	HRS/MSC AFL	20000				23-OCT-1978 0 0	20000	9035
275129	REPLACE RIGHT ELEVATOR HINGE BOLTS (IRN E2730024)	MOS							LIFE LIMIT
27.220	REF: GENERIC NO REF	HRS/MSC AFL	20000				23-OCT-1978 0 0	20000	9035
275131	INDICATOR:HORIZONTAL STABILIZER POSITION INDICATOR 6608217-13	MOS		TSN:0					
27.380	535 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			31-AUG-2007 10509.9 8839		
275151	STABILIZER:VERTICAL STABILIZER PN	MOS		TSN:0					
27.400	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			23-OCT-1978 0 0		
275601	FLAP:LEFT FLAP PN	MOS		TSN:0					LIFE LIMIT
27.260	SN-UNKNOWN REF: AMM 27-50-01	HRS/MSC AFL	19300	TSN:0 TSN:0			23-OCT-1978 0 0	19300	8335
275606	ACTUATOR:LEFT FLAP ACTUATOR PN	MOS		TSN:0					
27.040	SN-UNKNOWN REF: AMM 27-50-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			23-OCT-1978 0 0		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
275636	TRACK:LEFT INBOARD FLAP TRACK								LIFE LIMIT
27.310	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0	20000	9035
275641	TRACK:LEFT OUTBOARD FLAP TRACK								LIFE LIMIT
27.320	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0	20000	9035
275646	TRACK:LEFT FLAP INBOARD NOSE ROLLER TRACK								LIFE LIMIT
27.330	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0	20000	9035
275651	TRACK:LEFT FLAP OUTBOARD NOSE ROLLER TRACK								LIFE LIMIT
27.340	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0	20000	9035
275661	FLAP:REPLACE LEFT FLAP ** NOSE ROLLER BUSHINGS (NAS76A4) (IRN E2750002)								SCRAP
27.360	MOS HRS/MSC REF: GENERIC NO REF	AFL	1200	+25/-25			10-JAN-2005 10438.3 8767	11638.3	11663.3 673.3 (+25)
275681	FLAP:REPLACE LEFT FLAP ** SECTOR MOUNTING BOLT WHICH SECURES FLAP SECTOR (IRN G2750034)								SCRAP
27.350	MOS HRS/MSC REF: GENERIC NO REF	AFL	144	+14d/-14d			23-SEP-2002 9789.9 8061	30-SEP-2014	07-OCT-2014 1667 d (+7) 4826 (+25)
275688	FLAP:REPLACE LEFT FLAP * INBOARD FLAP HINGE FITTING (ON FLAP 2625023) (IRN F2750017)								LIFE LIMIT
27.280	MOS HRS/MSC REF: GENERIC NO REF	AFL	20000				23-OCT-1978 0 0	20000	9035
275689	FLAP:REPLACE LEFT FLAP * OUTBOARD FLAP HINGE FITTING (ON FLAP 2625024) (IRN F2750019)								LIFE LIMIT
27.290	MOS HRS/MSC REF: GENERIC NO REF	AFL	20000				23-OCT-1978 0 0	20000	9035
276101	FLAP:RIGHT FLAP								LIFE LIMIT
27.260	PN-UNKNOWN SN-UNKNOWN REF: AMM 27-50-01	MOS HRS/MSC AFL	19300	TSR:0 TSN:5574.4 TSR:0			14-JUL-1992 5574.4 4547	19300	8335
276106	ACTUATOR:RIGHT FLAP ACTUATOR								LIFE LIMIT
27.040	PN SN-UNKNOWN REF: AMM 27-50-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
276136	TRACK:RIGHT INBOARD FLAP TRACK								LIFE LIMIT
27.310	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0	20000	9035
276141	TRACK:RIGHT OUTBOARD FLAP TRACK								LIFE LIMIT
27.320	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0	20000	9035

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
276146	TRACK:RIGHT FLAP INBOARD NOSE ROLLER TRACK								LIFE LIMIT
27.330	2322511-27 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			21-FEB-1996 6608.1 5446	26608.1	15643.1
276151	TRACK:RIGHT FLAP OUTBOARD NOSE ROLLER TRACK								LIFE LIMIT
27.340	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0	20000	9035
276161	FLAP:REPLACE RIGHT FLAP ** NOSE ROLLER BUSHINGS (NAS76A4) (IRN E2750002)								SCRAP
27.360	REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+25/-25			10-JAN-2005 10438.3 8767	11638.3	11663.3 673.3 (+25)
276181	FLAP:REPLACE RIGHT FLAP ** SECTOR MOUNTING BOLT WHICH SECURES FLAP SECTOR (IRN G2750034)								SCRAP
27.350	REF: GENERIC NO REF	MOS HRS/MSC AFL	144	+14d/-14d			23-SEP-2002 9789.9 8061	30-SEP-2014	07-OCT-2014 1667 d (+7) 4826 (+25)
276188	FLAP:REPLACE RIGHT FLAP * INBOARD FLAP HINGE FITTING (2625023) (IRN F2750017)								LIFE LIMIT
27.280	REF: GENERIC NO REF	MOS HRS/MSC AFL	20000				23-OCT-1978 0 0	20000	9035
276189	FLAP:REPLACE RIGHT FLAP * OUTBOARD FLAP HINGE FITTING (ON FLAP 2625024) (IRN F2750019)								LIFE LIMIT
27.290	REF: GENERIC NO REF	MOS HRS/MSC AFL	20000				23-OCT-1978 0 0	20000	9035
276601	VALVE:FLAP CONTROL VALVE								
27.460	PN SN-UNKNOWN REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
276606	RESTRICTOR:FLAP RESTRICTOR								
27.480	PN SN-UNKNOWN REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
276611	VALVE:FLAP LOAD LIMIT RELIEF VALVE								
27.420	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
276616	INDICATOR:FLAP POSIITON INDICATOR								
27.380	6608210-1 298 REF: AMM 27-50-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			10-JUN-1993 5859.8 4800		
276626	POTENTIOMETER:FLAP POSITION POTENTIOMETER								
27.460	PN SN-UNKNOWN REF: AMM 27-51-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
276666	SWITCH:FLAP AIRSPEED SWITCH								
27.620	PN-UNKNOWN 105 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				12-SEP-1994 6235.6 5126		



Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
276671	VALVE:FLAP BLOW-UP RELIEF VALVE								
27.420	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
276676	VALVE:FLAP LOAD LIMIT SOLENOID VALVE								
27.420	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
277101	SPOILER:LEFT SPOILER								LIFE LIMIT
27.370	2492001-1 SN-UNKNOWN REF: AMM 27-60-01	MOS HRS/MSC AFL	9000	TSN:0 TSN:0 TSN:0			02-JUN-1987 3600.1	12600.1	1635.1
277106	ACTUATOR:LEFT SPOILER ACTUATOR								LIFE LIMIT
27.050	PN SN-UNKNOWN REF: AMM 27-60-01	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0	20000	9035
277116	ARM:LEFT SPOILER ACTUATOR ARM								LIFE LIMIT
27.590	2422511-31 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	9000	TSN:0			20-APR-2000 8999 7352	17999	7034
277125	REPLACE LEFT SPOILER ACTUATOR ATTACH FITTING (IRN E2760076)								LIFE LIMIT
27.440	MOS HRS/MSC REF: GENERIC NO REF	MOS HRS/MSC AFL	20000				23-OCT-1978 0 0	20000	9035
277126	REPLACE LEFT SPOILER ACTUATOR FITTING BOLTS (IRN E2760076)								LIFE LIMIT
27.390	MOS HRS/MSC REF: GENERIC NO REF	MOS HRS/MSC AFL	20000				23-OCT-1978 0 0	20000	9035
277131	REPLACE LEFT SPOILER ATTACH BOLTS								LIFE LIMIT
27.590	MOS HRS/MSC REF: GENERIC NO REF	MOS HRS/MSC AFL	9000				20-APR-2000 8999 7352	17999	7034
277136	REPLACE LEFT ACTUATOR SPOILER PIVOT BOLT								LIFE LIMIT
27.590	MOS HRS/MSC REF: GENERIC NO REF	MOS HRS/MSC AFL	9000				20-APR-2000 8999 7352	17999	7034
277138	REPLACE LEFT ACTUATOR SPOILER BOLT								LIFE LIMIT
27.590	MOS HRS/MSC REF: GENERIC NO REF	MOS HRS/MSC AFL	9000				20-APR-2000 8999 7352	17999	7034
277601	SPOILER:RIGHT SPOILER								LIFE LIMIT
27.370	2422511-31 SN-UNKNOWN REF: AMM 27-60-01	MOS HRS/MSC AFL	9000	TSN:0			02-JUN-1987 3600.1	12600.1	1635.1
277606	ACTUATOR:RIGHT SPOILER ACTUATOR								LIFE LIMIT
27.050	PN SN-UNKNOWN REF: AMM 27-60-01	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0	20000	9035

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
277616	ARM:RIGHT SPOILER ACTUATOR ARM 2422511-31	MOS							LIFE LIMIT
27.595	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	9000	TSN:0			20-APR-2000 8999 7352	17999	7034
277625	REPLACE RIGHT SPOILER ACTUATOR ATTACH FITTING (IRN E2760076)	MOS							LIFE LIMIT
27.440	REF: GENERIC NO REF	HRS/MSC AFL	20000				23-OCT-1978 0 0	20000	9035
277626	REPLACE RIGHT SPOILER ACTUATOR FITTING BOLTS (IRN E2760076)	MOS							LIFE LIMIT
27.390	REF: GENERIC NO REF	HRS/MSC AFL	20000				23-OCT-1978 0 0	20000	9035
277631	REPLACE RIGHT SPOILER ATTACH BOLTS	MOS							LIFE LIMIT
27.595	REF: GENERIC NO REF	HRS/MSC AFL	9000				20-APR-2000 8999 7352	17999	7034
277636	REPLACE RIGHT ACTUATOR SPOILER PIVOT BOLT	MOS							LIFE LIMIT
27.595	REF: GENERIC NO REF	HRS/MSC AFL	9000				20-APR-2000 8999 7352	17999	7034
277638	REPLACE RIGHT ACTUATOR SPOILER BOLT	MOS							LIFE LIMIT
27.595	REF: GENERIC NO REF	HRS/MSC AFL	9000				20-APR-2000 8999 7352	17999	7034
278101	SWITCH:LEFT SPOILER DOWN/LOCK SWITCH PN	MOS		TSN:0					
27.490	SN-UNKNOWN REF: AMM 27-60-07	HRS/MSC AFL	O/C	TSN:0 TSN:0			23-OCT-1978 0 0		
278106	SWITCH:LEFT SPOILER UP LIMIT SWITCH 622EN513-6	MOS		TSN:0					
27.500	SN-UNKNOWN REF: AMM 27-60-06	HRS/MSC AFL	O/C	TSN:0 TSN:0			16-OCT-2002 9803.2 8073		
278111	FOLLOWUP:LEFT AILERON AUGMENTATION FOLLOWUP PN	MOS		TSN:0					
27.510	SN-UNKNOWN REF: AMM 27-60-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			23-OCT-1978 0 0		
278118	FOLLOWUP:LEFT SPOILER FOLLOWUP PN	MOS		TSN:0					
27.520	SN-UNKNOWN REF: AMM 27-60-05	HRS/MSC AFL	O/C	TSN:0 TSN:0			23-OCT-1978 0 0		
278121	VALVE:LEFT SPOILER SERVO VALVE PN	MOS		TSN:0					
27.530	SN-UNKNOWN REF: AMM 27-60-03	HRS/MSC AFL	O/C	TSN:0 TSN:0			23-OCT-1978 0 0		
278126	SWITCH:RIGHT SPOILER DOWN/LOCK SWITCH 622EN513-6	MOS		TSN:0					
27.490	SN-UNKNOWN REF: AMM 27-60-07	HRS/MSC AFL	O/C	TSN:0 TSN:0			10-SEP-1996 6971.6 5724		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
278131	SWITCH:RIGHT SPOILER UP LIMIT SWITCH								
27.500	PN SN-UNKNOWN REF: AMM 27-60-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
278136	FOLLOWUP:RIGHT AILERON AUGMENTATION FOLLOWUP								
27.510	PN SN-UNKNOWN REF: AMM 27-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
278143	FOLLOWUP:RIGHT SPOILER FOLLOWUP								
27.520	PN SN-UNKNOWN REF: AMM 27-60-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
278146	VALVE:RIGHT SPOILER SERVO VALVE								
27.530	PN SN-UNKNOWN REF: AMM 27-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
278601	VALVE:SPOILER CONTROL VALVE								
27.610	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
278606	VALVE:SPOILER SOLENOID RESTRICTOR VALVE								
27.610	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
278611	COMPUTER:SPOILER COMPUTER								
27.610	501-1133-03 1388 REF: AMM 27-60-08	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			13-AUG-2001 9511.4 7763		
278616	MANIFOLD:SPOILER SERVO VALVE MANIFOLD								
27.470	2627023-1 118 REF: AMM 27-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-FEB-1979 59.4		
279101	COMPUTER:STALL WARNING COMPUTER								
27.570	6608263-9 027-71 REF: AMM 27-31-04	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			26-APR-1995 6295.5 5174		
279107	BOARD:STALL WARNING PC BOARD								
27.270	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
279111	TRANSDUCER:LEFT ANGLE-OF-ATTACK TRANSDUCER								
27.540	6608263 104-051 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C				25-FEB-1984 2441.6		
279117	SWITCH:LEFT ALTITUDE PRESSURE SWITCH								
27.600	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
279121	TRANSDUCER:RIGHT ANGLE-OF-ATTACK TRANSDUCER									
27.540	6608263-6 104-129 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			08-OCT-1985 2841.9			
279127	SWITCH:RIGHT ALTITUDE PRESSURE SWITCH									
27.600	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
279131	BIAS BOX:STALL WARNING BIAS BOX									
27.570	PN SN-UNKNOWN REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
279141	SHAKER:PILOT STICK SHAKER									
27.550	6608289-2 442 REF: AMM 27-31-02	MOS HRS/MSC AFL	O/C				11-MAY-1979 264.8 187			
279151	SHAKER:COPILOT STICK SHAKER									
27.550	PN SN-UNKNOWN REF: AMM 27-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
279161	ACCELEROMETER:STALL WARNING ACCELEROMETER									
27.580	PN SN-UNKNOWN REF: AMM 27-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
+ 279163	OPERATIONAL CHECK STALL WARNING ACCELEROMETER (IRN N2731062)									
27.580		MOS HRS/MSC AFL	300	+25			07-DEC-2009 10928.4 9202	11228.4	11253.4	263.4 (+25)
279171	INDICATOR:LEFT ANGLE-OF-ATTACK INDICATOR									
27.560	6608208-5 257 REF: AMM 27-31-11	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			26-APR-1995 6295.5 5174			
279181	CUTOUT:STALL WARNING ACCELEROMETER CUTOUT									
27.580	PN SN-UNKNOWN REF: AMM 27-31-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
279197	INDICATOR:RIGHT ANGLE-OF-ATTACK INDICATOR									
27.560	6608208-5 126 REF: AMM 27-31-11	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			26-APR-1995 6295.5 5174			
279204	MONITOR:1/2 G ACCELEROMETER MONITOR									
27.300	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
279206	CONTROLLER:PITCH TRIM SPEED CONTROLLER									
27.630	PN SN-UNKNOWN REF: AMM 27-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
279208	SENSOR:HORIZONTAL STABILIZER ACTUATOR OVERLOAD SENSOR								
27.230	PN SN-UNKNOWN REF: AMM 27-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
279210	DETECTOR:TRIM-IN-MOTION DETECTOR								
27.240	PN SN-UNKNOWN REF: AMM 27-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
5-11-00-F2710009	REPLACE PRIMARY AILERON CONTROL SYSTEM CABLES								LIFE LIMIT
		MOS HRS/MSC AFL	2400				16-NOV-2001 9585.1 7825	11985.1	1020.1
5-11-00-F2720012	REPLACE PRIMARY RUDDER CONTROL SYSTEM CABLES								LIFE LIMIT
		MOS HRS/MSC AFL	2400	+25/-25			16-NOV-2001 9585.1 7825	11985.1	12010.1
5-11-00-F2730015	REPLACE PRIMARY ELEVATOR CONTROL SYSTEM CABLES								LIFE LIMIT
		MOS HRS/MSC AFL	2400				16-NOV-2001 9585.1 7825	11985.1	1020.1
<b>CHAPTER 28 FUEL</b>									
280001	CALIBRATION CHECK FUEL QUANTITY SYSTEM								
		MOS HRS/MSC AFL	24				14-NOV-2008 10763.4 9034	30-NOV-2010	267 d
280101	PUMP:LEFT TIP TANK JET PUMP								
28.190	PN SN-UNKNOWN REF: AMM 28-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
280106	CAP:LEFT FILLER TIP TANK CAP								
28.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
280111	VALVE:LEFT TIP TANK FORWARD FLOAT VALVE								
28.060	62-401 3091898 REF: AMM 28-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-APR-1979 196		
280116	VALVE:LEFT TIP TANK AFT FLOAT VALVE								
28.070	P62-401 8013150 REF: AMM 28-14-01	MOS HRS/MSC AFL	O/C				23-DEC-1981 1602		
280121	VALVE:LEFT TIP TANK PRIMARY PRESSURE RELIEF VALVE								
28.080	PN SN-UNKNOWN REF: AMM 28-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
280126	VALVE:LEFT TIP TANK SECONDARY PRESSURE RELIEF VALVE									
	PN	MOS		TSN:0			23-OCT-1978			
28.090	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 28-11-03	AFL		TSN:0			0			
280131	VALVE:LEFT TIP TANK VENT CHECK VALVE									
	P62-401	MOS		TSN:0			23-DEC-1981			
28.020	9040423	HRS/MSC	O/C	TSN:0			1602			
	REF: GENERIC NO REF	AFL		TSN:0						
280141	VALVE:LEFT TIP TANK MANUAL DRAIN VALVE									
	750C-9	MOS		TSN:0			11-FEB-1986			
28.100	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			2910.7			
	REF: GENERIC NO REF	AFL		TSN:0						
280146	VALVE:LEFT TIP TANK JETTISON VALVE									
	6600357-1	MOS		TSO:0			21-FEB-1996			
28.110	40920107	HRS/MSC	O/C	TSO:0			6608.1			
	REF: AMM 28-30-01	AFL		TSO:0			5446			
280151	TANK:LEFT TIP TANK									
	PN	MOS		TSN:0			23-OCT-1978			
28.040	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 28-11-00	AFL		TSN:0			0			
280153	MOUNT ASSEMBLY:LEFT TIP TANK MOUNT ASSEMBLY									
	PN	MOS		TSN:0			23-OCT-1978			
28.400	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: GENERIC NO REF	AFL		TSN:0			0			
280560	REPLACE ** TIP TANK FLAPPER VALVES (2323006-5) (IRN K2812001)								NOT INSTALLED	
		MOS					18-DEC-1995			
28.460		HRS/MSC	N/A				6531.2			
	REF: GENERIC NO REF	AFL					5390			
280570	INSPECT LEFT WING TIP TANK FLAPPER VALVES (IRN M2812003)									
		MOS	24	+14d/-14d			29-APR-2009	30-APR-2011	13-MAY-2011	418 d (+13)
28.480		HRS/MSC					10810			
	REF: AMM 28-11-06	AFL					9080			
280575	INSPECT RIGHT WING TIP TANK FLAPPER VALVES (IRN M2812003)									
		MOS	24	+14d/-14d			29-APR-2009	30-APR-2011	13-MAY-2011	418 d (+13)
28.480		HRS/MSC					10810			
	REF: AMM 28-11-06	AFL					9080			
+ 280580	INSPECT LEFT WING TIP TANK (IRN R2812011)									
		MOS	24	+14d/-14d			29-APR-2009	30-APR-2011	13-MAY-2011	418 d (+13)
28.470		HRS/MSC					10810			
	REF:	AFL					9080			
280585	INSPECT RIGHT WING TIP TANK (IRN R2812011)									
		MOS	24	+14d/-14d			29-APR-2009	30-APR-2011	13-MAY-2011	418 d (+13)
28.470		HRS/MSC					10810			
	REF:	AFL					9080			
280601	PUMP:RIGHT TIP TANK JET PUMP									
	PN	MOS		TSN:0			23-OCT-1978			
28.190	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 28-11-01	AFL		TSN:0			0			

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
280606	CAP:RIGHT FILLER TIP TANK CAP								
	PN	MOS		TSN:0				23-OCT-1978	
28.050	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
280611	VALVE:RIGHT TIP TANK FORWARD FLOAT VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.060	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-14-01	AFL		TSN:0			0		
280616	VALVE:RIGHT TIP TANK AFT FLOAT VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.070	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-14-01	AFL		TSN:0			0		
280621	VALVE:RIGHT TIP TANK PRIMARY PRESSURE RELIEF VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.080	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-11-03	AFL		TSN:0			0		
280626	VALVE:RIGHT TIP TANK SECONDARY PRESSURE RELIEF VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.090	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-11-03	AFL		TSN:0			0		
280631	VALVE:RIGHT TIP TANK VENT CHECK VALVE								
	P62-401	MOS		TSN:0				23-DEC-1981	
28.020	80329127	HRS/MSC	O/C	TSN:0			1602		
	REF: GENERIC NO REF	AFL		TSN:0					
280641	VALVE:RIGHT TIP TANK MANUAL DRAIN VALVE								
	750C-9	MOS		TSN:0				11-FEB-1986	
28.100	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			2910.7		
	REF: GENERIC NO REF	AFL		TSN:0					
280646	VALVE:RIGHT TIP TANK JETTISON VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.110	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-30-01	AFL		TSN:0			0		
280651	TANK:RIGHT TIP TANK								
	PN	MOS		TSN:0				23-OCT-1978	
28.040	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-11-00	AFL		TSN:0			0		
280653	MOUNT ASSEMBLY:RIGHT TIP TANK MOUNT ASSEMBLY								
	PN	MOS		TSN:0				23-OCT-1978	
28.400	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281101	PUMP:LEFT WING (STAND-BY) BOOST PUMP								
	PN-UNKNOWN	MOS		TSN:0				26-JUN-1981	
28.200	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			1372.2		
	REF: AMM 28-20-02	AFL		TSN:0					
281102	VALVE:LEFT BOOST PUMP CHECK VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.430	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
281106	PUMP:LEFT JET PUMP								
	PN	MOS		TSN:0				23-OCT-1978	
28.230	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-20-01	AFL		TSN:0			0		
281108	VALVE:LEFT JET PUMP CHECK VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.440	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281111	SWITCH:LEFT WING FLOAT SWITCH								
	PN	MOS		TSN:0				23-OCT-1978	
28.120	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-12-03	AFL		TSN:0			0		
281116	VALVE:LEFT WING DRAIN SUMP VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.130	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281131	VALVE:CROSSFLOW SHUTOFF VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.340	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-12-05	AFL		TSN:0			0		
281141	VALVE:LEFT FUSELAGE TRANSFER SHUTOFF VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.160	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-13-02	AFL		TSN:0			0		
281146	VALVE:LEFT WING DEFUELING VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.140	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281151	VALVE:LEFT WING PRESSURE RELIEF VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.150	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281156	SCOOP:LEFT WING RAM AIR SCOOP								
	PN	MOS		TSN:0				23-OCT-1978	
28.180	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-14-04	AFL		TSN:0			0		
281601	PUMP:RIGHT WING (STAND-BY) BOOST PUMP								
	PN-UNKNOWN	MOS		TSO:0				14-JUL-1992	
28.200	B2800	HRS/MSC	O/C	TSO:0			5574.4		
	REF: AMM 28-20-02	AFL		TSO:0			4547		
281602	VALVE:RIGHT BOOST PUMP CHECK VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.430	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281606	PUMP:RIGHT JET PUMP								
	PN	MOS		TSN:0				23-OCT-1978	
28.230	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-20-01	AFL		TSN:0			0		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)



Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING		
							COMPLIANCE (ENH)	NEXT DUE			
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT			
281608	VALVE:RIGHT JET PUMP CHECK VALVE PN	MOS		TSN:0				23-OCT-1978			
28.440	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0				
281611	SWITCH:RIGHT WING FLOAT SWITCH L15H-8	MOS		TSN:0				13-AUG-1990			
28.120	SN-UNKNOWN REF: AMM 28-12-03	HRS/MSC AFL	O/C	TSN:0 TSN:0			5361.1 4362				
281616	VALVE:RIGHT WING DRAIN SUMP VALVE PN	MOS		TSN:0				23-OCT-1978			
28.130	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0				
281621	SWITCH:WING FUEL PRESSURE SWITCH 1G134-4	MOS		TSN:0				19-FEB-1997			
28.010	1777 REF: AMM 28-12-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			7228.7 5945				
281641	VALVE:RIGHT FUSELAGE TRANSFER SHUTOFF VALVE PN	MOS		TSN:0				23-OCT-1978			
28.160	SN-UNKNOWN REF: AMM 28-13-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0				
281646	VALVE:RIGHT WING DEFUELING VALVE PN	MOS		TSN:0				23-OCT-1978			
28.140	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0				
281651	VALVE:RIGHT WING PRESSURE RELIEF VALVE PN	MOS		TSN:0				23-OCT-1978			
28.150	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0				
281656	SCOOP:RIGHT WING RAM AIR SCOOP PN	MOS		TSN:0				23-OCT-1978			
28.180	SN-UNKNOWN REF: AMM 28-14-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0				
282089	REPLACE NO. 1 ENGINE **FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (IRN G7110021)	MOS	60	+14d/-14d		-38		17-FEB-2010	<b>31-JAN-2015</b>	31-JAN-2015	1790 d
28.360	REF: GENERIC NO REF	HRS/MSC AFL	2400	+25/-25			10956.5 9224		<b>13356.5</b>	13381.5	2391.5 (+25)
282090	REPLACE NO. 2 ENGINE ** FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (IRN G7110021)	MOS	60	+14d/-14d		-38		17-FEB-2010	<b>31-JAN-2015</b>	31-JAN-2015	1790 d
28.360	REF: GENERIC NO REF	HRS/MSC AFL	2400	+25/-25			10956.5 9224		<b>13356.5</b>	13381.5	2391.5 (+25)
282091	REPLACE ** ALL FUEL HOSE ASSEMBLIES (EXCLUDING ALL HOSES IN ENGINE NACELLE AREA) IN AIRCRAFT (PRESSURE) (IRN G2820002)	MOS	144	+14d/-14d				11-JUN-2007	<b>30-JUN-2019</b>	30-JUN-2019	3401 d
28.370	REF: GENERIC NO REF	HRS/MSC AFL	6000	+25/-25			10494.7 8823		<b>14823</b>	14848	5588 (+25)
282101	CELL:LEFT FUSELAGE FUEL CELL PN	MOS		TSN:0				23-OCT-1978			
28.260	SN-UNKNOWN REF: AMM 28-13-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0				

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
282106	CELL:RIGHT FUSELAGE FUEL CELL								
	PN	MOS		TSN:0				23-OCT-1978	
28.260	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-13-01	AFL		TSN:0			0		
283106	SWITCH:FUSELAGE TANK LOW PRESSURE SWITCH								
	PN	MOS		TSN:0				23-OCT-1978	
28.240	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-13-03	AFL		TSN:0			0		
283111	SWITCH:FUSELAGE TANK FLOAT SWITCH								
	PN	MOS		TSN:0				23-OCT-1978	
28.240	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-13-04	AFL		TSN:0			0		
283116	PUMP:FUSELAGE TANK BOOST PUMP								
	2380060-30	MOS						22-MAR-1996	
28.200	B-4991	HRS/MSC	O/C				6682.1		
	REF: AMM 28-13-05	AFL					5497		
283121	VALVE:FUSELAGE TANK VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.420	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
283601	VALVE:FUSELAGE TANK VENT FLOAT VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.250	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-14-01	AFL		TSN:0			0		
283606	VALVE:FUSELAGE TANK VENT CHECK VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.100	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
284116	VALVE:LEFT FUEL SHUTOFF VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.340	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-20-04	AFL		TSN:0			0		
284126	VALVE:LEFT HIGH PRESSURE RELIEF VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.170	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-20-06	AFL		TSN:0			0		
284131	VALVE:LEFT MOTIVE FLOW VALVE								
	PN-UNKNOWN	MOS		TSO:0				09-SEP-1992	
28.210	J75119	HRS/MSC	O/C	TSO:0			5630.4		
	REF: AMM 28-20-05	AFL		TSO:0			4595		
284136	SWITCH:NO. 1 ENGINE FUEL PRESSURE SWITCH								
	PN	MOS		TSN:0				23-OCT-1978	
28.220	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-41-00	AFL		TSN:0			0		
284156	VALVE:RIGHT FUEL SHUTOFF VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
28.340	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-20-04	AFL		TSN:0			0		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
284166	VALVE:RIGHT HIGH PRESSURE RELIEF VALVE								
	PN	MOS		TSN:0			23-OCT-1978		
28.170	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-20-06	AFL		TSN:0			0		
284171	VALVE:RIGHT MOTIVE FLOW VALVE								
	PN	MOS		TSN:0			23-OCT-1978		
28.210	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-20-05	AFL		TSN:0			0		
284176	SWITCH:NO. 2 ENGINE FUEL PRESSURE SWITCH								
	PN	MOS		TSN:0			23-OCT-1978		
28.220	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-41-00	AFL		TSN:0			0		
284606	BOARD:FUEL PRINTED CIRCUIT BOARD								
	542-1158-01	MOS		TSN:0			03-JUN-1997		
28.350	3336	HRS/MSC	O/C	TSN:0			7300.1		
	REF: GENERIC NO REF	AFL		TSN:0			6009		
284611	COUNTER:FUEL (24 VOLT DC) COUNTER								
	BD177004-146	MOS		TSN:0			08-AUG-1997		
28.410	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			7348.6		
	REF: GENERIC NO REF	AFL		TSN:0			6069		
284616	ASSEMBLY:COMPUTER AMP CHASSIS ASSEMBLY								
	PN	MOS		TSN:0			23-OCT-1978		
28.410	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
285101	PROBE:FUSELAGE (MT62 OR MT69) PROBE								
	PN	MOS		TSN:0			23-OCT-1978		
28.330	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-40-02	AFL		TSN:0			0		
285106	PROBE:LEFT WING STATION 193 (MT71) PROBE								
	PN	MOS		TSN:0			23-OCT-1978		
28.290	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-40-02	AFL		TSN:0			0		
285111	PROBE:LEFT WING STATION 108 (MT63) PROBE								
	PN	MOS		TSN:0			23-OCT-1978		
28.300	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-40-02	AFL		TSN:0			0		
285116	PROBE:LEFT WING CENTERLINE (MT65) PROBE								
	PN	MOS		TSN:0			23-OCT-1978		
28.310	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-40-02	AFL		TSN:0			0		
285121	PROBE:RIGHT WING STATION 193 (MT72) PROBE								
	PN	MOS		TSN:0			23-OCT-1978		
28.290	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-40-02	AFL		TSN:0			0		
285126	PROBE:RIGHT WING STATION 108 (MT64) PROBE								
	PN	MOS		TSN:0			23-OCT-1978		
28.300	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-40-02	AFL		TSN:0			0		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
285131	PROBE:RIGHT WING CENTERLINE (MT66) PROBE								
	PN	MOS		TSN:0			23-OCT-1978		
28.310	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-40-02	AFL		TSN:0			0		
285136	PROBE:LEFT WING TIP TANK (MT67) PROBE								
	PN	MOS		TSN:0			23-OCT-1978		
28.320	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-40-02	AFL		TSN:0			0		
285141	PROBE:RIGHT WING TIP TANK (MT68) PROBE								
	PN	MOS		TSN:0			23-OCT-1978		
28.320	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-40-02	AFL		TSN:0			0		
285601	INDICATOR:FUEL QUANTITY INDICATOR								
	JG911A7	MOS		TSN:0			18-APR-1997		
28.450	R-34	HRS/MSC	O/C	TSN:0			7283.8		
	REF: AMM 28-40-01	AFL		TSN:0			5992		
285611	SWITCH:FUEL QUANTITY SELECTOR SWITCH								
	PN	MOS		TSN:0			23-OCT-1978		
28.420	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-40-01	AFL		TSN:0			0		
286281	HOSE:LEFT FORWARD /AFT OUTBOARD CONNECTOR HOSE								
	PN	MOS		TSN:0			23-OCT-1978		
28.380	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
286286	HOSE:LEFT FORWARD /AFT INBOARD CONNECTOR HOSE								
	PN	MOS		TSN:0			23-OCT-1978		
28.390	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
286291	HOSE:RIGHT FORWARD /AFT INBOARD CONNECTOR HOSE								
	PN	MOS		TSN:0			23-OCT-1978		
28.390	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
286296	HOSE:RIGHT FORWARD /AFT OUTBOARD CONNECTOR HOSE								
	PN	MOS		TSN:0			23-OCT-1978		
28.380	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
<b>CHAPTER 29</b>	<b>HYDRAULIC POWER</b>								
290101	RESERVOIR:HYDRAULIC RESERVOIR								
	PN	MOS		TSN:0			23-OCT-1978		
29.020	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-10-01	AFL		TSN:0			0		
290111	SHUTOFF VALVE:NO. 1 HYDRAULIC SHUTOFF VALVE								
	PN	MOS		TSN:0			23-OCT-1978		
29.030	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-10-02	AFL		TSN:0			0		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
290121	SHUTOFF VALVE:NO. 2 HYDRAULIC SHUTOFF VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
29.030	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-10-02	AFL		TSN:0			0		
290131	PUMP:NO. 1 ENGINE HYDRAULIC PUMP								
	6600301-3	MOS		TSO:0				21-MAY-1996	
29.080	178243B	HRS/MSC	O/C	TSO:0			6771.9		
	REF: AMM 29-10-03	AFL		TSO:0					
290136	PUMP:NO. 2 ENGINE HYDRAULIC PUMP								
	6600301-3	MOS		TSO:0				28-DEC-1989	
29.080	153979A	HRS/MSC	O/C	TSO:0			4979.5		
	REF: AMM 29-10-03	AFL		TSO:0			4043		
290151	ACCUMULATOR:HYDRAULIC ACCUMULATOR								
	PN	MOS		TSN:0				23-OCT-1978	
29.020	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-10-05	AFL		TSN:0			0		
290601	CHECK VALVE:NO. 1 ENGINE HYDRAULIC PRESSURE CHECK VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
29.040	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
290606	CHECK VALVE:NO. 2 ENGINE HYDRAULIC PRESSURE CHECK VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
29.040	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
290611	VALVE:HYDRAULIC CASE DRAIN VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
29.050	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
290616	VALVE:HYDRAULIC RESERVOIR PRESSURE VALVE								
	2702-13	MOS		TSN:0				10-JAN-2005	
29.050	0729	HRS/MSC	O/C	TSN:0			10438.3		
	REF: GENERIC NO REF	AFL		TSN:0			8767		
290621	VALVE:AUXILIARY PUMP CHECK VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
29.050	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
290626	RELIEF VALVE:HYDRAULIC RESERVOIR PRESSURE RELIEF VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
29.060	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
290631	RELIEF VALVE:HYDRAULIC SYSTEM RELIEF VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
29.060	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
290636	RELIEF VALVE:HYDRAULIC RESERVOIR VACUUM RELIEF VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
29.070	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
290641	RELIEF VALVE:EMERGENCY AIR PRESSURE RELIEF VALVE									
	PN	MOS		TSN:0			23-OCT-1978			
29.070	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: GENERIC NO REF	AFL		TSN:0			0			
291081	REPLACE NO. 1 ENGINE ** HYDRAULIC HOSE ASSEMBLIES IN THE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIREWALL) (IRN G7110022)								<b>SCRAP</b>	
		MOS	60	+14d/-14d	-38		17-FEB-2010	<b>31-JAN-2015</b>	31-JAN-2015	1790 d
29.120		HRS/MSC	2400	+25/-25			10956.5	<b>13356.5</b>	13381.5	2391.5 (+25)
	REF: GENERIC NO REF	AFL					9224			
291082	REPLACE NO. 2 ENGINE ** HYDRAULIC HOSE ASSEMBLIES IN THE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIREWALL) (IRN G7110022)								<b>SCRAP</b>	
		MOS	60	+14d/-14d	-38		17-FEB-2010	<b>31-JAN-2015</b>	31-JAN-2015	1790 d
29.120		HRS/MSC	2400	+25/-25			10956.5	<b>13356.5</b>	13381.5	2391.5 (+25)
	REF: GENERIC NO REF	AFL					9224			
291083	REPLACE ** HYDRAULIC HOSES ASSEMBLIES (EXCLUDING LANDING GEAR AND NACELLE) (IRN G2900001)								<b>SCRAP</b>	
		MOS	144	+14d/-14d			11-JUN-2007	<b>30-JUN-2019</b>	30-JUN-2019	3401 d
29.010		HRS/MSC					10494.7			
	REF: GENERIC NO REF	AFL	6000	+25/-25			8823	<b>14823</b>	14848	5588 (+25)
291101	GAUGE:COCKPIT HYDRAULIC PRESSURE GAUGE									
	PN	MOS		TSN:0			23-OCT-1978			
29.110	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: GENERIC NO REF	AFL		TSN:0			0			
291106	GAUGE:TAILCONE HYDRAULIC PRESSURE GAUGE									
	S218-1	MOS		TSO:0			15-APR-1990			
29.100	2225	HRS/MSC	O/C	TSO:0			5178.1			
	REF: GENERIC NO REF	AFL		TSO:0			4219			
291111	PUMP:AUXILIARY ELECTRIC PUMP									
	PN	MOS		TSN:0			23-OCT-1978			
29.090	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 29-20-01	AFL		TSN:0			0			
291116	SWITCH:HYDRAULIC PUMP AUXILIARY SWITCH									
	PN	MOS		TSN:0			23-OCT-1978			
29.090	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 29-20-02	AFL		TSN:0			0			
291121	SWITCH:HYDRAULIC PRESSURE SWITCH									
	PN	MOS		TSN:0			23-OCT-1978			
29.110	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: GENERIC NO REF	AFL		TSN:0			0			
291126	VALVE:ACCUMULATOR AIR FILLER VALVE									
	MS28889-2	MOS		TSN:0			06-FEB-1998			
29.110	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			7715.4			
	REF: GENERIC NO REF	AFL		TSN:0			6298			
291131	REGULATOR:RESERVOIR PRESSURE REGULATOR									
	PN	MOS		TSN:0			23-OCT-1978			
29.100	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: GENERIC NO REF	AFL		TSN:0			0			

**CHAPTER 30 ICE AND RAIN PROTECTION**

?-Insufficient Information    +-Task exists in Inspection Manual    (s)-Suppressed Requirement    (EBT)-Estimated Base Time    \*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
300101	REGULATOR:ANTI-ICE PRESSURE REGULATOR								
30.010	PN SN-UNKNOWN REF: AMM 30-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
300106	SENSOR:WING ANTI-ICE TEMPERATURE SENSOR								
30.020	PN SN-UNKNOWN REF: AMM 30-11-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
300111	THERMOSTAT:WING ANTI-ICE THERMOSTAT								
30.040	PN SN-UNKNOWN REF: AMM 30-11-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
300116	INDICATOR:WING ANTI-ICE TEMPERATURE INDICATOR								
30.030	PN SN-UNKNOWN REF: AMM 30-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
300121	INDICATOR:STABILIZER ANTI-ICE TEMPERATURE INDICATOR								
30.030	66008210-23 459 REF: AMM 30-12-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-JAN-2005 10438.3 8767		
300601	THERMOSTAT:HORIZONTAL STABILIZER ANTI-ICE THERMOSTAT								
30.040	PN SN-UNKNOWN REF: AMM 30-12-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
301101	SWITCH:LEFT NACELLE PRESSURE SWITCH								
30.050	PN SN-UNKNOWN REF: AMM 30-21-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
301106	SWITCH:RIGHT NACELLE PRESSURE SWITCH								
30.050	PN SN-UNKNOWN REF: AMM 30-21-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
301111	VALVE:LEFT NACELLE ANTI-ICE SHUTOFF VALVE								
30.060	PN SN-UNKNOWN REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
301116	VALVE:RIGHT NACELLE ANTI-ICE SHUTOFF VALVE								
30.060	27241302-01 SN-UNKNOWN REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			09-SEP-1992 5630.4 4595		
301131	SWITCH:NO. 1 ENGINE ANTI-ICE PRESSURE SWITCH								
30.090	P22B-11 3155 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-1988 4205.5 3398		
301136	SWITCH:NO. 2 ENGINE ANTI-ICE PRESSURE SWITCH								
30.090	P20M-30 2818 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-OCT-2007 10546.7 8865		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
301601	VALVE:DEFOG PRESSURE REGULATOR VALVE								
30.100	55510 164 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				02-AUG-1985 2794.3		
301606	VALVE:DEFOG SHUTOFF VALVE								
30.100	32-2867-003 5800415 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			24-SEP-1982 1950		
301611	THERMOSTAT:LEFT WINDSHIELD DEFOG LOW LIMIT THERMOSTAT								
30.110	PN SN-UNKNOWN REF: AMM 30-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
301616	THERMOSTAT:RIGHT WINDSHIELD DEFOG LOW LIMIT THERMOSTAT								
30.110	PN SN-UNKNOWN REF: AMM 30-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
301621	THERMOSTAT:LEFT WINDSHIELD DEFOG HIGH LIMIT THERMOSTAT								
30.120	PN SN-UNKNOWN REF: AMM 30-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
301626	THERMOSTAT:RIGHT WINDSHIELD DEFOG HIGH LIMIT THERMOSTAT								
30.120	PN SN-UNKNOWN REF: AMM 30-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
301631	VALVE:MANUAL DEFOG CONTROL VALVE								
30.100	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
302101	TANK:ALCOHOL ANTI-ICE TANK								
30.140	PN SN-UNKNOWN REF: AMM 30-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
302111	PUMP:ALCOHOL ANTI-ICE PUMP								
30.140	PN SN-UNKNOWN REF: AMM 30-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
302121	VALVE:ALCOHOL ANTI-ICE SHUTOFF VALVE								
30.080	PN SN-UNKNOWN REF: AMM 30-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
302136	SWITCH:LOW PRESSURE ALCOHOL ANTI-ICE SWITCH								
30.130	PN SN-UNKNOWN REF: AMM 30-50-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
302141	VALVE:ALCOHOL PRESSURE RELIEF VALVE								
30.150	PN SN-UNKNOWN REF: AMM 30-50-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		



Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
302146	VALVE:ALCOHOL ANTI-SYPHON VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
30.070	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
302151	VALVE:ALCOHOL 3-WAY SHUTOFF VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
30.150	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 30-50-08	AFL		TSN:0			0		
302156	SWITCH:ALCOHOL ANTI-ICE FLOAT SWITCH								
	6608259-4	MOS		TSN:0				07-MAR-1983	
30.130	SN-UNKNOWN	HRS/MSC	O/C	TSN:0					
	REF: AMM 30-50-09	AFL		TSN:0					
303043	SENSOR:LEFT & RIGHT PITOT CURRENT SENSOR								
	PN	MOS		TSN:0				23-OCT-1978	
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
303101	VALVE:WINDSHIELD ANTI-ICE SHUTOFF VALVE								
	PN	MOS		TSN:0				23-OCT-1978	
30.080	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 30-40-01	AFL		TSN:0			0		
303106	EXCHANGER:WINDSHIELD ANTI-ICE HEAT EXCHANGER								
	PN	MOS		TSN:0				23-OCT-1978	
30.010	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 30-40-05	AFL		TSN:0			0		
303121	SENSOR:WINDSHIELD ANTI-ICE SENSOR								
	PN	MOS		TSN:0				23-OCT-1978	
30.020	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 30-40-06	AFL		TSN:0			0		
5-10-29-E3020001-L	INSPECT NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION.								
		MOS						17-FEB-2010	
		HRS/MSC	MPI				10956.5		
	REF:	AFL					9224		
5-10-29-E3020001-R	INSPECT NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION.								
		MOS						17-FEB-2010	
		HRS/MSC	MPI				10956.5		
	REF:	AFL					9224		
<b>CHAPTER 31</b>	<b>INDICATING/RECORDING SYSTEMS</b>								
310106	CLOCK:COCKPIT CLOCK								
	811-BATT-1	MOS		TSO:0				03-MAY-1995	
31.010	11012007	HRS/MSC	O/C	TSO:0			6297.9		
	REF: AMM 31-22-00	AFL		TSO:0					
310106A	CLOCK:COCKPIT CLOCK BATTERY REPLACEMENT								
		MOS	24					29-JUL-2009	31-JUL-2011
		HRS/MSC						10867.8	510 d
	REF:	AFL					9134		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
310116	SPEAKER:AURAL WARNING SPEAKER								
31.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
310121	UNIT:AURAL WARNING CONTROL UNIT								
31.030	PN SN-UNKNOWN REF: AMM 31-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
310131	ENCODER:TRIP AND DATE ENCODER								
31.020	PN SN-UNKNOWN REF: AMM 31-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
310136	CLUSTER:ENGINE INSTRUMENT CLUSTER								
31.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
310606	ACCELEROMETER:FLIGHT RECORDER ACCELEROMETER								
31.060	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
311611	BULB:RAM AIR TEMPERATURE BULB								
34.190	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
<b>CHAPTER 32 LANDING GEAR</b>									
320101	STRUT:LEFT MAIN GEAR SHOCK STRUT								LIFE LIMIT
32.010	2341100-5 2274 REF: AMM 32-11-00	MOS HRS/MSC AFL					01-JUL-2008 10713.2 8998	11035	1800
320106	PILLAR:LEFT MAIN GEAR ACTUATOR PILLAR								LIFE LIMIT
32.430	PN SN-UNKNOWN REF: AMM 32-31-05	MOS HRS/MSC AFL	18000	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0	18000	8765
320108	PIN:LEFT MAIN GEAR ACTUATOR ATTACHMENT PIN								LIFE LIMIT
32.040	2341100-6 2262 REF: GENERIC NO REF	MOS HRS/MSC AFL	9000				01-JUL-2008 10713.2 8998	11035	1800
320111	ACTUATOR:LEFT MAIN GEAR ACTUATOR								LIFE LIMIT
32.020	2327100-6 2912 REF: AMM 32-31-01	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0	20000	10765
320113	VALVE:LEFT MAIN GEAR ACTUATOR SHUTTLE VALVE								
32.410	PN SN-UNKNOWN REF: AMM 32-33-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
320131	SWITCH:LEFT MAIN GEAR DOOR UPLATCH SWITCH								
	PN	MOS		TSN:0			23-OCT-1978		
32.170	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-60-02	AFL		TSN:0			0		
320136	SWITCH:LEFT MAIN GEAR UP SWITCH								
	PN	MOS		TSN:0			23-OCT-1978		
32.170	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-30-01	AFL		TSN:0			0		
320141	SWITCH:LEFT MAIN GEAR DOWNLOCK SWITCH								
	PN	MOS		TSN:0			23-OCT-1978		
32.160	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-60-01	AFL		TSN:0			0		
320146	SWITCH:LEFT MAIN GEAR DOOR DOWN SWITCH								
	PN	MOS		TSN:0			23-OCT-1978		
32.190	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-30-03	AFL		TSN:0			0		
320151	SWITCH:LEFT MAIN GEAR SQUAT SWITCH								
	PN	MOS		TSN:0			23-OCT-1978		
32.200	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-30-04	AFL		TSN:0			0		
320161	ACTUATOR:LEFT INBOARD DOOR UPLOCK ACTUATOR								
	PN	MOS		TSN:0			23-OCT-1978		
32.280	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-31-04	AFL		TSN:0			0		
320166	ACTUATOR:LEFT INBOARD DOOR ACTUATOR								
	PN	MOS		TSN:0			23-OCT-1978		
32.320	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-31-03	AFL		TSN:0			0		
320168	VALVE:LEFT MAIN GEAR DOOR SHUTTLE VALVE								
	PN	MOS		TSN:0			23-OCT-1978		
32.420	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-33-01	AFL		TSN:0			0		
320171	ARM:LEFT MAIN GEAR STRUT UPPER TORQUE ARM								
	2341119-7	MOS		TSN:0			24-JAN-1997		
32.270	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			7187.4		
	REF: AMM 32-11-01	AFL		TSN:0			5919		
320176	ARM:LEFT MAIN GEAR STRUT LOWER TORQUE ARM								
	PN	MOS		TSN:0			23-OCT-1978		
32.270	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-11-01	AFL		TSN:0			0		
320601	STRUT:RIGHT MAIN GEAR SHOCK STRUT								<b>LIFE LIMIT</b>
	2341100-6	MOS					01-JUL-2008		
32.010	2262	HRS/MSC					10713.2		
	REF: AMM 32-11-00	AFL	9000	TSN:6963			8998	<b>11035</b>	1800
320606	PILLAR:RIGHT MAIN GEAR ACTUATOR PILLAR								<b>LIFE LIMIT</b>
	PN	MOS		TSN:0			23-OCT-1978		
32.430	SN-UNKNOWN	HRS/MSC		TSN:0			0		
	REF: AMM 32-31-05	AFL	18000	TSN:0			0	<b>18000</b>	8765

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
320608	PIN:RIGHT MAIN GEAR ACTUATOR ATTACHMENT PIN								LIFE LIMIT
32.040	5441101 N/A REF: GENERIC NO REF	MOS HRS/MSC AFL		TSN:0 TSN:0			01-JUL-2008 10713.2 8998	17998	8763
320611	ACTUATOR:RIGHT MAIN GEAR ACTUATOR								LIFE LIMIT
32.020	2327100-6 2969 REF: AMM 32-31-01	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0	20000	10765
320613	VALVE:RIGHT MAIN GEAR ACTUATOR SHUTTLE VALVE								
32.410	PN SN-UNKNOWN REF: AMM 32-33-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
320631	SWITCH:RIGHT MAIN GEAR DOOR UPLATCH SWITCH								
32.180	PN SN-UNKNOWN REF: AMM 32-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
320636	SWITCH:RIGHT MAIN GEAR UP SWITCH								
32.180	PN SN-UNKNOWN REF: AMM 32-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
320641	SWITCH:RIGHT MAIN GEAR DOWNLOCK SWITCH								
32.160	1EN1-8 SN-UNKNOWN REF: AMM 32-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-DEC-1996 7115.4 5855		
320646	SWITCH:RIGHT MAIN GEAR DOOR DOWN SWITCH								
32.190	PN SN-UNKNOWN REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
320651	SWITCH:RIGHT MAIN GEAR SQUAT SWITCH								
32.200	PN SN-UNKNOWN REF: AMM 32-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
320661	ACTUATOR:RIGHT INBOARD DOOR UPLOCK ACTUATOR								
32.280	PN SN-UNKNOWN REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
320666	ACTUATOR:RIGHT INBOARD DOOR ACTUATOR								
32.320	PN SN-UNKNOWN REF: AMM 32-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
320668	VALVE:RIGHT MAIN GEAR DOOR SHUTTLE VALVE								
32.420	PN SN-UNKNOWN REF: AMM 32-33-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
320671	ARM:RIGHT MAIN GEAR STRUT UPPER TORQUE ARM								
32.290	2341119-7 SN-UNKNOWN REF: AMM 32-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-JAN-1997 7187.4 5919		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
320676	ARM:RIGHT MAIN GEAR STRUT LOWER TORQUE ARM								
32.290	PN SN-UNKNOWN REF: AMM 32-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
320681	SWITCH:GEAR DOWN SAFETY SWITCH								
32.210	PN SN-UNKNOWN REF: AMM 32-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
321079	REPLACE LEFT MAIN LANDING GEAR DOOR ACTUATOR RETRACT HOSE (IRN G3210003)								<b>SCRAP</b>
		MOS HRS/MSC AFL	60 1500	+14d/-14d +25/-25	-8		28-AUG-2008 10753.8 9029	<b>31-AUG-2013</b> <b>12253.8</b>	03-SEP-2013 12278.8 1272 d (+3) 1288.8 (+25)
321080	REPLACE RIGHT MAIN LANDING GEAR DOOR ACTUATOR RETRACT HOSE (IRN G3210003)								<b>SCRAP</b>
		MOS HRS/MSC AFL	60 1500	+14d/-14d +25/-25	-8		28-AUG-2008 10753.8 9029	<b>31-AUG-2013</b> <b>12253.8</b>	03-SEP-2013 12278.8 1272 d (+3) 1288.8 (+25)
321081	REPLACE LEFT MAIN LANDING GEAR ACTUATOR RETRACT HOSE (IRN G3210003)								<b>SCRAP</b>
		MOS HRS/MSC AFL	60 1500	+14d/-14d +25/-25	-8		28-AUG-2008 10753.8 9029	<b>31-AUG-2013</b> <b>12253.8</b>	03-SEP-2013 12278.8 1272 d (+3) 1288.8 (+25)
321082	REPLACE RIGHT MAIN LANDING GEAR ACTUATOR RETRACT HOSE (IRN G3210003)								<b>SCRAP</b>
		MOS HRS/MSC AFL	60 1500	+14d/-14d +25/-25	-8		28-AUG-2008 10753.8 9029	<b>31-AUG-2013</b> <b>12253.8</b>	03-SEP-2013 12278.8 1272 d (+3) 1288.8 (+25)
321083	REPLACE NOSE LANDING GEAR ACTUATOR RETRACT HOSE (IRN G3210003)								<b>SCRAP</b>
		MOS HRS/MSC AFL	60 1500	+14d/-14d +25/-25	-8		28-AUG-2008 10753.8 9029	<b>31-AUG-2013</b> <b>12253.8</b>	03-SEP-2013 12278.8 1272 d (+3) 1288.8 (+25)
321084	REPLACE NOSE LANDING GEAR ACTUATOR EXTEND HOSE (IRN G3210003)								<b>SCRAP</b>
32.470		MOS HRS/MSC AFL	60 1500	+14d/-14d +25/-25	-8		28-AUG-2008 10753.8 9029	<b>31-AUG-2013</b> <b>12253.8</b>	03-SEP-2013 12278.8 1272 d (+3) 1288.8 (+25)
	REF: GENERIC NO REF								
321085	REPLACE LEFT MAIN LANDING GEAR ACTUATOR EXTEND HOSE (IRN G3210003)								<b>SCRAP</b>
32.480		MOS HRS/MSC AFL	60 1500	+14d/-14d +25/-25	-8		28-AUG-2008 10753.8 9029	<b>31-AUG-2013</b> <b>12253.8</b>	03-SEP-2013 12278.8 1272 d (+3) 1288.8 (+25)
	REF: GENERIC NO REF								
321086	REPLACE RIGHT MAIN LANDING GEAR ACTUATOR EXTEND HOSE (IRN G3210003)								<b>SCRAP</b>
32.480		MOS HRS/MSC AFL	60 1500	+14d/-14d +25/-25	-8		28-AUG-2008 10753.8 9029	<b>31-AUG-2013</b> <b>12253.8</b>	03-SEP-2013 12278.8 1272 d (+3) 1288.8 (+25)
	REF: GENERIC NO REF								
321087	REPLACE LEFT MAIN LANDING GEAR DOOR ACTUATOR EXTEND HOSE (IRN G3210003)								<b>SCRAP</b>
32.490		MOS HRS/MSC AFL	60 1500	+14d/-14d +25/-25	-8		28-AUG-2008 10753.8 9029	<b>31-AUG-2013</b> <b>12253.8</b>	03-SEP-2013 12278.8 1272 d (+3) 1288.8 (+25)
	REF: GENERIC NO REF								
321088	REPLACE RIGHT MAIN LANDING GEAR DOOR ACTUATOR EXTEND HOSE (IRN G3210003)								<b>SCRAP</b>
32.490		MOS HRS/MSC AFL	60 1500	+14d/-14d +25/-25	-8		28-AUG-2008 10753.8 9029	<b>31-AUG-2013</b> <b>12253.8</b>	03-SEP-2013 12278.8 1272 d (+3) 1288.8 (+25)
	REF: GENERIC NO REF								

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
321089	REPLACE LEFT MAIN LANDING GEAR DOOR UPLATCH ACTUATOR HOSE (IRN G3210003)								<b>SCRAP</b>
32.500		MOS	60	+14d/-14d	-8	28-AUG-2008	31-AUG-2013	03-SEP-2013	1272 d (+3)
		HRS/MSC	1500	+25/-25		10753.8	12253.8	12278.8	1288.8 (+25)
	REF: GENERIC NO REF	AFL				9029			
321090	REPLACE RIGHT MAIN LANDING GEAR DOOR UPLATCH ACTUATOR HOSE (IRN G3210003)								<b>SCRAP</b>
32.500		MOS	60	+14d/-14d	-8	28-AUG-2008	31-AUG-2013	03-SEP-2013	1272 d (+3)
		HRS/MSC	1500	+25/-25		10753.8	12253.8	12278.8	1288.8 (+25)
	REF: GENERIC NO REF	AFL				9029			
321091	REPLACE NOSE LANDING GEAR UPLATCH ACTUATOR HOSE (IRN G3210003)								<b>SCRAP</b>
32.500		MOS	60	+14d/-14d	-8	28-AUG-2008	31-AUG-2013	03-SEP-2013	1272 d (+3)
		HRS/MSC	1500	+25/-25		10753.8	12253.8	12278.8	1288.8 (+25)
	REF: GENERIC NO REF	AFL				9029			
321093	REPLACE LEFT MAIN GEAR ** HYDRAULIC BRAKE HOSE ASSEMBLY (IRN G3243040)								<b>SCRAP</b>
32.505		MOS	60	+14d/-14d	-38	17-FEB-2010	31-JAN-2015	31-JAN-2015	1790 d
		HRS/MSC	2400	+25/-25		10956.5	13356.5	13381.5	2391.5 (+25)
	REF: GENERIC NO REF	AFL				9224			
321094	REPLACE RIGHT MAIN GEAR ** HYDRAULIC BRAKE HOSE ASSEMBLY (IRN G3243040)								<b>SCRAP</b>
32.505		MOS	60	+14d/-14d	-38	17-FEB-2010	31-JAN-2015	31-JAN-2015	1790 d
		HRS/MSC	2400	+25/-25		10956.5	13356.5	13381.5	2391.5 (+25)
	REF: GENERIC NO REF	AFL				9224			
321101	STRUT:NOSE GEAR STRUT								<b>LIFE LIMIT</b>
32.220	2342100-7	MOS				23-OCT-1978			
	2468	HRS/MSC				0			
	REF: AMM 32-21-00	AFL	20000	+25/-25		0	20000	20025	10765 (+25)
321106	ACTUATOR:NOSE GEAR ACTUATOR								<b>LIFE LIMIT</b>
32.030	2317100-5	MOS				23-OCT-1978			
	2474	HRS/MSC				0			
	REF: AMM 32-32-02	AFL	20000			0	20000		10765
321116	VALVE:NOSE GEAR PRIORITY VALVE								
32.330	4558	MOS				02-DEC-1996			
	1421	HRS/MSC	O/C			7115.4			
	REF: AMM 32-32-01	AFL				5855			
321119	VALVE:NOSE GEAR SHUTTLE VALVE								
32.510	PN-UNKNOWN	MOS				01-DEC-1993			
	2660	HRS/MSC	O/C			6008.8			
	REF: AMM 32-33-01	AFL				4926			
321126	ACTUATOR:NOSE GEAR UPLATCH ACTUATOR								
32.250	PN	MOS				23-OCT-1978			
	SN-UNKNOWN	HRS/MSC	O/C			0			
	REF: AMM 32-32-03	AFL				0			
321141	SWITCH:NOSE GEAR DOWN LOCK SWITCH								
32.230	PN	MOS				23-OCT-1978			
	SN-UNKNOWN	HRS/MSC	O/C			0			
	REF: AMM 32-60-03	AFL				0			
321146	SWITCH:NOSE GEAR UPLATCH SWITCH								
32.230	PN	MOS				23-OCT-1978			
	SN-UNKNOWN	HRS/MSC	O/C			0			
	REF: AMM 32-60-04	AFL				0			

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
321301	VALVE:GEAR SELECTOR VALVE 48C48608-102	MOS					24-JAN-2006		
32.530	3493 REF: GENERIC NO REF	HRS/MSC AFL	O/C				10468.3		
321306	VALVE:MLG GEAR DOOR CONTROL VALVE PN	MOS		TSN:0			23-OCT-1978		
32.530	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
321601	VALVE:EMERGENCY AIR SHUTTLE VALVE PN	MOS		TSN:0			23-OCT-1978		
32.330	SN-UNKNOWN REF: AMM 32-33-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
321626	VALVE:EMERGENCY GEAR EXTEND VALVE PN	MOS		TSN:0			23-OCT-1978		
32.520	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
321646	VALVE:EMERGENCY BRAKE VALVE PN	MOS		TSN:0			23-OCT-1978		
32.520	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
321651	VALVE:EMERGENCY AIR RELIEF VALVE PN	MOS		TSN:0			23-OCT-1978		
32.510	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
322101	WHEEL:LEFT MAIN GEAR OUTBOARD WHEEL 9543991-4	MOS		TSO:25			07-DEC-2009		
32.050	APR76-1867 REF: AMM 32-42-00	HRS/MSC AFL	O/C	TSO:365.5 TSO:324			10928.4 9202		
322106	TIRE:LEFT MAIN GEAR OUTBOARD TIRE 178K23-5	MOS					07-DEC-2009		
32.050	SN-UNKNOWN REF: AMM 32-42-00	HRS/MSC AFL	O/C				10928.4 9202		
322121	WHEEL:LEFT MAIN GEAR INBOARD WHEEL 9543991-4	MOS		TSO:25			07-DEC-2009		
32.060	MAY-79-3800 REF: AMM 32-42-00	HRS/MSC AFL	O/C	TSO:365.5 TSO:324			10928.4 9202		
322126	TIRE:LEFT MAIN GEAR INBOARD TIRE 178K23-5	MOS					07-DEC-2009		
32.060	SN-UNKNOWN REF: AMM 32-42-00	HRS/MSC AFL	O/C				10928.4 9202		
322141	WHEEL:RIGHT MAIN GEAR INBOARD WHEEL 9543991-4	MOS		TSO:25			07-DEC-2009		
32.070	MAR82-5680 REF: AMM 32-42-00	HRS/MSC AFL	O/C	TSO:365.5 TSO:324			10928.4 9202		
322146	TIRE:RIGHT MAIN GEAR INBOARD TIRE 178K23-5	MOS					07-DEC-2009		
32.070	SN-UNKNOWN REF: AMM 32-42-00	HRS/MSC AFL	O/C				10928.4 9202		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
322161	WHEEL:RIGHT MAIN GEAR OUTBOARD WHEEL 9543991-4	MOS		TSO:25				07-DEC-2009	
32.080	DEC86-7130 REF: AMM 32-42-00	HRS/MSC AFL	O/C	TSO:365.5 TSO:324			10928.4 9202		
322166	TIRE:RIGHT MAIN GEAR OUTBOARD TIRE 178K23-5	MOS						07-DEC-2009	
32.080	SN-UNKNOWN REF: AMM 32-40-00	HRS/MSC AFL	O/C				10928.4 9202		
322181	WHEEL:NOSE LANDING GEAR WHEEL 9544207-5	MOS						10-JAN-2005	
32.090	JAN75-1819 REF: AMM 32-41-00	HRS/MSC AFL	O/C				10438.3 8767		
322186	TIRE:NOSE LANDING GEAR TIRE PN-UNKNOWN	MOS		TSN:0				10-JAN-2005	
32.090	SN-UNKNOWN REF: AMM 32-41-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			10438.3 8767		
322191	WHEEL ASSEMBLY:SPARE WHEEL ASSEMBLY PN	MOS		TSN:0				23-OCT-1978	
322196	TIRE ASSEMBLY:SPARE TIRE ASSEMBLY PN	MOS		TSN:0				23-OCT-1978	
32.370	2380002-18 7751913 REF: AMM 32-43-02	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			7187.4 5919		
322606	VALVE:PILOT RIGHT POWER BRAKE VALVE 2380002-18	MOS		TSN:0				24-JAN-1997	
32.370	7992966A REF: AMM 32-43-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			7187.4 5919		
322611	VALVE:COPILOT LEFT POWER BRAKE VALVE 2380002-20	MOS		TSN:0				01-APR-1998	
32.380	3602A REF: AMM 32-43-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			7830		
322616	VALVE:COPILOT RIGHT POWER BRAKE VALVE 2380002-20	MOS		TSN:0				01-APR-1998	
32.380	5604A REF: AMM 32-43-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			7830		
322621	VALVE:LEFT BRAKE SHUTTLE VALVE PN	MOS		TSN:0				23-OCT-1978	
32.340	SN-UNKNOWN REF: AMM 32-45-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
322626	VALVE:RIGHT BRAKE SHUTTLE VALVE PN	MOS		TSN:0				23-OCT-1978	
32.340	SN-UNKNOWN REF: AMM 32-45-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)



Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
322631	BRAKE:LEFT MAIN GEAR OUTBOARD BRAKE PN-UNKNOWN MAY82-655 REF: AMM 32-43-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-SEP-2003 10283.9 8615		
322636	BRAKE:LEFT MAIN GEAR INBOARD BRAKE PN-UNKNOWN MAY80-2244 REF: AMM 32-43-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-SEP-2003 10283.9 8615		
322641	BRAKE:RIGHT MAIN GEAR INBOARD BRAKE PN-UNKNOWN JUN99-5124 REF: AMM 32-43-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-SEP-2003 10283.9 8615		
322646	BRAKE:RIGHT MAIN GEAR OUTBOARD BRAKE PN-UNKNOWN MAY85-294 REF: AMM 32-43-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-SEP-2003 10283.9 8615		
322651	FUSE:LEFT OUTBOARD HYDRAULIC BRAKE FUSE PN SN-UNKNOWN REF: AMM 32-43-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
322656	FUSE:LEFT INBOARD HYDRAULIC BRAKE FUSE PN SN-UNKNOWN REF: AMM 32-43-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
322661	FUSE:RIGHT INBOARD HYDRAULIC BRAKE FUSE PN SN-UNKNOWN REF: AMM 32-43-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
322666	FUSE:RIGHT OUTBOARD HYDRAULIC BRAKE FUSE PN SN-UNKNOWN REF: AMM 32-43-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
322671	VALVE:LEFT OUTBOARD BRAKE SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-45-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
322676	VALVE:LEFT INBOARD BRAKE SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-45-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
322681	VALVE:RIGHT INBOARD BRAKE SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-45-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
322686	VALVE:RIGHT OUTBOARD BRAKE SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-45-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
322691	VALVE:LEFT PARKING BRAKE VALVE 2380059-5	MOS		TSR:0			23-SEP-2002			
32.390	SN-UNKNOWN REF: AMM 32-43-04	HRS/MSC AFL	O/C	TSR:0 TSR:0			9789.9 8061			
322696	VALVE:RIGHT PARKING BRAKE VALVE PN	MOS		TSN:0			23-OCT-1978			
32.390	SN-UNKNOWN REF: AMM 32-43-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
323091	REPLACE LEFT MAIN GEAR AIR HOSE ASSEMBLY FOR LANDING GEAR EMERGENCY BLOWDOWN (IRN L3233013)	MOS	144	+14d/-14d			10-MAY-2007	<b>31-MAY-2019</b>	31-MAY-2019	3371 d
32.450	REF: GENERIC NO REF	HRS/MSC AFL					10494.7 8823	<b>14823</b>	14848	5588 (+25)
323092	REPLACE RIGHT MAIN GEAR AIR HOSE ASSEMBLY FOR LANDING GEAR EMERGENCY BLOWDOWN (IRN L3233013)	MOS	144	+14d/-14d			10-MAY-2007	<b>31-MAY-2019</b>	31-MAY-2019	3371 d
32.450	REF: GENERIC NO REF	HRS/MSC AFL					10494.7 8823	<b>14823</b>	14848	5588 (+25)
323093	REPLACE NOSE GEAR AIR HOSE ASSEMBLY FOR LANDING GEAR EMERGENCY BLOWDOWN (IRN L3233013)	MOS	144	+14d/-14d			10-MAY-2007	<b>31-MAY-2019</b>	31-MAY-2019	3371 d
32.450	REF: GENERIC NO REF	HRS/MSC AFL					10494.7 8823	<b>14823</b>	14848	5588 (+25)
323094	REPLACE LEFT MAIN GEAR AIR HOSE ASSEMBLY FOR EMERGENCY BRAKING SYSTEM (IRN L3233013)	MOS	144	+14d/-14d			10-MAY-2007	<b>31-MAY-2019</b>	31-MAY-2019	3371 d
32.460	REF: GENERIC NO REF	HRS/MSC AFL					10494.7 8823	<b>14823</b>	14848	5588 (+25)
323095	REPLACE RIGHT MAIN GEAR AIR HOSE ASSEMBLY FOR EMERGENCY BRAKING SYSTEM (IRN L3233013)	MOS	144	+14d/-14d			10-MAY-2007	<b>31-MAY-2019</b>	31-MAY-2019	3371 d
32.460	REF: GENERIC NO REF	HRS/MSC AFL					10494.7 8823	<b>14823</b>	14848	5588 (+25)
323101	TRANSDUCER:LEFT OUTBOARD MAIN GEAR WHEEL SPEED TRANSDUCER 40-911	MOS		TSO:0			22-JUL-1996			
32.120	2506 REF: AMM 32-44-01	HRS/MSC AFL	O/C	TSO:0 TSO:0			6899.5			
323106	TRANSDUCER:LEFT INBOARD MAIN GEAR WHEEL SPEED TRANSDUCER PN	MOS		TSN:0			23-OCT-1978			
32.120	SN-UNKNOWN REF: AMM 32-44-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
323111	TRANSDUCER:RIGHT INBOARD MAIN GEAR WHEEL SPEED TRANSDUCER PN	MOS		TSN:0			23-OCT-1978			
32.130	SN-UNKNOWN REF: AMM 32-44-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
323116	TRANSDUCER:RIGHT OUTBOARD MAIN GEAR WHEEL SPEED TRANSDUCER PN	MOS		TSN:0			23-OCT-1978			
32.130	SN-UNKNOWN REF: AMM 32-44-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
323121	VALVE:LEFT ANTI-SKID VALVE 39-309-1	MOS		TSO:0			25-AUG-1999			
32.400	1293 REF: AMM 32-44-02	HRS/MSC AFL	O/C	TSO:0 TSO:0			8564.7 6998			

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
323126	VALVE:RIGHT ANTI-SKID VALVE									
32.400	39-309-1 307 REF: AMM 32-44-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-JUN-1996 6827.7 5607			
323131	CONTROL BOX:ANTI-SKID CONTROL BOX									
32.240	42-379-1 605A REF: AMM 32-44-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-AUG-1996 6925.6 5686			
323601	COMPUTER/AMPLIFIER:NOSE STEERING COMPUTER/AMPLIFIER									
32.240	6608278-1 1456 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-JUN-1996 6827.7 5607			
323606	FOLLOWUP:NOSE WHEEL STEERING FOLLOWUP									
32.260	PN SN-UNKNOWN REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
323611	SERVO:NOSE WHEEL STEERING ACTUATOR SERVO									
32.140	501-1212-01 1818 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			23-SEP-2002 9789.9 8061			
+ 323612	SERVO:INSPECT NOSE WHEEL STEERING ACTUATOR SERVO (IRN C3255001)									
32.140	MOS HRS/MSC REF: See Workcard	MOS HRS/MSC AFL	2000	+25/-25			23-SEP-2002 9789.9 8061	11789.9	11814.9	824.9 (+25)
323613	GEARBOX:NOSE STEERING ACTUATOR GEARBOX									
32.150	PN SN-UNKNOWN REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
323616	FOLLOWUP:RUDDER PEDAL FOLLOWUP									
32.260	PN SN-UNKNOWN REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
325005	UNIT:STEERING INTERFACE UNIT									
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
326000	PERFORM FUNCTIONAL TEST ON THE RIGHT GEAR DOWN SAFETY SWITCH AND ANTI-SKID ELECTRICAL CONTACTS (IRN R3244024)								<b>INSPECT</b>	
	MOS HRS/MSC REF: AMM 32-30-02	MOS HRS/MSC AFL	300				(EBT)  11220.18	11220.18	255.18	
5-11-00-G3210003	REPLACE HYDRAULIC HOSE ASSEMBLIES ATTACHED TO THE MAIN GEAR ACTUATORS, MAIN GEAR DOOR ACTUATORS, AND THE MAIN AND NOSE GEAR UPLATCH ACTUATOR								<b>SCRAP</b>	
	MOS HRS/MSC REF:	MOS HRS/MSC AFL	60	+14d/-14d	-8		28-AUG-2008 10753.8 9029	31-AUG-2013 12253.8	03-SEP-2013 12278.8	1272 d (+3) 1288.8 (+25)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
5-11-00-L3233013	REPLACE EMERGENCY AIR HOSE ASSEMBLIES FOR LANDING GEAR EMERGENCY BLOWDOWN AND EMERGENCY BRAKING SYSTEMS	MOS	144	+14d/-14d			10-MAY-2007	31-MAY-2019	31-MAY-2019	3371 d
	REF:	HRS/MSC AFL	6000	+25/-25			10494.7 8823	14823	14848	5588 (+25)
<b>CHAPTER 33 LIGHTS</b>										
330101	CONTROL BOX:WARNING LIGHT CONTROL BOX 2618055-30	MOS					26-NOV-2007			
33.010	237401	HRS/MSC	O/C				10567.7			
	REF: AMM 33-14-03	AFL					8882			
330601	BULB:LEFT LANDING & TAXI LIGHT BULB 4580	MOS					23-SEP-1996			
33.020	SN-UNKNOWN	HRS/MSC	O/C				TSN:0			
	REF: AMM 33-40-01	AFL					TSN:0			
330606	BULB:RIGHT LANDING & TAXI LIGHT BULB 4580	MOS					24-OCT-1996			
33.020	SN-UNKNOWN	HRS/MSC	O/C				TSN:0			
	REF: AMM 33-40-01	AFL					TSN:0			
330611	LIGHT:LEFT WING TIP TANK RECOGNITION LIGHT PN	MOS					23-OCT-1978			
33.030	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 33-40-05	AFL					0			
330612	LIGHT:RIGHT WING TIP TANK RECOGNITION LIGHT PN	MOS					23-OCT-1978			
33.030	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 33-40-05	AFL					0			
331101	LIGHT:LEFT WING STROBE LIGHT PN	MOS					23-OCT-1978			
33.040	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 33-40-04	AFL					0			
331106	LIGHT:RIGHT WING STROBE LIGHT PN	MOS					23-OCT-1978			
33.040	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 33-40-04	AFL					0			
331111	LIGHT:TAIL STROBE LIGHT 40-0100-1	MOS					27-FEB-1990			
33.040	5444	HRS/MSC	O/C				5085.3			
	REF: AMM 33-40-04	AFL					4137			
331112	POWER SUPPLY:LEFT STROBE LIGHT POWER SUPPLY PN	MOS					23-OCT-1978			
33.050	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 33-40-04	AFL					0			
331113	POWER SUPPLY:RIGHT STROBE LIGHT POWER SUPPLY PN	MOS					23-OCT-1978			
33.050	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 33-40-04	AFL					0			

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
331114	POWER SUPPLY:TAIL STROBE LIGHT POWER SUPPLY 61-2008	MOS		TSR:0			26-APR-1995		
33.050	4675 REF: AMM 33-40-04	HRS/MSC AFL	O/C	TSR:0 TSR:0			6295.5 5174		
331116	BASE & TIMER:STROBE LIGHT BASE & TIMER PN	MOS		TSN:0			23-OCT-1978		
33.060	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
331121	LIGHT:UPPER ANTI-COLLISION LIGHT 40-100-1	MOS					10-JAN-2005		
33.070	2963 REF: AMM 33-40-03	HRS/MSC AFL	O/C				10438.3 8767		
331126	LIGHT:LOWER ANTI-COLLISION LIGHT 40-0100-3	MOS		TSO:0			24-OCT-1996		
33.070	3846 REF: AMM 33-40-03	HRS/MSC AFL	O/C	TSO:0 TSO:0			7062.8		
331601	DIMMER ASSEMBLY:PILOT LIGHT DIMMER ASSEMBLY PN	MOS		TSN:0			23-OCT-1978		
33.080	SN-UNKNOWN REF: AMM 33-15-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
331606	DIMMER ASSEMBLY:COPILOT LIGHT DIMMER ASSEMBLY 1977-1	MOS		TSR:0			10-JAN-2005		
33.080	2429 REF: AMM 33-15-00	HRS/MSC AFL	O/C	TSR:0 TSR:0			10438.3 8767		
331611	ASSEMBLY:CENTER / PEDESTAL LIGHT DIMMER ASSEMBLY 6608096-5	MOS		TSN:0			13-JUN-1997		
33.080	2160 REF: AMM 33-15-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			7321.3 6022		
331616	TRANSFORMER:COLD CATHODE TRANSFORMER PN	MOS		TSN:0			23-OCT-1978		
33.060	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
331621	INVERTER:COLD CATHODE CABIN LIGHTS FORWARD INVERTER PN	MOS		TSN:0			23-OCT-1978		
33.090	SN-UNKNOWN REF: AMM 33-22-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
331626	INVERTER:COLD CATHODE CABIN LIGHTS AFT INVERTER PN	MOS		TSN:0			23-OCT-1978		
33.090	SN-UNKNOWN REF: AMM 33-22-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
331631	INVERTER:COLD CATHODE CABIN LIGHTS OPTIONAL INVERTER PN	MOS		TSN:0			23-OCT-1978		
33.090	SN-UNKNOWN REF: AMM 33-22-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
331636	CONTROL:FORWARD CABIN LIGHT DIMMER CONTROL PN	MOS		TSN:0			23-OCT-1978		
33.100	SN-UNKNOWN REF: AMM 33-22-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
331641	CONTROL:AFT CABIN LIGHT DIMMER CONTROL								
33.100	PN SN-UNKNOWN REF: AMM 33-22-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
335011	POWER SUPPLY:AFT EMERGENCY POWER SUPPLY								
33.110	PN SN-UNKNOWN REF: AMM 33-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
335016	POWER SUPPLY:FORWARD EMERGENCY POWER SUPPLY								
33.110	PN SN-UNKNOWN REF: AMM 33-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
<b>CHAPTER 34 NAVIGATION</b>									
340001	ANNUAL AVIONICS FUNCTIONAL CHECKS								
		MOS HRS/MSC AFL	12				07-DEC-2009 10928.4 9202	<b>31-DEC-2010</b>	298 d
	REF: OMM NDA LJ 35/36 AAIP APPENDIX A								
340002	CALIBRATION CHECK COMPASS SYSTEM (SYSTEM #1)								
		MOS HRS/MSC AFL	36				14-NOV-2008 10763.4 9034	<b>30-NOV-2011</b>	632 d
	REF: OMM NDA LJ 35/36 AAIP APPENDIX D								
340003	CALIBRATION CHECK COMPASS SYSTEM (SYSTEM #2)								
		MOS HRS/MSC AFL	36				14-NOV-2008 10763.4 9034	<b>30-NOV-2011</b>	632 d
	REF: OMM NDA LJ 35/36 AAIP APPENDIX D								
340004	CALIBRATION CHECK COMPASS SYSTEM (STANDBY)								
		MOS HRS/MSC AFL	36				14-NOV-2008 10763.4 9034	<b>30-NOV-2011</b>	632 d
	REF: OMM NDA LJ 35/36 AAIP APPENDIX D								
340101	INDICATOR:LEFT RATE OF CLIMB INDICATOR								
34.090	PN SN-UNKNOWN REF: AMM 34-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
340111	INDICATOR:RIGHT RATE OF CLIMB INDICATOR								
34.090	PN SN-UNKNOWN REF: AMM 34-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
340121	INDICATOR:LEFT MACH AIRSPEED INDICATOR								
34.100	BAS35035552-117 290 REF: AMM 34-10-02	MOS HRS/MSC AFL	O/C				14-APR-2005 10441 8769		
340131	INDICATOR:RIGHT MACH AIRSPEED INDICATOR								
34.100	BAS35035552-117 289 REF: AMM 34-10-02	MOS HRS/MSC AFL	O/C				14-APR-2005 10441 8769		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
340133	SWITCH:LEFT STALL WARNING ALTITUDE SWITCH								
34.110	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
340137	SWITCH:RIGHT STALL WARNING ALTITUDE SWITCH								
34.110	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
340138	PROBE:TOTAL TEMP PROBE								
34.110	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
340141	ALTIMETER / ADDU:LEFT ALTIMETER / ADDU								
34.010	90-80130-1 43109 REF: AMM 34-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-APR-2005 10441 8769		
+ 340146	ALTIMETER / ADDU:TEST LEFT ALTIMETER / ADDU (91.411)								<b>MANDATORY</b>
34.010	PKG 2 REF: See Workcard	MOS HRS/MSC AFL	24				28-MAY-2009 10838.5 9102	31-MAY-2011	449 d
340147	ALTIMETER / ADDU:EMERGENCY POWER CHECK LEFT ALTIMETER / ADDU								
34.020	REF: See Workcard	MOS HRS/MSC AFL	300				29-AUG-2008 10753.8 9029	11053.8	88.8
340151	ALTIMETER / ADDU:RIGHT ALTIMETER / ADDU								
34.020	90-80130-1 43011 REF: AMM 34-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-APR-2005 10441 8769		
+ 340156	ALTIMETER / ADDU:TEST RIGHT ALTIMETER / ADDU (91.411)								<b>MANDATORY</b>
34.020	PKG 2 REF: See Workcard	MOS HRS/MSC AFL	24				28-MAY-2009 10838.5 9102	31-MAY-2011	449 d
+ 340201	TEST LEFT PITOT SYSTEM(91.411)								<b>MANDATORY</b>
34.030	PKG 2 REF: OMM AMI-STC-LJ3536 (STC SA00952SE-D)	MOS HRS/MSC AFL	24				28-MAY-2009 10838.5 9102	31-MAY-2011	449 d
+ 340206	TEST RIGHT PITOT SYSTEM(91.411)								<b>MANDATORY</b>
34.030	PKG 2 REF: See Workcard	MOS HRS/MSC AFL	24				28-MAY-2009 10838.5 9102	31-MAY-2011	449 d
+ 340211	TEST LEFT STATIC SYSTEM(91.411)								<b>MANDATORY</b>
34.040	PKG 2 REF: See Workcard	MOS HRS/MSC AFL	24				28-MAY-2009 10838.5 9102	31-MAY-2011	449 d

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
340212	INSPECT/OPERATIONAL CHECK OF RVSM AVIONICS COMPONENTS PKG 2	MOS	24				28-MAY-2009 10838.5 9102	31-MAY-2011	449 d
	REF: OMM AMI-STC-LJ3536 (STC SA00952SE-D)	AFL							
340213	AIR DATA CHECK - VERIFY THE AIR DATA SYSTEM ERRORS ARE WITHIN SPECIFIED RVSM TOLERANCES PKG 2	MOS	24				28-MAY-2009 10838.5 9102	31-MAY-2011	449 d
	REF: OMM AMI-STC-LJ3536 (STC SA00952SE-D)	AFL							
340214	VISUAL INSPECTION OF THE RVSM CRITICAL REGION PKG 2	MOS	24				28-MAY-2009 10838.5 9102	31-MAY-2011	449 d
	REF: OMM AMI-STC-LJ3536 (STC SA00952SE-D)	AFL							
340215	INSPECTION/CHECK PITOT-STATIC PROBES AND INSTALLATION ANGLE MEASUREMENT. CONFIRM PROBES HAVE LESS THAN 10,000 HOURS OF OPERATIONAL SERVICE. PKG 2	MOS	24				28-MAY-2009 10838.5 9102	31-MAY-2011	449 d
	REF: OMM AMI-STC-LJ3536 (STC SA00952SE-D)	AFL							
+ 340216	TEST RIGHT STATIC SYSTEM(91.411) PKG 2	MOS	24				28-MAY-2009 10838.5 9102	31-MAY-2011	MANDATORY 449 d
34.040	REF: See Workcard	AFL							
340218	RVSM ALTITUDE HOLD CHECK FLIGHT PKG 2	MOS	24				28-MAY-2009 10838.5 9102	31-MAY-2011	449 d
	REF: OMM AMI-STC-LJ3536 (STC SA00952SE-D)	AFL							
340221	PITOT TUBE:LEFT PITOT TUBE 856NA1	MOS		TSN:0			14-APR-2005		LIFE LIMIT
34.150	229134	HRS/MSC	10000	TSN:0			10441	20441	9476
	REF: AMM 34-11-01	AFL		TSN:0			8769		
340226	PITOT TUBE:RIGHT PITOT TUBE 856NA2	MOS		TSN:0			14-APR-2005		LIFE LIMIT
34.150	230089	HRS/MSC	10000	TSN:0			10441	20441	9476
	REF: AMM 34-11-01	AFL		TSN:0			8769		
340228	SWITCH:MACH SWITCH PN-UNKNOWN	MOS		TSR:0			26-APR-1995		
34.130	378	HRS/MSC	O/C	TSR:0			6295.5		
	REF: AMM 34-11-04	AFL		TSR:0			5174		
340251	COMPUTER:NO. 1 AIR DATA COMPUTER PN	MOS		TSN:0			23-OCT-1978		
34.160	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		



Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
+ 340252	COMPUTER:TEST NO. 1 AIR DATA PKG 2	COMPUTER	(91.411) 24				28-MAY-2009 10838.5 9102	31-MAY-2011	MANDATORY	449 d
34.160	REF: See Workcard	MOS HRS/MSC AFL								
340261	COMPUTER:NO. 2 AIR DATA PN	COMPUTER		TSN:0			23-OCT-1978			
34.160	SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
+ 340262	COMPUTER:TEST NO. 2 AIR DATA PKG 2	COMPUTER	(91.411) 24				28-MAY-2009 10838.5 9102	31-MAY-2011	MANDATORY	449 d
34.160	REF: See Workcard	MOS HRS/MSC AFL								
340265	PANEL:ADC ANNUNCIATOR SWITCH BAS35035283-1	PANEL		TSN:0			14-APR-2005			
	0319 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			10441 8769			
341101	ALTIMETER:LEFT RADIO ALTIMETER PN	ALTIMETER		TSN:0			23-OCT-1978			
34.170	SN-UNKNOWN REF: AMM 34-15-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
341111	ALTIMETER:RIGHT RADIO ALTIMETER PN	ALTIMETER		TSN:0			23-OCT-1978			
34.170	SN-UNKNOWN REF: AMM 34-15-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
341121	TRANSCEIVER:RADIO ALTIMETER PN	TRANSCEIVER		TSN:0			23-OCT-1978			
34.180	SN-UNKNOWN REF: AMM 34-15-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
341131	ANTENNA:FORWARD RADIO ALTIMETER PN	ANTENNA		TSN:0			23-OCT-1978			
34.490	SN-UNKNOWN REF: AMM 34-15-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
341136	ANTENNA:AFT RADIO ALTIMETER PN	ANTENNA		TSN:0			23-OCT-1978			
34.490	SN-UNKNOWN REF: AMM 34-15-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
341141	INDICATOR:LEFT RADIO MAGNETIC 3137L-B-2-1-C	INDICATOR					17-AUG-2001			
34.570	1643 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C				9512 7764			
341151	INDICATOR:RIGHT RADIO MAGNETIC 3137L-B-2-1-C	INDICATOR		TSR:0			30-SEP-2007			
34.570	5669 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			10527.2 8851			
341156	AMPLIFIER:RMI SERVO AMPLIFIER PN	AMPLIFIER		TSN:0			23-OCT-1978			
34.580	SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
341601	INDICATOR:RAM AIR TEMPERATURE INDICATOR								
	PN	MOS		TSN:0				23-OCT-1978	
34.190	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
342101	GYRO:LEFT DIRECTIONAL GYRO								
	PN-UNKNOWN	MOS		TSR:0				26-APR-1995	
34.050	1288	HRS/MSC	O/C	TSR:0			6295.5		
	REF: AMM 34-21-00	AFL		TSR:0			5174		
342111	GYRO:RIGHT DIRECTIONAL GYRO								
	501-1162-01	MOS		TSR:0				18-OCT-2002	
34.050	1288	HRS/MSC	O/C	TSR:0			9807.1		
	REF: AMM 34-21-00	AFL		TSR:0			8027		
342121	FLUX VALVE:LEFT WING FLUX VALVE								
	620359	MOS		TSN:0				16-MAR-1982	
34.200	78076771	HRS/MSC	O/C	TSN:0					
	REF: AMM 34-21-01	AFL		TSN:0					
342131	FLUX VALVE:RIGHT WING FLUX VALVE								
	620359	MOS		TSN:0				16-MAR-1982	
34.200	78076772	HRS/MSC	O/C	TSN:0					
	REF: AMM 34-21-01	AFL		TSN:0					
342136	HSI:LEFT HSI								
	792-6356-003	MOS		TSR:0				26-JUN-2001	
34.210	781	HRS/MSC	O/C	TSR:0			9492.1		
	REF: AMM 34-23-00	AFL		TSR:0			7742		
342146	HSI:RIGHT HSI								
	PN	MOS		TSN:0				23-OCT-1978	
34.210	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-23-00	AFL		TSN:0			0		
342176	COMPASS:STANDBY COMPASS								
	PN	MOS		TSN:0				23-OCT-1978	
34.500	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
342601	GYRO:PRIMARY VERTICAL GYRO								
	501-1204-01	MOS		TSO:0				04-JAN-2008	
34.220	1623	HRS/MSC	O/C	TSO:0			10610.7		
	REF: AMM 34-22-00	AFL		TSO:0			8909		
342611	GYRO:SECONDARY VERTICAL GYRO								
	501-1114-01	MOS		TSO:0				22-DEC-2003	
34.220	2380	HRS/MSC	O/C	TSO:0			10421.9		
	REF: AMM 34-22-00	AFL		TSO:0			8753		
342621	INDICATOR:PRIMARY VERTICAL GYRO INDICATOR								
	PN	MOS		TSN:0				23-OCT-1978	
34.230	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-23-00	AFL		TSN:0			0		
342631	INDICATOR:SECONDARY VERTICAL GYRO INDICATOR								
	5-4000-08	MOS		TSN:0				23-AUG-1996	
34.230	1323	HRS/MSC	O/C	TSN:0			6939.1		
	REF: AMM 34-23-00	AFL		TSN:0			5694		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
343101	COMPUTER:NO. 1 FLIGHT DIRECTOR COMPUTER								
	PN	MOS		TSN:0				23-OCT-1978	
34.250	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
343111	AMPLIFIER:NO. 1 INSTRUMENT AMPLIFIER								
	501-1115-01	MOS		TSR:0				21-MAY-1999	
34.260	1407	HRS/MSC	O/C	TSR:0					
	REF: GENERIC NO REF	AFL		TSR:0					
343121	INDICATOR:NO. 1 FLIGHT DIRECTOR INDICATOR								
	622-0836-003	MOS		TSR:0				31-AUG-2007	
34.240	1847	HRS/MSC	O/C	TSR:0			10509.9		
	REF: AMM 34-23-00	AFL		TSR:0			8839		
343131	CONTROL:NO. 1 FLIGHT DIRECTOR CONTROL								
	PN	MOS		TSN:0				23-OCT-1978	
34.310	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
343141	COUPLER:NO. 1 MODE COUPLER								
	PN	MOS		TSN:0				23-OCT-1978	
34.270	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
343151	SENSOR:NO. 1 RATE OF TURN SENSOR								
	PN	MOS		TSN:0				23-OCT-1978	
34.280	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
343161	COMPUTER:PRIMARY MODE COMPUTER								
	PN	MOS		TSN:0				23-OCT-1978	
34.540	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
343166	SELECTOR:PRIMARY MODE SELECTOR								
	PN	MOS		TSN:0				23-OCT-1978	
34.540	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
343171	CONTROL:PRIMARY ALTITUDE CONTROL								
	PN	MOS		TSN:0				23-OCT-1978	
34.560	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
343176	COMPUTER:SECONDARY MODE COMPUTER								
	PN	MOS		TSN:0				23-OCT-1978	
34.550	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
343181	SELECTOR:SECONDARY MODE SELECTOR								
	PN	MOS		TSN:0				23-OCT-1978	
34.550	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
343186	CONTROL:SECONDARY ALTITUDE CONTROL								
	PN	MOS		TSN:0				23-OCT-1978	
34.560	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
343601	COMPUTER:NO. 2 FLIGHT DIRECTOR COMPUTER								
	PN	MOS		TSN:0				23-OCT-1978	
34.250	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
343611	AMPLIFIER:NO. 2 INSTRUMENT AMPLIFIER								
	PN	MOS		TSN:0				23-OCT-1978	
34.260	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
343621	INDICATOR:NO. 2 FLIGHT DIRECTOR INDICATOR								
	5-4000-08	MOS		TSO:0				10-JAN-2005	
34.240	1290	HRS/MSC	O/C	TSO:0			10438.3		
	REF: AMM 34-23-00	AFL		TSO:0			8767		
343631	CONTROL:NO. 2 FLIGHT DIRECTOR CONTROL								
	PN	MOS		TSN:0				23-OCT-1978	
34.310	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
343641	COUPLER:NO. 2 MODE COUPLER								
	PN	MOS		TSN:0				23-OCT-1978	
34.270	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
343651	SENSOR:NO. 2 RATE OF TURN SENSOR								
	PN	MOS		TSN:0				23-OCT-1978	
34.280	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
344001	ALTIMETER-STANDBY:ALTIMETER-STANDBY								
	16650-1142	MOS		TSR:0				08-FEB-2008	
	172373B	HRS/MSC	O/C	TSR:0			10630.2		
	REF:	AFL		TSR:0			8930		
344002	ALTIMETER-STANDBY:TEST ALTIMETER-STANDBY (FAR 91.411)								
	PKG 2	MOS	24					28-MAY-2009	<b>MANDATORY</b>
		HRS/MSC						10838.5	449 d
	REF: See Workcard	AFL					9102		
344007	UNIT:AIU - ANALOG INTERFACE UNIT								
	9B-81040-1	MOS		TSN:0				14-APR-2005	
	41895	HRS/MSC	O/C	TSN:0			10441		
	REF:	AFL		TSN:0			8769		
344101	RECEIVER:NO. 1 NAVIGATION RECEIVER								
	PN	MOS						15-SEP-1995	
34.290	SN-UNKNOWN	HRS/MSC	O/C				6434.5		
	REF: AMM 34-51-01	AFL							
344111	CONTROL:NO. 1 NAVIGATION CONTROL								
	PN	MOS						15-SEP-1995	
34.300	SN-UNKNOWN	HRS/MSC	O/C				6434.5		
	REF: GENERIC NO REF	AFL							
344131	RECEIVER:NO. 2 NAVIGATION RECEIVER								
	PN	MOS		TSN:0				23-OCT-1978	
34.290	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-51-01	AFL		TSN:0			0		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
344141	CONTROL:NO. 2 NAVIGATION CONTROL								
	PN	MOS		TSN:0				23-OCT-1978	
34.300	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
344142	PROCESSOR:TCAS (TPU-67A) PROCESSOR								
	PN	MOS		TSN:0				23-OCT-1978	
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
344143	PROCESSOR:TCAS (TTR-4000) PROCESSOR								
	PN	MOS		TSN:0				23-OCT-1978	
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
344151	COMPARATOR:MONITOR WARNING COMPARATOR								
	PN	MOS		TSN:0				23-OCT-1978	
34.580	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
344156	INDICATOR:COMPARATOR CONTROL INDICATOR								
	PN	MOS		TSN:0				23-OCT-1978	
34.580	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
344161	ANTENNA:PRIMARY GLIDESLOPE ANTENNA								
	PN	MOS		TSN:0				23-OCT-1978	
34.420	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-30-01	AFL		TSN:0			0		
344166	ANTENNA:SECONDARY GLIDESLOPE ANTENNA								
	PN	MOS		TSN:0				23-OCT-1978	
34.420	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-30-01	AFL		TSN:0			0		
344171	ANTENNA:NO. 1 NAVIGATION ANTENNA								
	PN	MOS		TSN:0				23-OCT-1978	
34.430	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-51-02	AFL		TSN:0			0		
344176	ANTENNA:NO. 2 NAVIGATION ANTENNA								
	PN	MOS		TSN:0				23-OCT-1978	
34.430	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-51-02	AFL		TSN:0			0		
344179	TRANSCEIVER:MARKER BEACON TRANSCEIVER								
	PN	MOS		TSN:0				23-OCT-1978	
34.610	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
344181	ANTENNA:NO. 1 MARKER BEACON ANTENNA								
	PN	MOS		TSN:0				23-OCT-1978	
34.450	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-30-02	AFL		TSN:0			0		
344186	ANTENNA:NO. 2 MARKER BEACON ANTENNA								
	PN	MOS		TSN:0				23-OCT-1978	
34.450	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-30-02	AFL		TSN:0			0		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
344191	INDICATOR:STANDBY HORIZONTAL GYRO INDICATOR								
34.590	501-1105-04 3585 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			08-FEB-2008 10630.2 8930		
344196	INDICATOR:COURSE DEVIATION INDICATOR								
34.610	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
344201	DISPLAY:VLF DIGITAL DISPLAY								
34.510	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
344206	INDICATOR:VLF STATION INDICATOR								
34.510	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
344211	CONTROL:VLF CONTROL								
34.510	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
344216	FREQUENCY STANDARD:VLF (OEU) FREQUENCY STANDARD								
34.520	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
344221	BATTERY PACK:VLF BATTERY PACK								
34.630	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
344226	RECEIVER:VLF COMPUTER RECEIVER								
34.520	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
344231	ANTENNA:VLF ANTENNA								
34.500	10085-2 2140 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-MAR-1979 138		
344236	PRESELECT:VLF PRESELECT								
34.530	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
344241	ADAPTER:VLF ADAPTER								
34.560	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
344256	DISPLAY:SECONDARY VLF DISPLAY								
34.620	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
344261	DISPLAY:PILOT NUMERICAL VLF DISPLAY								
34.620	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
344301	ANTENNA:UPPER TCAS DIRECTIONAL ANTENNA								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
344302	PROCESSER:TCAS PROCESSER								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
344306	ANTENNA:LOWER TCAS DIRECTIONAL ANTENNA								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
344513	COMPUTER:TAWS COMPUTER								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
344515	MODULE:TAWS CONFIGURATION MODULE								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
344601	TRANSCEIVER:WEATHER RADAR TRANSCEIVER								
34.400	4000502-0101 2900 REF: AMM 34-41-01	MOS HRS/MSC AFL	O/C				12-MAY-1995 6303.7		
344611	INDICATOR:WEATHER RADAR INDICATOR								
34.400	4001291-2104 1537 REF: AMM 34-41-03	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			23-SEP-2002 9789.9 8061		
344621	ANTENNA:WEATHER RADAR ANTENNA								
34.410	PN SN-UNKNOWN REF: AMM 34-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
344626	ARRAY:PHASED ARRAY								
34.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
345005	COMPUTER:ENHANCED GROUND PROXIMITY WARNING SYSTEM COMPUTER								
	066-01197-0205 2617 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-APR-2005 10441 8769		
345010	INDICATOR:AUX GPWS/WINDSHEAR INDICATOR								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
345101	INTERROGATOR:NO. 1 DME INTERROGATOR								
	PN	MOS		TSN:0				23-OCT-1978	
34.320	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-52-01	AFL		TSN:0			0		
345111	INDICATOR:NO. 1 DME INDICATOR								
	PN	MOS		TSN:0				23-OCT-1978	
34.330	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-52-04	AFL		TSN:0			0		
345121	CONVERTER:NO. 1 DME CONVERTER								
	PN	MOS		TSN:0				23-OCT-1978	
34.340	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-52-02	AFL		TSN:0			0		
345131	ANTENNA:NO. 1 DME FORWARD ANTENNA								
	PN	MOS		TSN:0				23-OCT-1978	
34.460	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-52-03	AFL		TSN:0			0		
345301	INDICATOR:SAT/TAS INDICATOR								
	PN	MOS		TSN:0				23-OCT-1978	
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
345601	INTERROGATOR:NO. 2 DME INTERROGATOR								
	PN	MOS		TSN:0				23-OCT-1978	
34.320	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-52-01	AFL		TSN:0			0		
345611	INDICATOR:NO. 2 DME INDICATOR								
	PN	MOS		TSN:0				23-OCT-1978	
34.330	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-52-04	AFL		TSN:0			0		
345621	CONVERTER:NO. 2 DME CONVERTER								
	PN	MOS		TSN:0				23-OCT-1978	
34.340	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-52-02	AFL		TSN:0			0		
345631	ANTENNA:NO. 2 DME AFT ANTENNA								
	PN	MOS		TSN:0				23-OCT-1978	
34.460	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-52-03	AFL		TSN:0			0		
345636	CONTROL:PRIMARY DME CONTROL								
	PN	MOS		TSN:0				23-OCT-1978	
34.590	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
346021	UNIT:FMS DATA TRANSFER (DTU) UNIT								
	PN	MOS		TSN:0				23-OCT-1978	
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
346101	RECEIVER:NO. 1 ADF RECEIVER								
	622-2362-001	MOS		TSO:0				22-JAN-2008	
34.360	21377	HRS/MSC	O/C	TSO:0			10616.8		
	REF: AMM 34-53-01	AFL		TSO:0			8915		



Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
346111	CONTROL:NO. 1 ADF CONTROL								
34.370	PN SN-UNKNOWN REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
346121	ANTENNA:NO. 1 ADF SENSE ANTENNA								
34.470	PN SN-UNKNOWN REF: AMM 34-53-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
346126	ANTENNA:NO. 1 ADF LOOP ANTENNA								
34.480	PN SN-UNKNOWN REF: AMM 34-53-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
346131	INDICATOR:NO. 1 ADF INDICATOR								
34.350	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
346141	CORRECTOR:NO. 1 ADF CORRECTOR								
34.600	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
346601	RECEIVER:NO. 2 ADF RECEIVER								
34.360	PN SN-UNKNOWN REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
346611	CONTROL:NO. 2 ADF CONTROL								
34.370	PN SN-UNKNOWN REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
346621	ANTENNA:NO. 2 ADF SENSE ANTENNA								
34.470	PN SN-UNKNOWN REF: AMM 34-53-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
346626	ANTENNA:NO. 2 ADF LOOP ANTENNA								
34.480	PN SN-UNKNOWN REF: AMM 34-53-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
346631	INDICATOR:NO. 2 ADF INDICATOR								
34.350	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
346641	CORRECTOR:NO. 2 ADF CORRECTOR								
34.600	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
347101	TRANSPONDER:NO. 1 ATC TRANSPONDER								
34.380	622-1270-001 10736 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C				05-AUG-1998		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
+ 347108	TRANSPONDER:TEST NO. 1 ATC TRANSPONDER (91.413) PKG 2	MOS	24				28-MAY-2009 10838.5 9102	31-MAY-2011	MANDATORY	449 d
34.380	REF: See Workcard	AFL								
347111	TRANSPONDER:NO. 2 ATC TRANSPONDER PN	MOS		TSN:0			23-OCT-1978			
34.380	SN-UNKNOWN REF: AMM 34-55-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
+ 347118	TRANSPONDER:TEST NO. 2 ATC TRANSPONDER (91.413) PKG 2	MOS	24				28-MAY-2009 10838.5 9102	31-MAY-2011	MANDATORY	449 d
34.380	REF: See Workcard	AFL								
347121	CONTROL:TRANSPONDER CONTROL PN	MOS		TSN:0			23-OCT-1978			
34.390	SN-UNKNOWN REF: AMM 34-55-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
347131	ANTENNA:NO. 1 ATC TRANSPONDER ANTENNA PN	MOS		TSN:0			23-OCT-1978			
34.440	SN-UNKNOWN REF: AMM 34-55-03	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
347136	ANTENNA:NO. 2 ATC TRANSPONDER ANTENNA PN	MOS		TSN:0			23-OCT-1978			
34.440	SN-UNKNOWN REF: AMM 34-55-03	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
347510	ANTENNA:FORWARD GPS ANTENNA 071-1553-0200 60009	MOS		TSN:0			14-APR-2005 10441			
	REF:	AFL		TSN:0			8769			
347511	ANTENNA:AFT GPS ANTENNA PN	MOS		TSN:0			23-OCT-1978			
	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
<b>CHAPTER 35 OXYGEN</b>										
350101	DETECTOR:PILOT FLOW DETECTOR PN	MOS		TSN:0			23-OCT-1978			
35.170	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
350104	DETECTOR:COPILOT FLOW DETECTOR PN	MOS		TSN:0			23-OCT-1978			
35.170	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
350106	CYLINDER:NOSE OXYGEN CYLINDER 176000-38	MOS		TSN:0			23-OCT-1978			
35.010	43678 REF: AMM 35-20-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
350108	REGULATOR:NOSE OXYGEN CYLINDER REGULATOR									
	PN	MOS		TSN:0				23-OCT-1978		
35.010	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF: AMM 35-20-02	AFL		TSN:0				0		
+ 350111	CYLINDER:HYDROSTATIC TEST NOSE OXYGEN CYLINDER									
		MOS	60					03-MAY-2007	31-MAY-2012	815 d
35.010		HRS/MSC						10494.5		
	REF:	AFL						8822		
350121	INDICATOR:OVERBOARD DISCHARGE INDICATOR									
	PN	MOS		TSN:0				23-OCT-1978		
35.150	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF: GENERIC NO REF	AFL		TSN:0				0		
350126	SWITCH:OXYGEN ANEROID SWITCH									
	PN	MOS		TSN:0				23-OCT-1978		
35.140	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF: AMM 35-20-05	AFL		TSN:0				0		
350131	VALVE:NO. 1 LANYARD ACTUATOR VALVE									
	PN	MOS		TSN:0				23-OCT-1978		
35.120	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF: AMM 35-20-03	AFL		TSN:0				0		
350136	VALVE:NO. 2 LANYARD ACTUATOR VALVE									
	PN	MOS		TSN:0				23-OCT-1978		
35.120	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF: AMM 35-20-03	AFL		TSN:0				0		
350141	VALVE:NO. 3 LANYARD ACTUATOR VALVE									
	PN	MOS		TSN:0				23-OCT-1978		
35.120	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF: AMM 35-20-03	AFL		TSN:0				0		
350146	VALVE:NO. 4 LANYARD ACTUATOR VALVE									
	PN	MOS		TSN:0				23-OCT-1978		
35.130	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF: AMM 35-20-03	AFL		TSN:0				0		
350151	VALVE:NO.5 LANYARD ACTUATOR VALVE									
	PN	MOS		TSN:0				23-OCT-1978		
35.130	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF: AMM 35-20-03	AFL		TSN:0				0		
350601	MASK:NO. 1 PASSENGER OXYGEN (A) MASK									
	PN	MOS		TSN:0				23-OCT-1978		
35.060	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF: AMM 35-20-04	AFL		TSN:0				0		
350606	MASK:NO. 1 PASSENGER OXYGEN (B) MASK									
	PN	MOS		TSN:0				23-OCT-1978		
35.060	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF: AMM 35-20-04	AFL		TSN:0				0		
350611	MASK:NO. 1 PASSENGER OXYGEN (C) MASK									
	PN	MOS		TSN:0				23-OCT-1978		
35.060	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0		
	REF: AMM 35-20-04	AFL		TSN:0				0		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
350616	MASK:NO. 2 PASSENGER OXYGEN (A) MASK PN	MOS		TSN:0				23-OCT-1978	
35.070	SN-UNKNOWN REF: AMM 35-20-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
350621	MASK:NO. 2 PASSENGER OXYGEN (B) MASK PN	MOS		TSN:0				23-OCT-1978	
35.070	SN-UNKNOWN REF: AMM 35-20-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
350626	MASK:NO. 2 PASSENGER OXYGEN (C) MASK PN	MOS		TSN:0				23-OCT-1978	
35.070	SN-UNKNOWN REF: AMM 35-20-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
350631	MASK:NO. 3 PASSENGER OXYGEN (A) MASK PN	MOS		TSN:0				23-OCT-1978	
35.080	SN-UNKNOWN REF: AMM 35-20-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
350636	MASK:NO. 3 PASSENGER OXYGEN (B) MASK PN	MOS		TSN:0				23-OCT-1978	
35.080	SN-UNKNOWN REF: AMM 35-20-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
350641	MASK:NO. 3 PASSENGER OXYGEN (C) MASK PN	MOS		TSN:0				23-OCT-1978	
35.080	SN-UNKNOWN REF: AMM 35-20-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
350646	MASK:NO. 4 PASSENGER OXYGEN (A) MASK PN	MOS		TSN:0				23-OCT-1978	
35.090	SN-UNKNOWN REF: AMM 35-20-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
350651	MASK:NO. 4 PASSENGER OXYGEN (B) MASK PN	MOS		TSN:0				23-OCT-1978	
35.090	SN-UNKNOWN REF: AMM 35-20-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
350656	MASK:NO. 4 PASSENGER OXYGEN (C) MASK PN	MOS		TSN:0				23-OCT-1978	
35.090	SN-UNKNOWN REF: AMM 35-20-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
350661	MASK:NO. 5 PASSENGER OXYGEN (A) MASK PN	MOS		TSN:0				23-OCT-1978	
35.100	SN-UNKNOWN REF: AMM 35-20-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
350666	MASK:NO. 5 PASSENGER OXYGEN (B) MASK PN	MOS		TSN:0				23-OCT-1978	
35.100	SN-UNKNOWN REF: AMM 35-20-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
350671	MASK:NO. 5 PASSENGER OXYGEN (C) MASK PN	MOS		TSN:0				23-OCT-1978	
35.100	SN-UNKNOWN REF: AMM 35-20-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING	
								NEXT DUE ACTUAL	MAX LIMIT		
WORKCARD	PART#/PKG SERIAL #										
351101	MASK:PILOT OXYGEN MASK 174145-02 / 6600214-4	MOS	72	TSO:2			03-JAN-2008			OVERHAUL	1363 d
35.110	1185 REF: AMM 35-10-01	HRS/MSC AFL		TSO:0 TSO:0			10603.6 8906		30-NOV-2013		
351106	MASK:COPILOT OXYGEN MASK MC10-15-01	MOS	72	TSO:1			07-MAR-2007			OVERHAUL	1088 d
35.110	33826 REF: AMM 35-10-01	HRS/MSC AFL		TSO:0 TSO:0			10485.1 8814		28-FEB-2013		
351601	GAUGE:OXYGEN PRESSURE GAUGE PN	MOS		TSN:0			23-OCT-1978				
35.150	SN-UNKNOWN REF: AMM 35-00-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0				
351606	VALVE:MANUAL ANEROID BYPASS VALVE PN	MOS		TSN:0			23-OCT-1978				
35.150	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0				
351611	VALVE:OXYGEN SOLENOID VALVE 170551	MOS		TSN:0			19-AUG-1991				
35.160	SN-UNKNOWN REF: AMM 35-00-02	HRS/MSC AFL	O/C	TSN:0 TSN:0							
351616	VALVE:MANUAL PASSENGER OXYGEN VALVE PN	MOS		TSN:0			23-OCT-1978				
35.160	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0				
<b>CHAPTER 36 PNEUMATIC</b>											
360101	VALVE:LEFT BLEED AIR SHUTOFF / MOD VALVE 6600202-1	MOS		TSR:0			16-FEB-1990				
36.010	P-1120 REF: AMM 36-10-01	HRS/MSC AFL	O/C	TSR:0 TSR:0			5069.5 4119				
360106	VALVE:RIGHT BLEED AIR SHUTOFF / MOD VALVE 6600202-1	MOS		TSR:0			16-FEB-1990				
36.010	P-675 REF: AMM 36-10-01	HRS/MSC AFL	O/C	TSR:0 TSR:0			5069.5 4119				
360111	SWITCH:LEFT BLEED AIR PRESSURE SWITCH PN	MOS		TSN:0			23-OCT-1978				
36.020	SN-UNKNOWN REF: AMM 36-20-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0				
360116	SWITCH:RIGHT BLEED AIR PRESSURE SWITCH PN	MOS		TSN:0			23-OCT-1978				
36.020	SN-UNKNOWN REF: AMM 36-20-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0				
360121	THERMOSWITCH:LEFT PNEUMATIC SYSTEM THERMOSWITCH PN	MOS		TSN:0			23-OCT-1978				
36.030	SN-UNKNOWN REF: AMM 36-20-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0				

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
360126	THERMOSWITCH:RIGHT PNEUMATIC SYSTEM THERMOSWITCH								
36.030	PN SN-UNKNOWN REF: AMM 36-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
360131	VALVE:LEFT PNEUMATIC 2 INCH CHECK VALVE								
36.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
360136	VALVE:RIGHT PNEUMATIC 2 INCH CHECK VALVE								
36.040	3213798-1-1 B231 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			23-SEP-2002 9789.9 8061		
361606	BOTTLE:EMERGENCY AIR BOTTLE								<b>LIFE LIMIT</b>
36.050	23700146 1085 REF: AMM 36-15-01	MOS HRS/MSC AFL	480	TSN:36 TSR:0 TSR:0 TSR:0			10-SEP-2007 10509.9 8839	<b>30-SEP-2044 M</b>	12625 d
361608	INDICATOR:EMERGENCY AIR INDICATOR								
36.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
+ 361616	BOTTLE:HYDROSTATIC TEST EMERGENCY AIR BOTTLE								
36.050		MOS HRS/MSC AFL	72				30-SEP-2004	<b>30-SEP-2010</b>	206 d
+ 361618	BOTTLE:INSPECT EMERGENCY AIR BOTTLE								
36.050		MOS HRS/MSC AFL	72				30-SEP-2004	<b>30-SEP-2010</b>	206 d
+ 361620	BOTTLE:XRAY EMERGENCY AIR BOTTLE								
36.050		MOS HRS/MSC AFL	72				30-SEP-2004	<b>30-SEP-2010</b>	206 d
5-10-29-P3610045-L	INSPECT HIGH PRESSURE BLEED AIR HOSE AND GASKET (LOCATED ON AFT TOP OF ENGINE) FOR LEAKS.								
		MOS HRS/MSC AFL	MPI				17-FEB-2010 10956.5 9224		
5-10-29-P3610045-R	INSPECT HIGH PRESSURE BLEED AIR HOSE AND GASKET (LOCATED ON AFT TOP OF ENGINE) FOR LEAKS.								
		MOS HRS/MSC AFL	MPI				17-FEB-2010 10956.5 9224		
<b>CHAPTER 52 DOORS</b>									
520101	DOOR ASSEMBLY:CABIN LOWER DOOR ASSEMBLY								
52.010	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
520111	DOOR ASSEMBLY:CABIN UPPER DOOR ASSEMBLY									
52.010	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
520121	ACTUATOR:CABIN DOOR LOCK ACTUATOR									
52.010	PN SN-UNKNOWN REF: AMM 52-11-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
520126	LATCH:CABIN DOOR HINGE LATCH									
52.020	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
520141	CABLE:CABIN ENTRANCE DOOR FORWARD CABLE									
52.020	2411660-18 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-DEC-1999 8707.5 7131			
520146	CABLE:CABIN ENTRANCE DOOR AFT CABLE									
52.020	2411660-18 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-SEP-2009 10889.4 9150			
520151	DOOR:EMERGENCY DOOR									
52.030	PN SN-UNKNOWN REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
520166	REPLACE UPPER * DOOR MECHANISM HANDLE SHAFT BOLT (36 INCH DOOR) (IRN E5210091)								N/A BY SERIAL NUMBER	
52.040	MOS HRS/MSC REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				23-OCT-1978 0 0			
+ 521061	VISUALLY INSPECT EXTERIOR LOWER CABIN STRUCTURE, FUSELAGE DOOR CUT OUT FRAMING MEMBERS, AND HINGE AREA FOR EVIDENCE OF CORROSION (IRN L5210025)									
52.080	MOS HRS/MSC REF: AMM 5-10-00	MOS HRS/MSC AFL	24 +14d/-14d				29-APR-2009 10810 9080	30-APR-2011	13-MAY-2011	418 d (+13)
522032	WINDOW:ASSEMBLY, EMERGENCY EXIT/BAGGAGE DOOR WINDOW									
	6600115-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-JAN-1997 7187.4 5919			
522032A	WINDOW:PRISM CHECK ASSEMBLY, EMERGENCY EXIT/BAGGAGE DOOR WINDOW 05-10-29-E5620006 OR M5600009									
	MOS HRS/MSC REF:	MOS HRS/MSC AFL	C/C				19-NOV-2004 10438.3 8767			
528001	DOOR ASSEMBLY:LEFT INBOARD MAIN LANDING GEAR DOOR ASSEMBLY									
52.050	PN SN-UNKNOWN REF: AMM 52-80-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
528004	DOOR ASSEMBLY:RIGHT INBOARD MAIN LANDING GEAR DOOR ASSEMBLY									
52.050	PN SN-UNKNOWN REF: AMM 52-80-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
528007	DOOR ASSEMBLY:LEFT MAIN LANDING GEAR OUTBOARD DOOR ASSEMBLY									
	PN	MOS		TSN:0			23-OCT-1978			
52.060	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 52-80-00	AFL		TSN:0			0			
528010	DOOR ASSEMBLY:RIGHT MAIN LANDING GEAR OUTBOARD DOOR ASSEMBLY									
	PN	MOS		TSN:0			23-OCT-1978			
52.060	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 52-80-00	AFL		TSN:0			0			
528013	DOOR:LEFT NOSE LANDING GEAR DOOR									
	PN	MOS		TSN:0			23-OCT-1978			
52.070	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 52-81-00	AFL		TSN:0			0			
528016	DOOR:RIGHT NOSE LANDING GEAR DOOR									
	PN	MOS		TSN:0			23-OCT-1978			
52.070	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 52-81-00	AFL		TSN:0			0			
<b>CHAPTER 53 FUSELAGE</b>										
532601	RADOME:RADOME									
	2411008-6	MOS		TSR:0			10-NOV-2003			
53.010	326S	HRS/MSC	O/C	TSR:0						
	REF: AMM 53-50-01	AFL		TSR:0						
532606	BEAM ASSEMBLY:CENTER KEEL BEAM ASSEMBLY									
	PN	MOS		TSN:0			23-OCT-1978			
53.020	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: GENERIC NO REF	AFL		TSN:0			0			
535010	REPLACE ** KEELBEAM ATTACHMENT BOLTS (IRN E5322000)								<b>LIFE LIMIT</b>	
		MOS	144	+14d/-14d			16-APR-1999	<b>30-APR-2011</b>	30-APR-2011	418 d
53.030		HRS/MSC					8396.5			
	REF: GENERIC NO REF	AFL	6000	+25/-25			6845	<b>12845</b>	12870	3610 (+25)
+ 535060	INSPECT AFT PRESSURE BULKHEAD AT FRAME 22, F.S.421.42 FOR CORROSION (LEARJET 35 ONLY)(IRN J5320006)									
		MOS	144				23-SEP-2002	<b>30-SEP-2014</b>		1667 d
53.070		HRS/MSC					9789.9			
	REF: AMM 53-20-02	AFL	6000				8061	<b>14061</b>		4826
<b>CHAPTER 54 NACELLES/PYLONS</b>										
5-10-29-J5450043-L	INSPECT PYLON / ENGINE BEAM STRUCTURE									
		MOS					17-FEB-2010			
		HRS/MSC	MPI				10956.5			
	REF:	AFL					9224			
5-10-29-J5450043-R	INSPECT PYLON / ENGINE BEAM STRUCTURE									
		MOS					17-FEB-2010			
		HRS/MSC	MPI				10956.5			
	REF:	AFL					9224			
5-10-29-J5450045-L	INSPECT PYLON / ENGINE BEAM SUPPORT STRUCTURE									
		MOS					17-FEB-2010			
		HRS/MSC	MPI				10956.5			
	REF:	AFL					9224			



Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT		
5-10-29-J5450045-R	INSPECT PYLON / ENGINE BEAM SUPPORT STRUCTURE	MOS					17-FEB-2010			
	REF:	HRS/MSC MPI AFL					10956.5 9224			
+ 540116	EDDY CURRENT INSPECT NO. 1 ENGINE BEAM SUPPORT FITTINGS	MOS	144	+14d/-14d			15-JAN-2002	<b>31-JAN-2014</b>	31-JAN-2014	1425 d
54.030	REF: GENERIC NO REF	HRS/MSC AFL	6000	+25/-25			9620.6 7857	<b>13857</b>	13882	4622 (+25)
+ 540616	EDDY CURRENT INSPECT NO. 2 ENGINE BEAM SUPPORT FITTINGS	MOS	144	+14d/-14d			15-JAN-2002	<b>31-JAN-2014</b>	31-JAN-2014	1425 d
54.030	REF: GENERIC NO REF	HRS/MSC AFL	6000	+25/-25			9620.6 7857	<b>13857</b>	13882	4622 (+25)
541101	FITTING:NO. 1 ENGINE FORWARD ATTACH FITTING	MOS					23-OCT-1978			
54.010	PN SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0			
541106	FITTING:NO. 1 ENGINE AFT ATTACH FITTING	MOS					23-OCT-1978			
54.020	PN SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0			
541111	FITTING:NO. 2 ENGINE FORWARD ATTACH FITTING	MOS					23-OCT-1978			
54.010	PN SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0			
541116	FITTING:NO. 2 ENGINE AFT ATTACH FITTING	MOS					23-OCT-1978			
54.020	PN SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0			
<b>CHAPTER 55</b>		<b>STABILIZERS</b>								
555120	HINGE ASSEMBLY:HORIZONTAL STABILIZER HINGE ASSEMBLY	MOS					23-OCT-1978			
55.010	PN SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0			
<b>CHAPTER 56</b>		<b>WINDOWS</b>								
560101	WINDSHIELD:LEFT WINDSHIELD	MOS					29-SEP-2006			
56.010	PN-UNKNOWN SN-UNKNOWN REF: AMM 56-10-01	HRS/MSC AFL	O/C		TSR:0 TSR:0 TSR:0		10482.4			
+ 560103	WINDSHIELD:INSPECT LEFT WINDSHIELD (IRN G5610023).	MOS					07-DEC-2009			
56.010	REF: NDT PART 4 GENERAL / 56-10-01	HRS/MSC AFL	1200/-				10928.4 9202	<b>12128.4</b>		1163.4
560106	WINDSHIELD:RIGHT WINDSHIELD	MOS					05-DEC-2006			
56.015	PN-UNKNOWN SN-UNKNOWN REF: AMM 56-10-01	HRS/MSC AFL	O/C		TSR:0 TSR:0 TSR:0					

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
+ 560108	WINDSHIELD:INSPECT RIGHT WINDSHIELD (IRN G5610023).	MOS					07-DEC-2009		
56.015	REF: See Workcard	HRS/MSC AFL	1200				10928.4 9202	12128.4	1163.4
560601	WINDOW:LEFT NO.1 CABIN WINDOW PAS66000115-10	MOS		TSN:0			23-SEP-2002		
56.020	0931 REF: AMM 56-20-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			9789.9 8061		
560602	WINDOW:OPTICAL PRISM INSPECTION LEFT NO.1 CABIN WINDOW (IRN M5600009).	MOS					23-SEP-2002		
56.020	REF: NDT PART 4 GENERAL / 56-30-01	HRS/MSC AFL	C/C						
560606	WINDOW:LEFT NO.2 CABIN WINDOW PAS66000115-10	MOS		TSN:0			23-SEP-2002		
56.030	0924 REF: AMM 56-20-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			9789.9 8061		
560607	WINDOW:OPTICAL PRISM INSPECTION LEFT NO.2 CABIN WINDOW (IRN M5600009).	MOS					23-SEP-2002		
56.030	REF: NDT PART 4 GENERAL / 56-30-01	HRS/MSC AFL	C/C						
560611	WINDOW:LEFT NO.3 CABIN WINDOW PAS66000115-10	MOS		TSN:0			23-SEP-2002		
56.040	0927 REF: AMM 56-20-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			9789.9 8061		
560612	WINDOW:OPTICAL PRISM INSPECTION LEFT NO.3 CABIN WINDOW (IRN M5600009).	MOS					23-SEP-2002		
56.040	REF: NDT PART 4 GENERAL / 56-30-01	HRS/MSC AFL	C/C						
560616	WINDOW:LEFT NO.4 CABIN WINDOW PAS66000115-10	MOS		TSN:0			23-SEP-2002		
56.050	0923 REF: AMM 56-20-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			9789.9 8061		
560617	WINDOW:OPTICAL PRISM INSPECTION LEFT NO.4 CABIN WINDOW (IRN M5600009).	MOS					23-SEP-2002		
56.050	REF: NDT PART 4 GENERAL / 56-30-01	HRS/MSC AFL	C/C						
560621	WINDOW:RIGHT NO.1 CABIN WINDOW PN	MOS		TSN:0			23-OCT-1978		
56.020	SN-UNKNOWN REF: AMM 56-20-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
560622	WINDOW:OPTICAL PRISM INSPECTION RIGHT NO.1 CABIN WINDOW (IRN M5600009).	MOS					23-OCT-1978		
56.020	REF: NDT PART 4 GENERAL / 56-30-01	HRS/MSC AFL	C/C				0 0		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
560626	WINDOW:RIGHT NO.2 CABIN WINDOW PAS66000115-10	MOS		TSN:0			23-SEP-2002		
56.030	0923 REF: AMM 56-20-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			9789.9 8061		
560627	WINDOW:OPTICAL PRISM INSPECTION RIGHT NO.2 CABIN WINDOW (IRN M5600009).	MOS					23-SEP-2002		
56.030	REF: NDT PART 4 GENERAL / 56-30-01	HRS/MSC AFL	C/C						
560631	WINDOW:RIGHT NO.3 CABIN WINDOW PN	MOS		TSN:0			23-OCT-1978		
56.040	SN-UNKNOWN REF: AMM 56-20-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
560632	WINDOW:OPTICAL PRISM INSPECTION RIGHT NO.3 CABIN WINDOW (IRN M5600009).	MOS					23-OCT-1978		
56.040	REF: NDT PART 4 GENERAL / 56-30-01	HRS/MSC AFL	C/C				0 0		
560636	WINDOW:RIGHT NO.4 CABIN WINDOW 6600115-10	MOS		TSN:0			18-APR-1997		
56.050	SN-UNKNOWN REF: AMM 56-20-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			7283.8 5992		
560637	WINDOW:OPTICAL PRISM INSPECTION RIGHT NO.4 CABIN WINDOW (IRN M5600009).	MOS					18-APR-1997		
56.050	REF: NDT PART 4 GENERAL / 56-30-01	HRS/MSC AFL	C/C						
<b>CHAPTER 57 WINGS</b>									
+ 571021	INSPECT LEFT WING FLAPPER VALVE FOR FREEDOM OF MOVEMENT, SECURITY, AND GENERAL CONDITION. ADJACENT STRUCTURE FOR CORROSION, FATIGUE CRACKS, LOOSE OR MISSING FASTENERS AND BACTERIAL GROWTH (IRN L2812020)								
57.010		MOS	24	+14d/-14d			29-APR-2009 10810 9080	<b>30-APR-2011</b>	13-MAY-2011 418 d (+13)
+ 571022	INSPECT RIGHT WING FLAPPER VALVE FOR FREEDOM OF MOVEMENT, SECURITY, AND GENERAL CONDITION. ADJACENT STRUCTURE FOR CORROSION, FATIGUE CRACKS, LOOSE OR MISSING FASTENERS AND BACTERIAL GROWTH (IRN L2812020)								
57.010		MOS	24	+14d/-14d			29-APR-2009 10810 9080	<b>30-APR-2011</b>	13-MAY-2011 418 d (+13)
+ 571031	INSPECT LEFT WING INBOARD DRY BAY OF WING ADJACENT TO THE FUSELAGE AND FORWARD OF SPAR 2 FOR CRACKS, PRIMER CONDITION, AND CORROSION (IRN L5710035)								
57.010		MOS	24	+14d/-14d			29-APR-2009 10810 9080	<b>30-APR-2011</b>	13-MAY-2011 418 d (+13)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965 Landings: 9235

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT		
+ 571032	INSPECT RIGHT WING INBOARD DRY BAY OF WING ADJACENT TO THE FUSELAGE AND FORWARD OF SPAR 2 FOR CRACKS, PRIMER CONDITION, AND CORROSION (IRN L5710035)	MOS	24	+14d/-14d			29-APR-2009	<b>30-APR-2011</b>	13-MAY-2011	418 d (+13)
57.010	REF: GENERIC NO REF	HRS/MSC AFL					10810 9080			
<b>CHAPTER 71 POWER PLANT</b>										
5-10-29-E7120024-L	CHECK ENGINE MOUNT CASTINGS FOR CORROSION AND CRACKS. CHECK ENGINE MOUNT ATTACHMENTS FOR SECURITY AND GENERAL CONDITION.	MOS					17-FEB-2010			
	REF:	HRS/MSC MPI AFL					10956.5 9224			
5-10-29-E7120024-R	CHECK ENGINE MOUNT CASTINGS FOR CORROSION AND CRACKS. CHECK ENGINE MOUNT ATTACHMENTS FOR SECURITY AND GENERAL CONDITION.	MOS					17-FEB-2010			
	REF:	HRS/MSC MPI AFL					10956.5 9224			
5-10-29-Q7120063-L	PERFORM INSPECTION / CHECK OF FORWARD AND AFT ENGINE MOUNT ISOLATORS AND ASSOCIATED PARTS.	MOS					17-FEB-2010			
	REF: AMM 71-20-00	HRS/MSC MPI AFL					10956.5 9224			
5-10-29-Q7120063-R	PERFORM INSPECTION / CHECK OF FORWARD AND AFT ENGINE MOUNT ISOLATORS AND ASSOCIATED PARTS.	MOS					17-FEB-2010			
	REF: AMM 71-20-00	HRS/MSC MPI AFL					10956.5 9224			
5-10-29-Q7120067-L	PERFORM FLUORSECENT PENTRANT INSPECTION OF AFT ENGINE BOLT (P/N 2652002)	MOS					17-FEB-2010			
	REF:	HRS/MSC MPI AFL					10956.5 9224			
5-10-29-Q7120067-R	PERFORM FLUORSECENT PENTRANT INSPECTION OF AFT ENGINE BOLT (P/N 2652002)	MOS					17-FEB-2010			
	REF:	HRS/MSC MPI AFL					10956.5 9224			
5-10-29-Q7120072-L	PERFORM MAGNETIC PARTICLE INSPECTION ON AFT ENGINE ATTACH BOLT (P/N 2652002-3 AND 801)	MOS					17-FEB-2010			
	REF:	HRS/MSC MPI AFL					10956.5 9224			
5-10-29-Q7120072-R	PERFORM MAGNETIC PARTICLE INSPECTION ON AFT ENGINE ATTACH BOLT (P/N 2652002-3 AND 801)	MOS					17-FEB-2010			
	REF:	HRS/MSC MPI AFL					10956.5 9224			
+ 710121	PERFORM NO. 1 ENGINE AIRFRAME INSPECTION ITEMS DURING SCHEDULED MAJOR ENGINE INSPECTION / UNSCHEDULED ENGINE CHANGE	MOS					17-FEB-2010			
71.180	REF: AMM 5-10-29	HRS/MSC AFL	1400	+100			10956.5 9224	<b>12356.5</b>	12456.5	1391.5 (+100)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	MAX LIMIT	
+ 713620	PERFORM NO. 2 ENGINE AIRFRAME INSPECTION ITEMS DURING SCHEDULED MAJOR ENGINE INSPECTION / UNSCHEDULED ENGINE CHANGE									
71.190		MOS HRS/MSC AFL	1400 +100				17-FEB-2010 10956.5 9224	12356.5	12456.5	1391.5 (+100)
717101	MOUNT:NO. 1 ENGINE FORWARD MOUNT									
71.020		MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
717111	MOUNT:REPLACE NO. 1 ENGINE FORWARD MOUNT * FORWARD ENGINE ATTACH BOLTS (2651026) (IRN E7120038)									
71.020		MOS HRS/MSC AFL	20000				23-OCT-1978 0 0	20000 M		9035
717116	MOUNT:NO. 1 ENGINE AFT MOUNT									
71.020		MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
717126	REPLACE NO. 1 ENGINE * AFT ATTACH BOLTS (2652002, 2651027) (IRN E7120039)									
71.020		MOS HRS/MSC AFL	20000				23-OCT-1978 0 0	20000		9035
717127	REPLACE NO. 1 ENGINE AFT SHOCK MOUNT ATTACH BOLTS (NAS335CP23) (IRN E7120041)									
71.060		MOS HRS/MSC AFL	20000				23-OCT-1978 0 0	20000 M		9035
717131	SHOCK MOUNT:NO. 1 ENGINE FORWARD LOWER SHOCK MOUNT									
71.040		MOS HRS/MSC AFL	O/C	TSN:4083.3			08-JAN-1999 8233.8 6723			
717133	SHOCK MOUNT:REPLACE NO. 1 ENGINE FORWARD LOWER SHOCK MOUNT * FORWARD UPPER AND LOWER SHOCK SUPPORT BOLTS (6600187,NAS1307-3H) (IRN E7120040)									
71.040		MOS HRS/MSC AFL	20000				23-OCT-1978 0 0	20000		9035
717136	SHOCK MOUNT:NO. 1 ENGINE FORWARD UPPER SHOCK MOUNT									
71.045		MOS HRS/MSC AFL	O/C	TSN:4083.3			08-JAN-1999 8233.8 6723			
717138	SHOCK MOUNT:REPLACE NO. 1 ENGINE FORWARD UPPER SHOCK MOUNT * FORWARD UPPER AND LOWER SHOCK SUPPORT BOLTS (6600187,NAS1307-3H) (IRN E7120040)									
71.045		MOS HRS/MSC AFL	20000				23-OCT-1978 0 0	20000		9035
717139	SHOCK MOUNT:REPLACE NO. 1 ENGINE FORWARD LOWER SHOCK MOUNT ** FORWARD SHOCK MOUNT MOUNTING ASSEMBLY (LM-833-1) (IRN L7120065)									
71.070		MOS HRS/MSC AFL	8400 +400				14-OCT-1988 4205.5 3398	12605.5	13005.5	1640.5 (+400)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
717140	SHOCK MOUNT:REPLACE NO. 1 ENGINE FORWARD LOWER SHOCK MOUNT ** FORWARD SHOCK MOUNT HOUSING (LM-833-2) (IRN L7120066)									LIFE LIMIT
71.070	REF: AMM 71-20-00	MOS HRS/MSC AFL	8400 +400				14-OCT-1988 4205.5 3398	12605.5	M 13005.5	1640.5 (+400)
717141	SHOCK MOUNT:REPLACE NO. 1 ENGINE FORWARD LOWER SHOCK MOUNT ** COVER (LM-833-3) (IRN K7120036)									SCRAP
71.130	REF: AMM 71-20-00	MOS HRS/MSC AFL	4200 +200				15-JAN-2002 9620.6 7857	13820.6	14020.6	2855.6 (+200)
717142	SHOCK MOUNT:REPLACE NO. 1 ENGINE FORWARD LOWER SHOCK MOUNT ** FORWARD SHOCK MOUNT BOLTS (NAS1304-1H) (IRN K7120064)									SCRAP
71.130	REF: AMM 71-20-00	MOS HRS/MSC AFL	4200 +200				15-JAN-2002 9620.6 7857	13820.6	14020.6	2855.6 (+200)
717143	SHOCK MOUNT:REPLACE NO. 1 ENGINE FORWARD UPPER SHOCK MOUNT ** FORWARD SHOCK MOUNT MOUNTING ASSEMBLY (LM-833-1) (IRN L7120065)									SCRAP
71.080	REF: AMM 71-20-00	MOS HRS/MSC AFL	8400 +400				08-JAN-1999 8233.8 6723	16633.8	M 17033.8	5668.8 (+400)
717144	SHOCK MOUNT:REPLACE NO. 1 ENGINE FORWARD UPPER SHOCK MOUNT ** FORWARD SHOCK MOUNT HOUSING (LM-833-2) (IRN L7120066)									LIFE LIMIT
71.080	REF: AMM 71-20-00	MOS HRS/MSC AFL	8400 +400				09-JAN-1999 8233.8 6723	16633.8	M 17033.8	5668.8 (+400)
717145	SHOCK MOUNT:REPLACE NO. 1 ENGINE FORWARD UPPER SHOCK MOUNT ** COVER (LM-833-3) (IRN K7120036)									SCRAP
71.130	REF: AMM 71-20-00	MOS HRS/MSC AFL	4200 +200				15-JAN-2002 9620.6 7857	13820.6	14020.6	2855.6 (+200)
717146	SHOCK MOUNT:REPLACE NO. 1 ENGINE FORWARD UPPER SHOCK MOUNT ** FORWARD SHOCK MOUNT BOLTS (NAS1304-1H) (IRN K7120064)									SCRAP
71.130	REF: AMM 71-20-00	MOS HRS/MSC AFL	4200 +200				15-JAN-2002 9620.6 7857	13820.6	14020.6	2855.6 (+200)
717149	SHOCK MOUNT:REPLACE NO. 2 ENGINE FORWARD LOWER SHOCK MOUNT ** FORWARD SHOCK MOUNT MOUNTING ASSEMBLY (LM-833-1) (IRN L7120065)									SCRAP
71.090	REF: AMM 71-20-00	MOS HRS/MSC AFL	8400 +400				28-APR-1988 3999.6 3138	12399.6	12799.6	1434.6 (+400)
717150	SHOCK MOUNT:REPLACE NO. 2 ENGINE FORWARD LOWER SHOCK MOUNT ** FORWARD SHOCK MOUNT HOUSING (LM-833-2) (IRN L7120066)									LIFE LIMIT
71.090	REF: AMM 71-20-00	MOS HRS/MSC AFL	8400 +400				15-JAN-2002 9620.6 7857	18020.6	18420.6	7055.6 (+400)
717151	SHOCK MOUNT:REPLACE NO. 2 ENGINE FORWARD LOWER SHOCK MOUNT ** COVER (LM-833-3) (IRN K7120036)									SCRAP
71.140	REF: AMM 71-20-00	MOS HRS/MSC AFL	4200 +200				08-JAN-1999 8233.8 6723	12433.8	M 12633.8	1468.8 (+200)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								NEXT DUE ACTUAL	NEXT DUE MAX LIMIT	
WORKCARD	PART#/PKG SERIAL #									
717152	SHOCK MOUNT:REPLACE NO. 2 ENGINE FORWARD LOWER SHOCK MOUNT ** FORWARD SHOCK MOUNT BOLTS (NAS1304-1H) (IRN K7120064)									SCRAP
71.140	REF: AMM 71-20-00	MOS HRS/MSC AFL	4200 +200				15-JAN-2002 9620.6 7857	13820.6	14020.6	2855.6 (+200)
717153	SHOCK MOUNT:REPLACE NO. 2 ENGINE FORWARD UPPER SHOCK MOUNT ** FORWARD SHOCK MOUNT MOUNTING ASSEMBLY (LM-833-1) (IRN L7120065)									SCRAP
71.100	REF: AMM 71-20-00	MOS HRS/MSC AFL	8400 +400				28-APR-1988 3999.6 3138	12399.6	12799.6	1434.6 (+400)
717154	SHOCK MOUNT:REPLACE NO. 2 ENGINE FORWARD UPPER SHOCK MOUNT ** FORWARD SHOCK MOUNT HOUSING (LM-833-2) (IRN L7120066)									LIFE LIMIT
71.100	REF: AMM 71-20-00	MOS HRS/MSC AFL	8400 +400				15-JAN-2002 9620.6 7857	18020.6	18420.6	7055.6 (+400)
717155	SHOCK MOUNT:REPLACE NO. 2 ENGINE FORWARD UPPER SHOCK MOUNT ** COVER (LM-833-3) (IRN K7120036)									SCRAP
71.140	REF: AMM 71-20-00	MOS HRS/MSC AFL	4200 +200				15-JAN-2002 9620.6 7857	13820.6	14020.6	2855.6 (+200)
717156	SHOCK MOUNT:REPLACE NO. 2 ENGINE FORWARD UPPER SHOCK MOUNT ** FORWARD SHOCK MOUNT BOLTS (NAS1304-1H) (IRN K7120064)									SCRAP
71.140	REF: AMM 71-20-00	MOS HRS/MSC AFL	4200 +200				15-JAN-2002 9620.6 7857	13820.6	14020.6	2855.6 (+200)
+ 717161	NON DESTRUCTIVE TEST NO. 1 ENGINE MOUNT ASSEMBLIES									
71.150	REF:	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			15-JAN-2002 9620.6 7857	31-JAN-2014 13857	31-JAN-2014 13882	1425 d 4622 (+25)
717601	MOUNT:NO. 2 ENGINE FORWARD MOUNT PN SN-UNKNOWN									
71.030	REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C				23-OCT-1978 0 0			TSN:0 TSN:0 TSN:0
717611	MOUNT:REPLACE NO. 2 ENGINE FORWARD MOUNT * FORWARD ENGINE MOUNT ATTACH BOLTS (2651026) (IRN E7120038)									LIFE LIMIT
71.030	REF: AMM 71-20-00	MOS HRS/MSC AFL	20000				23-OCT-1978 0 0	20000 M		9035
717616	MOUNT:NO. 2 ENGINE AFT MOUNT 2651031-14									
71.030	REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C				01-FEB-2005 10438.7 8768			
717626	REPLACE NO. 2 ENGINE * AFT ATTACH BOLTS (2652002,2651027) (IRN E7120039)									LIFE LIMIT
71.030	REF: AMM 71-20-00	MOS HRS/MSC AFL	20000				23-OCT-1978 0 0	20000		9035
717627	REPLACE NO. 2 ENGINE AFT SHOCK MOUNT ATTACH BOLTS (NAS335CP23) (IRN E7120041)									LIFE LIMIT
71.060	REF: AMM 71-20-00	MOS HRS/MSC AFL	20000				23-OCT-1978 0 0	20000 M		9035

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
717631	SHOCK MOUNT:NO. 2 ENGINE FORWARD LOWER SHOCK MOUNT								
71.050	PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
717633	SHOCK MOUNT:REPLACE NO. 2 ENGINE FORWARD LOWER SHOCK MOUNT * FORWARD UPPER AND LOWER SHOCK SUPPORT BOLTS (6600187,NAS1307-3H) (IRN E7120040)								<b>LIFE LIMIT</b>
71.050	REF: AMM 71-20-00	MOS HRS/MSC AFL	20000				23-OCT-1978 0 0	<b>20000</b>	9035
717636	SHOCK MOUNT:NO. 2 ENGINE FORWARD UPPER SHOCK MOUNT								
71.055	PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
717638	SHOCK MOUNT:REPLACE NO. 2 ENGINE FORWARD UPPER SHOCK MOUNT * FORWARD UPPER AND LOWER SHOCK SUPPORT BOLTS (6600187,NAS1307-3H) (IRN E7120040)								<b>LIFE LIMIT</b>
71.055	REF: AMM 71-20-00	MOS HRS/MSC AFL	20000				23-OCT-1978 0 0	<b>20000</b>	9035
717641	ISOLATOR ASSEMBLY:NO. 1 ENGINE AFT ISOLATOR ASSEMBLY								<b>LIFE LIMIT</b>
71.060	6600309-3 SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	8400	+400	TSN:0 TSN:0 TSN:0		20-NOV-1998 8173.7 6672	<b>16573.7 M</b>	16973.7 5608.7 (+400)
717644	ISOLATOR ASSEMBLY:REPLACE NO. 1 ENGINE AFT ISOLATOR ASSEMBLY HOUSING (LM-833-30) (IRN L7120037)								<b>SCRAP</b>
71.110	REF: AMM 71-20-00	MOS HRS/MSC AFL	8400	+400			14-OCT-1988 4205.5 3398	<b>12605.5 M</b>	13005.5 1640.5 (+400)
717645	ISOLATOR ASSEMBLY:REPLACE NO. 1 ENGINE AFT ISOLATOR ASSEMBLY BONDING JOINT (LM-833-16) (IRN L7120037)								<b>SCRAP</b>
71.110	REF: AMM 71-20-00	MOS HRS/MSC AFL	8400	+400			27-APR-1996 6717 5523	<b>15117</b>	15517 4152 (+400)
717646	ISOLATOR ASSEMBLY:NO. 2 ENGINE AFT ISOLATOR ASSEMBLY								<b>LIFE LIMIT</b>
71.060	6600309-3 SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	8400	+400	TSN:0 TSN:0 TSN:0		20-NOV-1998 8173.7 6672	<b>16573.7 M</b>	16973.7 5608.7 (+400)
717649	ISOLATOR ASSEMBLY:REPLACE NO. 2 ENGINE AFT ISOLATOR ASSEMBLY HOUSING (LM833-30) (IRN L7120037)								<b>SCRAP</b>
71.060	REF: AMM 71-20-00	MOS HRS/MSC AFL	8400	+400			20-NOV-1998 8173.7 6672	<b>16573.7 M</b>	16973.7 5608.7 (+400)
717650	ISOLATOR ASSEMBLY:REPLACE NO. 2 ENGINE AFT ISOLATOR ASSEMBLY BONDING JOINT (LM-833-16) (IRN L7120037)								<b>SCRAP</b>
71.060	REF: AMM 71-20-00	MOS HRS/MSC AFL	8400	+400			20-NOV-1998 8173.7 6672	<b>16573.7 M</b>	16973.7 5608.7 (+400)
+ 717661	NON DESTRUCTIVE TEST NO. 2 ENGINE MOUNT ASSEMBLIES								
71.160	REF:	MOS HRS/MSC AFL	144	+14d/-14d			15-JAN-2002 9620.6 7857	<b>31-JAN-2014</b>	31-JAN-2014 1425 d 4622 (+25)



Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
WORKCARD	PART#/PKG SERIAL #									
71EN1	ENGINE:NO. 1 ENGINE 3070300-9	MOS		TSN:0			19-SEP-1978			
71.EN1	P-74621 REF:	HRS/MSC AFL	E/C	TSN:0 TSN:0			0 0			
71EN2	ENGINE:NO. 2 ENGINE 3070300-5	MOS		TSN:0			25-SEP-1978			
71.EN2	P-74622 REF:	HRS/MSC AFL	E/C	TSN:0 TSN:0			0 0			
<b>ENGINE NO. 1 Model : TFE731-2 Serial # P-74621 Part # 3070300-9</b>										
+ 710120	NO. 1 ENGINE - MAJOR PERIODIC INSPECTION	MOS					17-FEB-2010			
71.010		HRS/MSC ENC	1400	+100			10625.3 9211	(12025.3)	12356.5	12125.3 1391.5 (+100)
	REF: EMM 72-00-00									
+ 710130 (s)	NO. 1 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES	MOS					17-FEB-2010			
71.020	PKG 2	HRS/MSC ENC	300	+100			10625.3 9211			
	REF: EMM 72-00-00									
713110	NO. 1 ENGINE - COMPRESSOR WASH	MOS					17-FEB-2010			
71.030		HRS/MSC ENC	MPI				10625.3 9211			
	REF: EMM 72-00-00									
+ 714010 (s)	NO. 1 ENGINE - CHECK ENGINE ELECTRICAL WIRING AND CONNECTIONS	MOS					17-FEB-2010			
71.050	PKG 3	HRS/MSC ENC	800				10625.3 9211			
	REF: GENERIC NO REF									
+ 715010 (s)	NO. 1 ENGINE - CHECK ENGINE PLUMBING LINES AND CONNECTIONS	MOS					17-FEB-2010			
71.060	PKG 3	HRS/MSC ENC	800				10625.3 9211			
	REF: GENERIC NO REF									
<b>ENGINE NO. 2 Model : TFE731-2 Serial # P-74622 Part # 3070300-5</b>										
+ 710120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION	MOS					17-FEB-2010			
71.010		HRS/MSC ENC	1400	+100			10653.9 9031	(12053.9)	12356.5	12153.9 1391.5 (+100)
	REF: EMM 72-00-00									
+ 710130 (s)	NO. 2 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES	MOS					17-FEB-2010			
71.020	PKG 2	HRS/MSC ENC	300	+100			10653.9 9031			
	REF: EMM 72-00-00									
713110	NO. 2 ENGINE - COMPRESSOR WASH	MOS					17-FEB-2010			
71.030		HRS/MSC ENC	MPI				10653.9 9031			
	REF: EMM 72-00-00									
+ 714010 (s)	NO. 2 ENGINE - CHECK ENGINE ELECTRICAL WIRING AND CONNECTIONS	MOS					17-FEB-2010			
71.050	PKG 3	HRS/MSC ENC	800				10653.9 9031			
	REF: GENERIC NO REF									

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION	NEXT DUE	TIME REMAINING
WORKCARD	PART#/PKG SERIAL #							ACTUAL	MAX LIMIT	
+ 715010 (s)	NO. 2 ENGINE - CHECK ENGINE PLUMBING LINES AND CONNECTIONS						PKG			
71.060	PKG 3	MOS					17-FEB-2010			
	REF: GENERIC NO REF	HRS/MSC	800				10653.9			
		ENC					9031			
<b>CHAPTER 72 ENGINE</b>										
ENGINE NO. 1 Model : TFE731-2 Serial # P-74621 Part # 3070300-9										
+ 723110	NO. 1 ENGINE - INSPECT COMPRESSOR CORE									
72.010		MOS					19-DEC-1998			
	REF: GENERIC NO REF	HRS/MSC	4200	+200			7902.6	(12102.6)	12433.8	12302.6
		ENC					6587			1468.8 (+200)
724110	CASE:NO. 1 ENGINE - COMBUSTION CHAMBER PLENUM CASE									
72.020	3072443-3	MOS		TSN:0			19-SEP-1978			
	8P-13430	HRS/MSC	O/C	TSN:0			0			
	REF: GENERIC NO REF	ENC		TSN:0			0			
+ 724120	CASE:NO. 1 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE									
72.030		MOS					17-FEB-2010			
	REF: EMM 72-40-05	HRS/MSC	1400				10625.3	(12025.3)	12356.5	1391.5
		ENC					9211			
725010	DISC:NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC									LIFE LIMIT
72.040	3072070-5	MOS		TSN:0			10-JAN-2002			
	010322900337	HRS/MSC		TSN:0			9289.7			
	REF: GENERIC NO REF	ENC	4400	TSN:0			7719		12119	2897
725020	DISC:NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC									LIFE LIMIT
72.050	3072069-5	MOS		TSN:0			10-JAN-2002			
	010322901946	HRS/MSC		TSN:0			9289.7			
	REF: GENERIC NO REF	ENC	4500	TSN:0			7719		12219	2997
725030	DISC:NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC									LIFE LIMIT
72.060	3072068-3	MOS		TSN:0			10-JAN-2002			
	010322904367	HRS/MSC		TSN:0			9289.7			
	REF: GENERIC NO REF	ENC	9500	TSN:0			7719		17219	7997
725040	DISC:NO. 1 ENGINE - HIGH PRESSURE TURBINE DISC									LIFE LIMIT
72.070	3072732-2	MOS		TSN:0			23-APR-1996			
	5-23315-1756	HRS/MSC		TSN:0			6444.9			
	REF: EMM 72-50-06	ENC	5200	TSN:0			5369		10569	1347
725050	DISC:NO. 1 ENGINE - FAN DISC									LIFE LIMIT
72.080	3073563-2	MOS		TSN:0			19-DEC-1995			
	5-03229-1948	HRS/MSC		TSN:0			6259.1			
	REF: GENERIC NO REF	ENC	10000	TSN:0			5236		15236	6014
725060	DISC:NO. 1 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC									LIFE LIMIT
72.090	3072395-1	MOS		TSN:0			19-SEP-1978			
	7-12112-4288	HRS/MSC		TSN:0			0			
	REF: GENERIC NO REF	ENC	10000	TSN:0			0		10000	778
725070	DISC:NO. 1 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC									LIFE LIMIT
72.100	3072396-1	MOS		TSN:0			19-SEP-1978			
	7-12112-3131	HRS/MSC		TSN:0			0			
	REF: GENERIC NO REF	ENC	10000	TSN:0			0		10000	778

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
725080	DISC:NO. 1 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3072397-1	MOS		TSN:0					LIFE LIMIT
72.110	7-12112-4441 REF: GENERIC NO REF	HRS/MSC ENC	10000	TSN:0 TSN:0			0 0	19-SEP-1978 0	778
725090	DISC:NO. 1 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3072398-1	MOS		TSN:0					LIFE LIMIT
72.120	7-12112-1685 REF: GENERIC NO REF	HRS/MSC ENC	10000	TSN:0 TSN:0			0 0	19-SEP-1978 0	778
725091	TIE ROD:NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3073049-1	MOS		TSN:0					LIFE LIMIT
72.130	5P-6499 REF: EMM 72-30-10	HRS/MSC ENC	O/C	TSN:0 TSN:0			6444.9 5369	23-APR-1996	
725110	IMPELLER:NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER 3073394-1	MOS		TSN:0					LIFE LIMIT
72.150	1-23365-1007 REF: GENERIC NO REF	HRS/MSC ENC	10000	TSN:0 TSN:0			3985.2 3339	18-NOV-1988	4117
725130	SHAFT:NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT 3071441-1	MOS		TSN:0					LIFE LIMIT
72.160	6P4067 REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			6444.9 5369	21-JAN-1981	
725150	DRIVESHAFT:NO. 1 ENGINE - FAN DRIVESHAFT 3071955-5	MOS		TSN:0					LIFE LIMIT
72.180	OP-7887 REF: EMM 72-71-03	HRS/MSC ENC	O/C	TSN:0 TSN:0			6444.9 5369	23-APR-1996	
725160	DUCT:NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3072726-1	MOS		TSO:0					LIFE LIMIT
72.190	1-01345-540 REF: EMM 72-50-05	HRS/MSC ENC	O/C	TSO:0 TSO:0			9289.7 7719	10-JAN-2002	
725190	SEAL:NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING SEAL 3072621-1	MOS		TSN:0					LIFE LIMIT
72.200	8P-24723 REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0	19-SEP-1978	
725210	SEAL:NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PN	MOS		TSN:0					LIFE LIMIT
72.210	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0	19-SEP-1978	
726110	GEARBOX:NO. 1 ENGINE - ACCESSORY GEARBOX 3070003-25	MOS		TSN:0					LIFE LIMIT
72.220	P-1258 REF: EMM 72-60-01	HRS/MSC ENC	O/C	TSN:0 TSN:0			6444.9 5369	23-APR-1996	
+ 726120	GEARBOX:NO. 1 ENGINE - INSPECT ACCESSORY GEARBOX	MOS		TSN:0					LIFE LIMIT
72.230	REF: See Workcard	HRS/MSC ENC	4200	+200			7902.6 6587	19-DEC-1998	1468.8 (+200)
726130	GEARBOX:NO. 1 ENGINE - TRANSFER GEARBOX 3070093-12	MOS		TSN:0					LIFE LIMIT
72.240	P-1593 REF: EMM 72-60-01	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0	19-SEP-1978	

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
WORKCARD	PART#/PKG SERIAL #									
+ 726310 (s)	GEARBOX:NO. 1 ENGINE - CHECK GEARBOX STARTER/GENERATOR OR GENERATOR DRIVE SPLINES	ACCESSORY					PKG			
72.250	REF: See Workcard	MOS	150	+10			17-FEB-2010			
		HRS/MSC					10625.3			
		ENC					9211			
+ 727110	NO. 1 ENGINE - INSPECT FAN SUPPORT ASSEMBLY									
72.270	REF: EMM 72-70-06	MOS	4200	+200			19-DEC-1998			
		HRS/MSC					7902.6	(12102.6)	12433.8	12302.6
		ENC					6587			1468.8 (+200)
ENGINE NO. 2 Model : TFE731-2 Serial # P-74622 Part # 3070300-5										
+ 723110	NO. 2 ENGINE - INSPECT COMPRESSOR CORE									
72.010	REF: GENERIC NO REF	MOS	4200	+200			19-DEC-1998			
		HRS/MSC					7931.2	(12131.2)	12433.8	12331.2
		ENC					6505			1468.8 (+200)
724110	CASE:NO. 2 ENGINE - COMBUSTION CHAMBER PLENUM CASE									
72.020	REF: GENERIC NO REF	MOS	O/C				23-APR-1996			
		HRS/MSC					6472			
		ENC					5360			
+ 724120	CASE:NO. 2 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE									
72.030	REF: EMM 72-40-05	MOS	1400				17-FEB-2010			
		HRS/MSC					10653.9	(12053.9)	12356.5	1391.5
		ENC					9031			
725010	DISC:NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC									LIFE LIMIT
72.040	REF: GENERIC NO REF	MOS	4400				10-JAN-2002			
		HRS/MSC					9318		12040	2998
		ENC					7640			
725020	DISC:NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC									LIFE LIMIT
72.050	REF: GENERIC NO REF	MOS	4500				10-JAN-2002			
		HRS/MSC					9318		12140	3098
		ENC					7640			
725030	DISC:NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC									LIFE LIMIT
72.060	REF: GENERIC NO REF	MOS	9500				25-SEP-1978			
		HRS/MSC					0		9500	458
		ENC					0			
725040	DISC:NO. 2 ENGINE - HIGH PRESSURE TURBINE DISC									LIFE LIMIT
72.070	REF: EMM 72-50-06	MOS	5200				16-FEB-1990			
		HRS/MSC					4895.6		9236	194
		ENC					4036			
725050	DISC:NO. 2 ENGINE - FAN DISC									LIFE LIMIT
72.080	REF: GENERIC NO REF	MOS	10000				23-APR-1996			
		HRS/MSC					6472		15360	6318
		ENC					5360			
725060	DISC:NO. 2 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC									LIFE LIMIT
72.090	REF: GENERIC NO REF	MOS	10000				25-SEP-1978			
		HRS/MSC					0		10000	958
		ENC					0			

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
725070	DISC:NO. 2 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3072396-1	MOS		TSN:0			25-SEP-1978		LIFE LIMIT
72.100	7-12112-3710 REF: GENERIC NO REF	HRS/MSC ENC	10000	TSN:0 TSN:0			0 0	10000	958
725080	DISC:NO. 2 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3072397-1	MOS		TSN:0			25-SEP-1978		LIFE LIMIT
72.110	7-12112-1800 REF: GENERIC NO REF	HRS/MSC ENC	10000	TSN:0 TSN:0			0 0	10000	958
725090	DISC:NO. 2 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3072398-1	MOS		TSN:0			25-SEP-1978		LIFE LIMIT
72.120	7-12112-1703 REF: GENERIC NO REF	HRS/MSC ENC	10000	TSN:0 TSN:0			0 0	10000	958
725091	TIE ROD:NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3073049-1	MOS		TSN:0			03-JUN-1993		LIFE LIMIT
72.130	3P-1051 REF: EMM 72-30-10	HRS/MSC ENC	O/C	TSN:0 TSN:0			5614.9 4636		
725110	IMPELLER:NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER 3073394-1	MOS		TSR:0			03-JUN-1993		LIFE LIMIT
72.150	0-23365-1999 REF: GENERIC NO REF	HRS/MSC ENC	10000	TSN:1791.2 TSN:1498			5616.4 4737	13239	4197
725130	SHAFT:NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT 3071441-1	MOS		TSN:0			25-SEP-1978		LIFE LIMIT
72.160	8P-22720 REF: GENERIC NO REF	HRS/MSC ENC	12000	TSN:0 TSN:0			0 0	12000	2958
725150	DRIVESHAFT:NO. 2 ENGINE - FAN DRIVESHAFT 3071955-3	MOS		TSR:0			06-FEB-1981		LIFE LIMIT
72.180	8P-16784 REF: EMM 72-71-03	HRS/MSC ENC	O/C	TSR:0 TSR:0			1111 858		
725160	DUCT:NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3072726-5	MOS		TSN:0			03-JUN-1993		LIFE LIMIT
72.190	1-01345-9057 REF: EMM 72-50-05	HRS/MSC ENC	O/C	TSN:0 TSN:0			5614.9 4636		
725190	SEAL:NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING SEAL 3072621-1	MOS		TSN:0			25-SEP-1978		LIFE LIMIT
72.200	8P-24725 REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
725210	SEAL:NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PN	MOS		TSN:0			25-SEP-1978		LIFE LIMIT
72.210	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
726110	GEARBOX:NO. 2 ENGINE - ACCESSORY GEARBOX 3070003-25	MOS		TSN:0			25-SEP-1978		LIFE LIMIT
72.220	P-1259 REF: EMM 72-60-01	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
+ 726120	GEARBOX:NO. 2 ENGINE - INSPECT ACCESSORY GEARBOX MOS	HRS/MSC	4200 +200				19-DEC-1998		LIFE LIMIT
72.230	REF: See Workcard ENC	HRS/MSC ENC					7931.2 6505	(12131.2) 12433.8	12331.2 1468.8 (+200)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
726130	GEARBOX:NO. 2 ENGINE - TRANSFER GEARBOX 3070093-12	MOS					25-SEP-1978		
72.240	P-1590 REF: EMM 72-60-01	HRS/MSC ENC	O/C	TSN:7038.8			0		
+ 726310 (s)	GEARBOX:NO. 2 ENGINE - CHECK PKG 1,2	ACCESSORY GEARBOX	STARTER/GENERATOR OR GENERATOR DRIVE SPLINES			PKG			
72.250	REF: See Workcard	MOS HRS/MSC ENC	150	+10			17-FEB-2010 10653.9 9031		
+ 727110	NO. 2 ENGINE - INSPECT FAN SUPPORT ASSEMBLY	MOS					19-DEC-1998		
72.270	REF: EMM 72-70-06	HRS/MSC ENC	4200	+200			7931.2 6505	(12131.2) 12433.8	12331.2 1468.8 (+200)
<b>CHAPTER 73 ENGINE FUEL AND CONTROL</b>									
730126	VALVE:NO. 1 ENGINE PRESSURE LIMITER VALVE PN-UNKNOWN	MOS					06-FEB-1981		
73.030	A3767 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			947 773		
731101	COMPUTER:NO. 1 ENGINE FUEL CONTROL COMPUTER 2101142-5	MOS					12-DEC-1997		
73.090	84-4270 REF: AMM 76-11-01	HRS/MSC AFL	O/C				7598.5 6224		
732101	TRANSMITTER:NO. 1 ENGINE FUEL FLOW TRANSMITTER PN	MOS					23-OCT-1978		
73.080	SN-UNKNOWN REF: AMM 73-31-01	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0		
732626	VALVE:NO. 2 ENGINE PRESSURE LIMITER VALVE 3070685-10	MOS					01-JUN-1980		
73.030	A9661 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			819.4 676		
733601	COMPUTER:NO. 2 ENGINE FUEL CONTROL COMPUTER 2101142-5	MOS					12-DEC-1997		
73.090	41-3759 REF: AMM 76-11-01	HRS/MSC AFL	O/C				7598.5 6224		
734601	TRANSMITTER:NO. 2 ENGINE FUEL FLOW TRANSMITTER PN	MOS					23-OCT-1978		
73.080	SN-UNKNOWN REF: AMM 73-31-01	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0		
734606	INDICATOR:DUAL FUEL FLOW INDICATOR PN-UNKNOWN	MOS					16-NOV-1983		
73.070	1149 REF: AMM 73-31-02	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0					
<b>ENGINE NO. 1 Model : TFE731-2 Serial # P-74621 Part # 3070300-9</b>									
731110	PUMP:NO. 1 ENGINE - FUEL PUMP 3070850-63	MOS					20-JUL-1999		
73.010	MX323714 REF: EMM 73-20-01	HRS/MSC ENC	O/C	TSR:0 TSR:0 TSR:0			8176.3 6810		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
731120 (s)	NO. 1 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 2	MOS					17-FEB-2010		
73.020	REF: EMM 73-21-02	HRS/MSC ENC	300 +100				10625.3 9211		
731130	VALVE:NO. 1 ENGINE - FLOW DIVIDER/DRAIN VALVE 394396-1-1	MOS		TSN:0			19-SEP-1978		
73.030	P1152 REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
731140	HEATER:NO. 1 ENGINE - FUEL HEATER PN	MOS		TSN:0			19-SEP-1978		
73.040	SN-UNKNOWN REF: EMM 73-10-04	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
731150	COOLER:NO. 1 ENGINE - FUEL/OIL COOLER 158610-8	MOS		TSN:0			19-SEP-1978		
73.050	106-1068 REF: EMM 79-20-07	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
732110	UNIT:NO. 1 ENGINE - FUEL CONTROL UNIT 3070800-22	MOS		TSR:0			30-DEC-1997		
73.060	A6229C1 REF: EMM 73-20-01	HRS/MSC ENC	O/C	TSR:0 TSR:0			7344.4 6150		
732130	VALVE:NO. 1 ENGINE - SURGE BLEED VALVE 978812-5-1	MOS		TSO:0			10-JAN-2002		
73.080	6460 REF: EMM 76-10-01	HRS/MSC ENC	O/C	TSO:0 TSO:0			9289.7 7719		
732140	VALVE:NO. 1 ENGINE - SOLENOID CONTROLLER VALVE 109696-3-1	MOS		TSN:0			19-SEP-1978		
73.100	P-1833 REF: EMM 76-10-01	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
732160	TRANSMITTER:NO. 1 ENGINE - FUEL FLOW TRANSMITTER PN	MOS		TSN:0			19-SEP-1978		
73.110	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
732190	NO. 1 ENGINE - REPLACE FUEL CONTROL FILTER MOS						19-SEP-1978		
73.120	REF: EMM 73-21-01	HRS/MSC ENC	C/C				0 0		
<b>ENGINE NO. 2 Model : TFE731-2 Serial # P-74622 Part # 3070300-5</b>									
731110	PUMP:NO. 2 ENGINE - FUEL PUMP 3070850-7	MOS		TSN:0			25-SEP-1978		
73.010	MX-326190 REF: EMM 73-20-01	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
731120 (s)	NO. 2 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 2	MOS					17-FEB-2010		
73.020	REF: EMM 73-21-02	HRS/MSC ENC	300 +100				10653.9 9031		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
731130	VALVE:NO. 2 ENGINE - FLOW DIVIDER/DRAIN VALVE 344346-1	MOS		TSO:0				10-JAN-2005	
73.030	P-205C REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSO:0 TSO:0			10135.7 8552		
731140	HEATER:NO. 2 ENGINE - FUEL HEATER PN	MOS		TSN:0				25-SEP-1978	
73.040	SN-UNKNOWN REF: EMM 73-10-04	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
731150	COOLER:NO. 2 ENGINE - FUEL/OIL COOLER 158610-8	MOS		TSR:0				01-JUN-1980	
73.050	48-1699 REF: EMM 79-20-07	HRS/MSC ENC	O/C	TSR:0 TSR:0			819.4 676		
732110	UNIT:NO. 2 ENGINE - FUEL CONTROL UNIT 3070800-11	MOS		TSR:0				01-OCT-1982	
73.060	A6069T REF: EMM 73-20-01	HRS/MSC ENC	O/C	TSR:0 TSR:0			1845.2		
732130	VALVE:NO. 2 ENGINE - SURGE BLEED VALVE 978812-5-1	MOS		TSO:0				10-JAN-2002	
73.080	8034 REF: EMM 76-10-01	HRS/MSC ENC	O/C	TSO:0 TSO:0			9318 7640		
732140	VALVE:NO. 2 ENGINE - SOLENOID CONTROLLER VALVE 109696-3-1	MOS		TSN:0				01-JUN-1980	
73.100	P-1711 REF: EMM 76-10-01	HRS/MSC ENC	O/C	TSN:0 TSN:0			819.4 676		
732160	TRANSMITTER:NO. 2 ENGINE - FUEL FLOW TRANSMITTER PN	MOS		TSN:0				25-SEP-1978	
73.110	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
732190	NO. 2 ENGINE - REPLACE FUEL CONTROL FILTER MOS	MOS						24-JAN-2006	
73.120	REF: EMM 73-21-01	HRS/MSC ENC	C/C				10165.7 8576		

**CHAPTER 74 IGNITION**

ENGINE NO. 1 Model : TFE731-2 Serial # P-74621 Part # 3070300-9									
+ 740120 (s)	NO. 1 ENGINE - OPERATION CHECK IGNITION SYSTEM PKG 4	MOS						PKG	
74.010	REF: EMM 74-00-01	HRS/MSC ENC	1400	+100			17-FEB-2010 10625.3 9211		
741110	UNIT:NO. 1 ENGINE - IGNITION UNIT PN	MOS		TSN:0				19-SEP-1978	
74.020	SN-UNKNOWN REF: EMM 74-00-01	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
742110	IGNITER PLUG:NO. 1 ENGINE - 6 OCLOCK IGNITER PLUG 3074541-1	MOS		TSN:0				23-APR-1996	
74.030	E9759 REF: EMM 74-00-01	HRS/MSC ENC	O/C	TSN:0 TSN:0			6444.9 5369		



Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	MAX LIMIT	
WORKCARD	PART#/PKG SERIAL #									
+ 742120 (s)	IGNITER PLUG:NO. 1 ENGINE - REMOVE AND INSPECT 6 OCLOCK IGNITER PLUG PKG 4	MOS					PKG 17-FEB-2010			
74.040	REF: EMM 74-00-01	HRS/MSC ENC	1400	+100			10625.3 9211			
742130	IGNITER PLUG:NO. 1 ENGINE - 7 OCLOCK IGNITER PLUG 3070967-1	MOS					23-MAY-1991			
74.050	SN-UNKNOWN REF: EMM 74-00-01	HRS/MSC ENC	O/C				5049.8 4183			
+ 742140 (s)	IGNITER PLUG:NO. 1 ENGINE - REMOVE AND INSPECT 7 OCLOCK IGNITER PLUG PKG 4	MOS					PKG 17-FEB-2010			
74.060	REF: EMM 74-00-01	HRS/MSC ENC	1400	+100			10625.3 9211			
<b>ENGINE NO. 2 Model : TFE731-2 Serial # P-74622 Part # 3070300-5</b>										
+ 740120 (s)	NO. 2 ENGINE - OPERATION CHECK IGNITION SYSTEM PKG 4	MOS					PKG 17-FEB-2010			
74.010	REF: EMM 74-00-01	HRS/MSC ENC	600	+200			10653.9 9031			
741110	UNIT:NO. 2 ENGINE - IGNITION UNIT 3070378-2	MOS					05-MAR-1999			
74.020	8635R040 REF: EMM 74-00-01	HRS/MSC ENC	O/C				8015.3 6564			
742110	IGNITER PLUG:NO. 2 ENGINE - 6 OCLOCK IGNITER PLUG 3074541-1	MOS					23-APR-1996			
74.030	E9768 REF: EMM 74-00-01	HRS/MSC ENC	O/C				6472 5360			
+ 742120 (s)	IGNITER PLUG:NO. 2 ENGINE - REMOVE AND INSPECT 6 OCLOCK IGNITER PLUG PKG 4	MOS					PKG 17-FEB-2010			
74.040	REF: EMM 74-00-01	HRS/MSC ENC	600	+200			10653.9 9031			
742130	IGNITER PLUG:NO. 2 ENGINE - 7 OCLOCK IGNITER PLUG 3074541-1	MOS					23-APR-1996			
74.050	E9775 REF: EMM 74-00-01	HRS/MSC ENC	O/C				6472 5360			
+ 742140 (s)	IGNITER PLUG:NO. 2 ENGINE - REMOVE AND INSPECT 7 OCLOCK IGNITER PLUG PKG 4	MOS					PKG 17-FEB-2010			
74.060	REF: EMM 74-00-01	HRS/MSC ENC	600	+200			10653.9 9031			
<b>CHAPTER 75 AIR</b>										
<b>ENGINE NO. 1 Model : TFE731-2 Serial # P-74621 Part # 3070300-9</b>										
750120	SWITCH:NO. 1 ENGINE - ENGINE ANTI-ICE PRESSURE SWITCH PN	MOS					19-SEP-1978			
75.010	SN-UNKNOWN REF: EMM 75-10-01	HRS/MSC ENC	O/C				0 0			
750130	SENSOR:NO. 1 ENGINE - ENGINE INLET PRESSURE/TEMPERATURE SENSOR 3070816	MOS					30-APR-1979			
75.020	3114 REF: EMM 75-40-01	HRS/MSC ENC	O/C				244.9			

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
751010	VALVE:NO. 1 ENGINE - ANTI-ICE SHUTOFF VALVE								
	PN	MOS		TSN:0				19-SEP-1978	
75.030	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0	
	REF: EMM 75-10-01	ENC		TSN:0				0	
<b>ENGINE NO. 2 Model : TFE731-2 Serial # P-74622 Part # 3070300-5</b>									
750120	SWITCH:NO. 2 ENGINE - ENGINE ANTI-ICE PRESSURE SWITCH								
	PN	MOS		TSN:0				25-SEP-1978	
75.010	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0	
	REF: EMM 75-10-01	ENC		TSN:0				0	
750130	SENSOR:NO. 2 ENGINE - ENGINE INLET PRESSURE/TEMPERATURE SENSOR								
	3070816-12	MOS		TSN:0				30-DEC-1997	
75.020	G0876	HRS/MSC	O/C	TSN:0				7371.5	
	REF: EMM 75-40-01	ENC		TSN:0				6069	
751010	VALVE:NO. 2 ENGINE - ANTI-ICE SHUTOFF VALVE								
	PN	MOS		TSN:0				25-SEP-1978	
75.030	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0	
	REF: EMM 75-10-01	ENC		TSN:0				0	
<b>CHAPTER 76 ENGINE CONTROLS</b>									
5-10-29-E7611001-L	PERFORM FUNCTIONAL CHECK OF FUEL COMPUTER ITT SIGNAL PORTION OF THE WIRING HARNESS.								
		MOS						17-FEB-2010	
		HRS/MSC	MPI					10956.5	
	REF: AMM 76-11-01	AFL						9224	
5-10-29-E7611001-R	PERFORM FUNCTIONAL CHECK OF FUEL COMPUTER ITT SIGNAL PORTION OF THE WIRING HARNESS.								
		MOS						17-FEB-2010	
		HRS/MSC	MPI					10956.5	
	REF: AMM 76-11-01	AFL						9224	
760601	CABLE:NO. 1 ENGINE FORWARD THROTTLE CABLE								
	PN	MOS		TSN:0				23-OCT-1978	
76.010	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0	
	REF: AMM 76-10-01	AFL		TSN:0				0	
760606	CABLE:NO. 1 ENGINE CENTER THROTTLE CABLE								
	PN	MOS		TSN:0				23-OCT-1978	
76.020	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0	
	REF: AMM 76-10-01	AFL		TSN:0				0	
760611	CABLE:NO. 1 ENGINE AFT THROTTLE CABLE								
	PN	MOS		TSN:0				23-OCT-1978	
76.030	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0	
	REF: AMM 76-10-01	AFL		TSN:0				0	
761101	CABLE:NO. 2 ENGINE FORWARD THROTTLE CABLE								
	PN	MOS		TSN:0				23-OCT-1978	
76.010	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0	
	REF: AMM 76-10-01	AFL		TSN:0				0	
761106	CABLE:NO. 2 ENGINE CENTER THROTTLE CABLE								
	PN	MOS		TSN:0				23-OCT-1978	
76.020	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0	
	REF: AMM 76-10-01	AFL		TSN:0				0	

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	MAX LIMIT	
WORKCARD	PART#/PKG SERIAL #									
761111	CABLE:NO. 2 ENGINE AFT THROTTLE CABLE									
76.030	PN SN-UNKNOWN REF: AMM 76-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
762601	INDICATOR:ENGINE SYNCHRONIZER INDICATOR									
76.040	PN SN-UNKNOWN REF: AMM 76-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
762606	CONTROL BOX:ENGINE SYNCHRONIZER CONTROL BOX									
76.040	2101208-1 11-555 REF: AMM 76-12-01	MOS HRS/MSC AFL	O/C				05-OCT-1983			
<b>ENGINE NO. 1 Model : TFE731-2 Serial # P-74621 Part # 3070300-9</b>										
760110	CONTROL:NO. 1 ENGINE - DIGITAL ENGINE ELECTRIC CONTROL									
76.010	2119020-4 50-AMO205 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				30-MAR-2001			
+ 760120 (s)	NO. 1 ENGINE - BITE CHECK									
76.020	PKG 2 REF: EMM 72-00-00	MOS HRS/MSC ENC	300	+100			PKG 17-FEB-2010 10625.3 9211			
760130	NO. 1 ENGINE - DEEC									
76.030	REF: GENERIC NO REF	DAYS HRS/MSC ENC		+10 40			17-FEB-2010 10625.3 9211	9251	9261	29 (+10)
<b>ENGINE NO. 2 Model : TFE731-2 Serial # P-74622 Part # 3070300-5</b>										
760110	CONTROL:NO. 2 ENGINE - DIGITAL ENGINE ELECTRIC CONTROL									
76.010	2119020-4 50-AM0196 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				30-MAR-2001			
+ 760120 (s)	NO. 2 ENGINE - BITE CHECK									
76.020	PKG 2 REF: EMM 72-00-00	MOS HRS/MSC ENC	300	+100			PKG 17-FEB-2010 10653.9 9031			
760130	NO. 2 ENGINE - DEEC									
76.030	REF: GENERIC NO REF	DAYS HRS/MSC ENC		+10 40			17-FEB-2010 10653.9 9031	9071	9081	29 (+10)
<b>CHAPTER 77 ENGINE INDICATING</b>										
770106	INDICATOR:NO. 1 ENGINE LOW PRESSURE (N1 FAN SPEED) INDICATOR									
77.030	PN SN-UNKNOWN REF: AMM 77-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
770606	INDICATOR:NO. 1 ENGINE HIGH PRESSURE (N2 TURBINE SPEED) INDICATOR									
77.040	PN SN-UNKNOWN REF: AMM 77-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
771106	INDICATOR:NO. 1 ENGINE ITT (INTERSTAGE) INDICATOR								
77.060	131350-3 68-815 REF: AMM 77-20-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			15-JAN-2002 9620.6 7857		
771606	INDICATOR:NO. 2 ENGINE LOW PRESSURE (N1 FAN SPEED) INDICATOR								
77.030	131344-3 117-799 REF: AMM 77-10-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			15-MAR-2005 10438.7 8768		
772106	INDICATOR:NO. 2 ENGINE HIGH PRESSURE (N2 TURBINE SPEED) INDICATOR								
77.040	PN SN-UNKNOWN REF: AMM 77-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
772606	INDICATOR:NO. 2 ENGINE ITT (INTERSTAGE) INDICATOR								
77.060	131350-3 68-784 REF: AMM 77-20-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			30-OCT-1997 7504.7 6155		

**ENGINE NO. 1 Model : TFE731-2 Serial # P-74621 Part # 3070300-9**

771110	TRANSDUCER:NO. 1 ENGINE - LOW PRESSURE (N1) TRANSDUCER								
77.010	3073827-4 981936001693 REF: EMM 77-10-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-DEC-1998 7902.6 6587		
771120	TRANSDUCER:NO. 1 ENGINE - HIGH PRESSURE (N2) TRANSDUCER								
77.020	3070722-2 1552T REF: EMM 77-10-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			04-JUN-1979		
772110	HARNES:NO. 1 ENGINE - ITT THERMOCOUPLE HARNES								
77.030	3073595-1 6-20219-124 REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			23-APR-1996 6444.9 5369		

**ENGINE NO. 2 Model : TFE731-2 Serial # P-74622 Part # 3070300-5**

771110	TRANSDUCER:NO. 2 ENGINE - LOW PRESSURE (N1) TRANSDUCER								
77.010	3073827-4 SN-UNKNOWN REF: EMM 77-10-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			10-JAN-2002 9318 7640		
771120	TRANSDUCER:NO. 2 ENGINE - HIGH PRESSURE (N2) TRANSDUCER								
77.020	3070722-2 2707T REF: EMM 77-10-05	MOS HRS/MSC ENC	O/C				13-FEB-1980 658.6 574		
772110	HARNES:NO. 2 ENGINE - ITT THERMOCOUPLE HARNES								
77.030	3073595-1 012021900355 REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			10-JAN-2002 9318 7640		

**CHAPTER 78 EXHAUST**

5-10-29-E7810005-L	PERFORM VISUAL INSPECTION OF ENGINE EXHAUST NOZZLES FOR CRACKS, SECURITY OF INSTALLATION, AND GENERAL CONDITION.								
		MOS					17-FEB-2010		
		HRS/MSC	MPI				10956.5		
	REF:	AFL					9224		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
5-10-29-E7810005-R	PERFORM VISUAL INSPECTION OF ENGINE EXHAUST NOZZLES FOR CRACKS, SECURITY OF INSTALLATION, AND GENERAL CONDITION.	MOS					17-FEB-2010		
	REF:	HRS/MSC MPI					10956.5		
		AFL					9224		
780101	THRUST REVERSER:NO. 1 ENGINE THRUST REVERSER	MOS					23-OCT-1978		
78.010	PN	HRS/MSC O/C		TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
780109	LUBRICATE NO. 1 ENGINE THRUST REVERSER (150 HOUR) (IRN P7830086)	MOS					17-FEB-2010		
78.0201	REF: CMM 78-30-00	HRS/MSC 150 +50					10956.5	11106.5	11156.5
		AFL					9224		141.5 (+50)
780111	ACTUATOR:NO. 1 ENGINE PNEUMATIC DRIVE ACTUATOR	MOS					15-JAN-2002		
78.080	126602-1	HRS/MSC O/C		TSR:0			9620.6		
	REF: CMM 78-30-03	AFL		TSR:0			7857		
780114	LUBRICATE NO. 1 ENGINE THRUST REVERSER (600 HOUR) (IRN P7830086)	MOS					17-FEB-2010		
78.0202	REF: CMM 78-30-00	HRS/MSC 600 +200					10956.5	11556.5	11756.5
		AFL					9224		591.5 (+200)
780115	LUBRICATE NO. 1 ENGINE THRUST REVERSER (MPI) (IRN P7830086)	MOS					17-FEB-2010		
78.040	REF: CMM 78-30-00	HRS/MSC 1400 +100					10956.5	12356.5	12456.5
		AFL					9224		1391.5 (+100)
780121	SHAFT:NO. 1 ENGINE OUTBOARD FLEX SHAFT	MOS					23-OCT-1978		
78.090	PN	HRS/MSC O/C		TSN:0			0		
	REF: CMM 78-30-04	AFL		TSN:0			0		
780131	SHAFT:NO. 1 ENGINE INBOARD FLEX SHAFT	MOS					19-DEC-1986		
78.100	121724-3	HRS/MSC O/C		TSN:0					
	REF: CMM 78-30-04	AFL		TSN:0					
780141	VALVE:NO. 1 ENGINE SOLENOID BLEED VALVE	MOS					23-OCT-1978		
78.110	PN	HRS/MSC O/C		TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
780151	PRESSURE SWITCH:NO. 1 ENGINE PNEUMATIC PRESSURE SWITCH	MOS					23-OCT-1978		
78.120	PN	HRS/MSC O/C		TSN:0			0		
	REF: CMM 78-30-11	AFL		TSN:0			0		
780161	GEARBOX:NO. 1 ENGINE OUTBOARD PINION GEARBOX	MOS					23-OCT-1978		
78.130	PN	HRS/MSC O/C		TSN:0			0		
	REF: CMM 78-30-06	AFL		TSN:0			0		
780171	GEARBOX:NO. 1 ENGINE INBOARD PINION GEARBOX	MOS					23-OCT-1978		
78.140	PN	HRS/MSC O/C		TSN:0			0		
	REF: CMM 78-30-06	AFL		TSN:0			0		

?-Insufficient Information (EFF)-Effective C/W  
08-MAR-2010

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

\*-Estimated Due (New Requirement)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
780601	THRUST REVERSER:NO. 2 ENGINE THRUST REVERSER								
	PN	MOS		TSN:0			23-OCT-1978		
78.011	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
780609	LUBRICATE NO. 2 ENGINE THRUST REVERSER (150 HOUR) (IRN P7830086)								
		MOS					17-FEB-2010		
78.0211		HRS/MSC	150	+50			10956.5	11106.5	11156.5
	REF: CMM 78-30-00	AFL					9224		141.5 (+50)
780611	ACTUATOR:NO. 2 ENGINE PNEUMATIC DRIVE ACTUATOR								
	126602-1	MOS		TSN:0			27-APR-1996		
78.080	P276	HRS/MSC	O/C	TSN:0			6717		
	REF: CMM 78-30-03	AFL		TSN:0			5523		
780614	LUBRICATE NO. 2 ENGINE THRUST REVERSER (600 HOUR) (IRN P7830086)								
		MOS					15-APR-2008		
78.0212		HRS/MSC	600	+200			10686.2	11286.2	11486.2
	REF: CMM 78-30-00	AFL					8968		321.2 (+200)
780615	LUBRICATE NO. 2 ENGINE THRUST REVERSER (MPI) (IRN P7830086)								
		MOS					15-APR-2008		
78.040		HRS/MSC	1400	+100			10686.2	12086.2	12186.2
	REF: CMM 78-30-00	AFL					8968		1121.2 (+100)
780621	SHAFT:NO. 2 ENGINE OUTBOARD FLEX SHAFT								
	PN	MOS		TSN:0			23-OCT-1978		
78.090	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: CMM 78-30-04	AFL		TSN:0			0		
780631	SHAFT:NO. 2 ENGINE INBOARD FLEX SHAFT								
	121724-3	MOS		TSN:0			19-AUG-1999		
78.100	173078	HRS/MSC	O/C	TSN:0			8558.5		
	REF: CMM 78-30-04	AFL		TSN:0			6988		
780641	VALVE:NO. 2 ENGINE SOLENOID BLEED VALVE								
	PN	MOS		TSN:0			23-OCT-1978		
78.110	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
780651	PRESSURE SWITCH:NO. 2 ENGINE PNEUMATIC PRESSURE SWITCH								
	PN	MOS		TSN:0			23-OCT-1978		
78.120	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: CMM 78-30-11	AFL		TSN:0			0		
780661	GEARBOX:NO. 2 ENGINE OUTBOARD PINION GEARBOX								
	45-12350-1	MOS		TSN:0			16-FEB-1990		
78.130	P316	HRS/MSC	O/C	TSN:0			5069.5		
	REF: CMM 78-30-06	AFL		TSN:0			4119		
780671	GEARBOX:NO. 2 ENGINE INBOARD PINION GEARBOX								
	PN	MOS		TSN:0			23-OCT-1978		
78.140	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: CMM 78-30-06	AFL		TSN:0			0		
780676	NOZZLE:NO. 1 ENGINE EXHAUST NOZZLE								
	PN	MOS		TSN:0			23-OCT-1978		
78.150	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
780681	NOZZLE:NO. 2 ENGINE EXHAUST NOZZLE									
78.150	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
780686	SOLENOID VALVE:NO. 1 ENGINE 3 WAY SOLENOID VALVE									
78.160	PN SN-UNKNOWN REF: CMM 78-30-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
780691	SOLENOID VALVE:NO. 2 ENGINE 3 WAY SOLENOID VALVE									
78.160	PN SN-UNKNOWN REF: CMM 78-30-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
780696	LATCH:NO. 1 ENGINE OUTBOARD SEQUENCING LATCH									
78.190	PN SN-UNKNOWN REF: CMM 78-30-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
780699	LATCH:NO. 1 ENGINE INBOARD SEQUENCING LATCH									
78.200	PN SN-UNKNOWN REF: CMM 78-30-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
780701	LATCH:NO. 2 ENGINE OUTBOARD SEQUENCING LATCH									
78.190	232-20242-7 SN-UNKNOWN REF: CMM 78-30-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-NOV-2000 9301 7594			
780704	LATCH:NO. 2 ENGINE INBOARD SEQUENCING LATCH									
78.200	232-20242-7 SN-UNKNOWN REF: CMM 78-30-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-NOV-2000 9301 7594			
780706	LATCH:NO. 1 ENGINE OUTBOARD PNEUMATIC LATCH									
78.170	PN SN-UNKNOWN REF: CMM 78-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
780711	LATCH:NO. 1 ENGINE INBOARD PNEUMATIC LATCH									
78.180	PN SN-UNKNOWN REF: CMM 78-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
780716	LATCH:NO. 2 ENGINE INBOARD PNEUMATIC LATCH									
78.180	PN SN-UNKNOWN REF: CMM 78-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
780721	LATCH:NO. 2 ENGINE OUTBOARD PNEUMATIC LATCH									
78.170	PN SN-UNKNOWN REF: CMM 78-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
+ 782101	INSPECT NO. 1 ENGINE THRUST REVERSER (150 HOUR) (IRN P7830086)									
78.0501	REF: See Workcard	MOS HRS/MSC AFL	150	+50			17-FEB-2010 10956.5 9224	11106.5	11156.5	141.5 (+50)

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
+ 782102	INSPECT NO. 1 ENGINE THRUST REVERSER (300 HOUR) (IRN P7830086)	MOS					17-FEB-2010			
78.0502	REF: See Workcard	HRS/MSC AFL	300 +100				10956.5 9224	11256.5	11356.5	291.5 (+100)
+ 782103	INSPECT NO. 1 ENGINE THRUST REVERSER (600 HOUR) (IRN P7830086)	MOS					17-FEB-2010			
78.0503	REF: See Workcard	HRS/MSC AFL	600 +200				10956.5 9224	11556.5	11756.5	591.5 (+200)
+ 782105	INSPECT NO. 1 ENGINE THRUST REVERSER (MPI) (IRN P7830086)	MOS					17-FEB-2010			
78.070	REF: See Workcard	HRS/MSC AFL	1400 +100				10956.5 9224	12356.5	12456.5	1391.5 (+100)
+ 782601	INSPECT NO. 2 ENGINE THRUST REVERSER (150 HOUR) (IRN P7830086)	MOS					17-FEB-2010			
78.0511	REF: See Workcard	HRS/MSC AFL	150 +50				10956.5 9224	11106.5	11156.5	141.5 (+50)
+ 782602	INSPECT NO. 2 ENGINE THRUST REVERSER (300 HOUR) (IRN P7830086)	MOS					01-JUL-2009			
78.0512	REF: See Workcard	HRS/MSC AFL	300 +100				10856.2 9122	11156.2	11256.2	191.2 (+100)
+ 782603	INSPECT NO. 2 ENGINE THRUST REVERSER (600 HOUR) (IRN P7830086)	MOS					15-APR-2008			
78.0513	REF: See Workcard	HRS/MSC AFL	600 +200				10686.2 8968	11286.2	11486.2	321.2 (+200)
+ 782605	INSPECT NO. 2 ENGINE THRUST REVERSER (MPI) (IRN P7830086)	MOS					15-APR-2008			
78.071	REF: See Workcard	HRS/MSC AFL	1400 +100				10686.2 8968	12086.2	12186.2	1121.2 (+100)
<b>CHAPTER 79 OIL</b>										
791101	PRESSURE SWITCH:NO. 1 ENGINE OIL PRESSURE SWITCH	PN								
79.120	REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
791111	TRANSMITTER:NO. 1 ENGINE OIL PRESSURE TRANSMITTER	PN								
79.130	REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
791116	BULB:NO. 1 ENGINE OIL TEMPERATURE BULB	PN								
79.140	REF: AMM 79-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			
791121	INDICATOR:NO. 1 ENGINE OIL TEMPERATURE INDICATOR	PN								
79.150	REF: AMM 79-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0			



Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
792601	PRESSURE SWITCH:NO. 2 ENGINE OIL PRESSURE SWITCH								
79.120	P22B-12 390 REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-APR-1979 196		
792611	TRANSMITTER:NO. 2 ENGINE OIL PRESSURE TRANSMITTER								
79.130	ST4H 11444 REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-NOV-1986 3264 2504		
792616	BULB:NO. 2 ENGINE OIL TEMPERATURE BULB								
79.140	PN SN-UNKNOWN REF: AMM 79-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
792621	INDICATOR:NO. 2 ENGINE OIL TEMPERATURE INDICATOR								
79.150	PN SN-UNKNOWN REF: AMM 79-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-OCT-1978 0 0		
793101	INDICATOR:DUAL OIL PRESSURE INDICATOR								
79.010	S-208-6 534 REF: AMM 79-30-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			22-FEB-2008 10634.7 8935		

**ENGINE NO. 1 Model : TFE731-2 Serial # P-74621 Part # 3070300-9**

+ 790110 (s)	NO. 1 ENGINE - ANALYZE OIL AND FILTER						PKG		
79.010	PKG 1,2 REF: EMM 72-00-00	MOS HRS/MSC ENC	150	+100			17-FEB-2010 10625.3 9211		
790120	NO. 1 ENGINE - CHANGE ENGINE OIL								
79.020	REF: EMM 72-00-00	MOS HRS/MSC ENC	600				17-FEB-2010 10625.3 9211	(11225.3) 11556.5	591.5
+ 790130 (s)	NO. 1 ENGINE - INSPECT OIL CHIP DETECTOR						PKG		
79.030	PKG 1,2 REF: EMM 79-20-03	MOS HRS/MSC ENC	150	+100			17-FEB-2010 10625.3 9211		
792110	PUMP:NO. 1 ENGINE - OIL PUMP								
79.050	3071949-6 4-211 REF: EMM 79-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			23-APR-1996 6444.9 5369		
792120	VALVE:NO. 1 ENGINE - BY-PASS INDICATOR VALVE								
79.060	PN SN-UNKNOWN REF: EMM 79-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			19-SEP-1978 0 0		
792130	VALVE:NO. 1 ENGINE - PRESSURE BREATHER VALVE								
79.070	3075323-3 03117 REF: EMM 79-20-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-DEC-1998 7902.6 6587		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
792140	COOLER:NO. 1 ENGINE - UPPER OIL COOLER								
	158600-7	MOS		TSN:0				19-SEP-1978	
79.080	98-980	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 79-20-09	ENC		TSN:0			0		
792150	COOLER:NO. 1 ENGINE - LOWER LEFT OIL COOLER								
	159900-3	MOS		TSN:0				19-SEP-1978	
79.090	98-1919	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 79-20-09	ENC		TSN:0			0		
792160	COOLER:NO. 1 ENGINE - LOWER RIGHT OIL COOLER								
	159910-3	MOS		TSN:0				19-SEP-1978	
79.100	18-1678	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 79-20-09	ENC		TSN:0			0		
792170	VALVE:NO. 1 ENGINE - TEMPERATURE CONTROL VALVE								
	157025	MOS		TSN:0				19-SEP-1978	
79.110	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
<b>ENGINE NO. 2 Model : TFE731-2 Serial # P-74622 Part # 3070300-5</b>									
+ 790110 (s)	NO. 2 ENGINE - ANALYZE OIL AND FILTER							PKG	
	PKG 1,2	MOS						17-FEB-2010	
79.010		HRS/MSC	150	+100			10653.9		
	REF: EMM 72-00-00	ENC					9031		
790120	NO. 2 ENGINE - CHANGE ENGINE OIL								
		MOS						17-FEB-2010	
79.020		HRS/MSC	600				10653.9	(11253.9) 11556.5	591.5
	REF: EMM 72-00-00	ENC					9031		
+ 790130 (s)	NO. 2 ENGINE - INSPECT OIL CHIP DETECTOR							PKG	
	PKG 1,2	MOS						17-FEB-2010	
79.030		HRS/MSC	150	+100			10653.9		
	REF: EMM 79-20-03	ENC					9031		
792110	PUMP:NO. 2 ENGINE - OIL PUMP								
	3071949-11	MOS		TSN:0				24-DEC-1998	
79.050	98-14057-0277	HRS/MSC	O/C	TSN:0					
	REF: EMM 79-20-03	ENC		TSN:0					
792120	VALVE:NO. 2 ENGINE - BY-PASS INDICATOR VALVE								
	PN	MOS		TSN:0				25-SEP-1978	
79.060	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 79-30-01	ENC		TSN:0			0		
792130	VALVE:NO. 2 ENGINE - PRESSURE BREATHER VALVE								
	3075323-3	MOS		TSN:0				08-APR-1997	
79.070	2013	HRS/MSC	O/C	TSN:0			7038.8		
	REF: EMM 79-20-02	ENC		TSN:0			5829		
792140	COOLER:NO. 2 ENGINE - UPPER OIL COOLER								
	158600	MOS						01-JUN-1980	
79.080	SN-UNKNOWN	HRS/MSC	O/C				819.4		
	REF: EMM 79-20-09	ENC					676		

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								NEXT DUE ACTUAL	NEXT DUE MAX LIMIT	
WORKCARD	PART#/PKG SERIAL #									
792150	COOLER:NO. 2 ENGINE - LOWER LEFT OIL COOLER									
	PN	MOS		TSN:0			25-SEP-1978			
79.090	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: EMM 79-20-09	ENC		TSN:0			0			
792160	COOLER:NO. 2 ENGINE - LOWER RIGHT OIL COOLER									
	PN	MOS		TSN:0			25-SEP-1978			
79.100	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: EMM 79-20-09	ENC		TSN:0			0			
792170	VALVE:NO. 2 ENGINE - TEMPERATURE CONTROL VALVE									
	157025	MOS					01-JUN-1980			
79.110	SN-UNKNOWN	HRS/MSC	O/C				819.4			
	REF: GENERIC NO REF	ENC					676			
<b>CHAPTER 80 STARTING</b>										
5-10-29-E8010004-L	STARTER:CHANGE NO. 1 ENGINE STARTER OIL									
		MOS					17-FEB-2010			
		HRS/MSC	MPI				10956.5			
	REF: AMM 80-10-01	AFL					9224			
5-10-29-E8010004-R	STARTER:CHANGE NO. 2 ENGINE STARTER OIL									
		MOS					17-FEB-2010			
		HRS/MSC	MPI				10956.5			
	REF: AMM 80-10-01	AFL					9224			
800101	STARTER:NO. 1 ENGINE STARTER									
	71B1-23A	MOS					10-JAN-2005			
80.010	A6144	HRS/MSC	O/C				10438.3			
	REF: AMM 80-10-01	AFL					8767			
800103	CONNECTOR:NO. 1 ENGINE STARTER JAW CONNECTOR									
	PN	MOS		TSN:0			23-OCT-1978			
80.010	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 80-10-01	AFL		TSN:0			0			
800601	STARTER:NO. 2 ENGINE STARTER									
	71B1-23A	MOS					06-OCT-2003			
80.070	9614	HRS/MSC	O/C				10332.3			
	REF: AMM 80-10-01	AFL					8666			
800603	CONNECTOR:NO. 2 ENGINE STARTER JAW CONNECTOR									
	PN	MOS		TSN:0			23-OCT-1978			
80.070	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 80-10-01	AFL		TSN:0			0			
801101	BOX:STARTER RESISTOR CUTOUT BOX									
	PN	MOS		TSN:0			23-OCT-1978			
80.060	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 80-10-02	AFL		TSN:0			0			
801111	RESISTOR:NO. 1 ENGINE STARTER TIMER RESISTOR									
	PN	MOS		TSN:0			23-OCT-1978			
80.020	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: GENERIC NO REF	AFL		TSN:0			0			

Model : LEARJET 35A  
 Owner : J.E.P. DEVELOPEMENT CORP.  
 Operator : NORTH DALLAS AVIATION INC.

A/C Serial #: 35A210 A/C Reg. #: N770JP

Aircraft HRS: 10965

Landings: 9235

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
801116	LIMITER:NO. 1 ENGINE TIMER CURRENT LIMITER								
	PN	MOS		TSN:0				23-OCT-1978	
80.040	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
801121	RELAY:NO. 1 ENGINE STARTER TIMER FORWARD RELAY								
	PN	MOS		TSN:0				23-OCT-1978	
80.030	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
801126	RELAY:NO. 1 ENGINE STARTER TIMER AFT RELAY								
	PN	MOS		TSN:0				23-OCT-1978	
80.030	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
801611	RESISTOR:NO. 2 ENGINE STARTER TIMER RESISTOR								
	PN	MOS		TSN:0				23-OCT-1978	
80.020	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
801616	LIMITER:NO. 2 ENGINE STARTER TIMER CURRENT LIMITER								
	PN	MOS		TSN:0				23-OCT-1978	
80.040	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
801621	RELAY:NO. 2 ENGINE STARTER TIMER FORWARD RELAY								
	PN	MOS		TSN:0				23-OCT-1978	
80.050	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
801626	RELAY:NO. 2 ENGINE STARTER TIMER AFT RELAY								
	PN	MOS		TSN:0				23-OCT-1978	
80.050	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		