

Aircraft Identification

Model: FALCON 10

Year of Manufacture: 1980, *Delivery:* 1980

Serial #: 10-158

Registration #: N700FH [Expires: 9/30/2011]

Purchase Date: 4/7/2009

For Sale Information (Date Listed: 2/23/2011)

Status: For Sale

Asking: Make Offer

On Exclusive with Dallas Aircraft Sales, LLC

Interior Details (Updated: 1/1999)

Number of Passengers: 8

Air Conditioning: Freon; *Seating:* Forward 2-place side-facing divan, aft 3-place divan;

Accessories: 110-volt outlets, Falcon 100-style one-piece composite window panels, plating upgrade in 2007; *Lavatory:* Forward potty; *Carpet:* New carpeting installed in 2007;

Exterior Details (Updated: 02/2009)

Done By: Duncan Aviation

Rating: 10

Colors: White w/blue & gray trim;



Key Features

- ✓ Engine Maintenance Program
- ✓ RVSM
- ✓ Thrust Reversers
- ✓ Terrain Awareness and Warning System
- ✓ Traffic Collision Avoidance System (TCAS)
- ✓ Cockpit Voice Recorder
- ✓ Baggage Mod

Airport Information

ADS - KADS - Addison Airport

Dallas - TX - United States

Engine Information

Engine Model: TFE731-2-2C , On Condition TBO: No

Engine Maintenance Program: Honeywell Engines & Systems - MSP Gold

| | Serial Number | Total Time Since New Hours | Since Overhaul Hours | Since Hot Inspection Hours | Time Between Overhaul Hours | Total Cycles Since New | Total Cycles Since Overhaul | Total Cycles Since Hot |
|-----------|---------------|----------------------------|----------------------|----------------------------|-----------------------------|------------------------|-----------------------------|------------------------|
| Eng 1 (L) | P73456 | | | | 4,200 | | | |
| Eng 2 (R) | P73457 | | | | 4,200 | | | |

Maintenance Details

Maintained: FAR Part 135

Inspection: RVSM; Landmark Aviation STC. Engines are enrolled on MSP Gold; \$193.62 per engine per hour. 4A+ inspection c/w 03/09. B inspection c/w at 7689TT. C inspection c/w 08/07.;

Airframe Maintenance Program: Unknown

Airframe Maintenance Tracking Program: CAMP (Computerized Aircraft Maintenance Program)

Certification: RVSM

Equipment Details

General: Thrust reversers, external aft baggage compartment, EROS quick-donning oxygen masks; **Lights:** Recognition;

Add Cockpit Equipment Details

General: Bendix IHAS-8000 w/KMH-980 mult-hazard system, Honeywell MFRD multi-function display, Collins altitude preselector, dual Baker cabin audio & paging system, J.E.T. standby horizon, Artex 406 ELT, DEEC's, Teledyne angle of attack, Davtron 811B clock;

Avionics

ADF: Dual Collins ADF-60; **Autopilot:** Collins APS-80; **Avionics Package:** Dual Collins FDC-80 / Pro Line; **Communication Radios:** Dual Collins VHF-20A; **Compass:** Dual Sperry C-14; **CVR:** Fairchild GA-100; **DME:** Dual Collins DME-40; **Flight Director:** Dual Collins FDC-80; **Flight Phone:** Wulfsberg VI; **FMS:** Global GNS-XLS w/GPS; **Hi Frequency:** Collins 718U-5 provisions; **Navigation Radios:** Dual Collins VIR-30A; **Radar Altimeter:** Collins ALT-50; **RMI:** Dual Honeywell; **TAWS:** Bendix IHAS-8000 w/KMH-980; **TCAS:** Bendix IHAS-8000 w/KMH-980; **Transponder:** Dual Collins TDR-90; **Weather Radar:** Honeywell Primus 400 color;



Owner - Planete Verts, Inc.
25 Highland Park Village 100-296
Dallas, TX 75205 United States
Office: 214-704-7004

Mr. Patrick T Cascio
President & Director

Operator - Planete Verts, Inc.
25 Highland Park Village 100-296
Dallas, TX 75205 United States
Office: 214-704-7004

Mr. Patrick T Cascio
President & Director

Chief Pilot - Planete Verts, Inc.
25 Highland Park Village 100-296
Dallas, TX 75205 United States
Office: 214-704-7004

Mr. Patrick T Cascio
President & Director

Exclusive Broker - Dallas Aircraft Sales, LLC
4553 Jimmy Doolittle Drive, Suite 3
Addison, TX 75001 United States
carl@dallasaircraftsales.com
www.dallasaircraftsales.com
Office: 972-735-9494
Fax: 972-735-9470

Mr. Carl Neuzil
Managing Member
carl@dallasaircraftsales.com
Office: 972-735-9494
Mobile: 214-212-0952
Fax: 972-735-9470

